

Switch Stacking – ArubaOS Switch





Why stacking?

To reduce the number of uplinks and optimize their usage

To reduce the number of IP interfaces and addresses

To simplify operations by unifying management and control planes Installation, configuration, software upgrades In stacking we have two types

Backplane stacking (BPS) Front plane stacking (FPS)-VSF

Currently we would be covering Backplane stacking and its topology, use case, functionality as well stacking troubleshooting

Some of the major functionalities provided by the stacking infrastructure are,

- Stack topology discovery
- Stack commander and standby election
- Stack member management addition, removal and provisioning
- Stack topology management
- Stack spilt

Backplane stacking (BPS)

Current switches models that supports Backplane stacking

3800 switch series (3810)

Mesh topology: up to 5 units Ring topology: up to 10 units Stack port throughput*: up to 40Gbps Stack module throughput*: up to 160Gbps



2900 switch series (2920/2930M)

2920

Ring topology: up to 4 units Stack port throughput*: up to 20Gbps Stack module throughput*: up to 40Gbps



2930M

Ring topology: up to 10 units Stack port throughput*: up to 25Gbps Stack module throughput*: up to 50Gbps



Topology supported

- Chain
- Ring (recommended)
- Mesh (recommended)

Chain:



Typical chain topology



Chain

The switches on the ends of the chain only have a single link back to the adjacent switch. For the inactive fragment, the switches remain powered on and create a separate stack, but all of network ports on the switches in the inactive fragment become disabled and do not pass network traffic. Chain topologies are not recommended because a single failure

When stacking failure at the switch, stacking module, or cable level, will cause switch-to-switch communication failures between switches that are located on opposite sides of the failure.

Up to 10 switches may be stacked in an open-ended chain with single cables between each pair.

Two-member chain topology (One 0.5 meter stacking cables) Three member chain topology (two 0.5 meter stacking cables) Four-member chain topology (three 0.5 meter stacking cables)



RING:

Ring topologies afford some protection from a single failure because communications between the switches continues, in a direction away from the failure

Up to 10 switches may be connected in a closed ring topology.

In a ring topology, two stacking ports are used on each switch..

Note that any one of the 4 stacking ports on the stacking module can be used to connect to any stacking port on the stacking module of the neighboring switch.



Typical Ring topology



7



MESH:

The mesh topology supports two to five stacked switches. Here we see examples of each supported configuration, with 2, 3 4 and 5 switches. In mesh topologies, every switch in the stack is connected to every other switch in the stack. So for example, with four stacking ports on the Stacking Module, the maximum number of switches that can be meshed together is limited to five, as shown. Mesh topologies provide the most protection from stacking failures because communications can be rerouted through multiple paths. Note that in all but the 4-switch configuration, all four stacking ports are connected.

Meshing is the recommended topology, whenever possible.





Traffic flow

RING



MESH



The hardware detects the stacking failure and notifies the Software. The hardware automatically redirects the packets through the stack. Hardware detect time < 1 µs



The packets use the shortest path through the Stack

The Hardware detects the Stacking failure and notifies the Software. The Hardware automatically redirects the packets through the Stack. Hardware detect time <1µsec

The switch updates the path that the packets will use through the Stack Initial failure detected quickly and redirected in hardware Gives time for software to update mesh forwarding tables

Topology supported

Тороlоду	No of members	Stacking cables
Chain	10	9
Ring	10	10
Mesh	5	10

Stacking Roles

Commander

Commander – This type indicates that this is the current commander of the stack. Note: In some stack merge cases two switches can momentarily assume that they are commanders until the stack is merged.

Runs network control and management protocols (STP, LACP, RIP, OSPF, Telnet, SNMP...) Syncs protocol states to the "Standby" for hitless failover. Manages the ASIC (forwarding) tables of *all* switches in the stack

Standby – This type indicates that this is the current standby switch.

Provides commander-level HA Receives configuration and protocol state information from Commander. Runs protocols in passive mode where their runtime states are updated based on sync from Commander. Is ready to take over as Commander of the Stack should the Commander fail

 Member – This is a switch that is active in the stack but is not the commander or standby switch. Remaining switches (if any) are "Member" switches
 Only have a copy of the configuration but no knowledge of protocol state
 Will be upgraded to Standby if commander/standby fails

Stacking configuration Methods

- Plug-and-go method
- Deterministic method

plug-and-go method

Factory-reset switches Power-off switches Reboot

If you don't care which switch functions as the Commander and Standby member, use can use the plug-and-go-method. The plug-and-go method only requires a few steps.

- 1. Power off all switches that will be part of the stack.
- 2. Install the stacking modules in the switches.
- 3. Power on the first switch and enable stacking if necessary. The switch will automatically reboot.
- 4. Power off the switch.

Repeat the process for each switch.

Next, connect the stacking cables to create your stacking topology. Always connect the stacking cables with the power off. Connecting the cables during or after a switch reboot can result in multiple stacks being formed.

Then, power on the switches. If they're all powered on at approximately the same time, the election process will begin after about 60 seconds after the switches fully reboot. The Commander and Standby will be elected and the remaining switches will be assigned a Member ID.

Continued...

Deterministic method

- Configure Commander priority
- Configure the Standby
- Configure members priority
- Configure OOBM port Member IP addresses

1. The Deterministic method, which results in specific switches being the stack commander and Standby and all remaining switches being stack members.

2. The Deterministic method will allow the administrator to specify which model of the switch that will be the commander and which model of the switch would be Standby.

CLI configurations

Plug-and-go method

- Insert the stacking module
- Factory reset the switch
- Enable stacking on the switch

(config)# stacking enable This will save the current configuration and reboot the switch. Continue [y/n]

show stacking

Stack ID : NO ID - will merge upon connectivity

MAC Address : f40343-3505c5 Stack Topology : No Stack Formed Stack Status : No Stack Formed Split Policy : One-Fragment-Up Uptime : Od Oh 2m Software Version : KB.16.02.0025

Mbr

ID Mac Address Model

Pri Status

*1 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot ... 128 Commander

Continued...

- Similarly perform the step on the secondary switch in order to join the stack
- After the switch comes up then connect the stacking cable to the secondary
- The switch will experience a reboot post the stacking cable connection

Post the connection

stack1# stack1# show stacking

Stack ID: 000200fd-4575a280MAC Address: 00fd45-75a2c4Stack Topology: ChainStack Status: Fragment ActiveSplit Policy: One-Fragment-UpUptime: 0d 0h 13mSoftware Version: KB.16.02.0025

Mbr

ID Mac Address Model

Pri Status

*1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot ... 128 Commander 2 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot ... 128 Missing

Plug-and-go method

After secondary switch comes up it established the connection to the commander

Stack ID: 000200fd-4575a280MAC Address: 00fd45-75a2c4Stack Topology: ChainStack Status: ActiveSplit Policy: One-Fragment-UpUptime: 0d 0h 17mSoftware Version: KB.16.02.0025

Mbr

ID Mac Address Model Pri Status

*1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot ... 128 Commander

2 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot ... 128 Standby

show stacking stack-ports

Up 2 1 1 1 2 0 Down 0 1 3 0 Down 0 4 Down 0 0 1 2 1 1 Up 1 2 2 Down 0 0 2 3 Down 0 0 0 2 4 Down 0

_____ ____

---- Reverse event Log listing: Events Since Boot ----

I 09/21/18 20:19:39 00179 mgr: ST1-CMDR: SME Console redirection from member 2 - MANAGER Mode I 09/21/18 20:17:35 00540 stacking: ST1-CMDR: Redundant Standby Management Module syncing is complete. Configuration changes are allowed I 09/21/18 20:17:35 03272 stacking: ST1-CMDR: Stack active I 09/21/18 20:17:35 03260 stacking: ST2-STBY: Member booted M 09/21/18 20:16:39 02797 chassis: ST2-STBY: Internal power supply 1 is OK. Total fault count: 0. M 09/21/18 20:16:39 02796 chassis: ST2-STBY: Internal power supply 1 inserted. Total fault count: 0. I 09/21/18 20:16:37 00540 stacking: ST1-CMDR: Redundant Standby Management Module syncing is in progress. Configuration changes are temporarily blocked I 09/21/18 20:16:28 00539 stacking: ST1-CMDR: Initial sync to standby starting W 09/21/18 20:16:28 03270 stacking: ST1-CMDR: Topology is a Chain I 09/21/18 20:16:28 00422 chassis: ST1-CMDR: Slot 2/1-24, A Ready I 09/21/18 20:16:20 00376 chassis: ST1-CMDR: Slot 2/1-24, A Download Complete I 09/21/18 20:16:19 00375 chassis: ST1-CMDR: Slot 2/1-24, A Downloading I 09/21/18 20:16:19 03846 InSysProg: ST1-CMDR: Slot 2/1-24,A: Checking for firmware updates. -- MORE --, next page: Space, next line: Enter, guit: Control-Cl 09/21/18 20:16:07 03279 stacking: ST1-CMDR: Member 2 (f40343-34f900) chosen as -- MORE --, next page: Space, next line: Enter, quit: Control-C standby. Reason: Only available standby -- MORE --, next page: Space, next line: Enter, guit: Control-Cl 09/21/18 20:16:07 02558 chassis: ST1-CMDR: Stack port 1 is now on-line.

-- MORE --, next page: Space, next line: Enter, quit: Control-Cl 09/21/18 20:15:19 02559 chassis: ST1-CMDR: Stack port 1 is now off-line.

-- MORE --, next page: Space, next line: Enter, quit: Control-Cl 09/21/18 20:15:14 03272 stacking: ST1-CMDR: Stack fragment active

Continued

show stacking

Stack ID: 000200fd-4575a280MAC Address: 00fd45-75a2c4Stack Topology: ChainStack Status: ActiveSplit Policy: One-Fragment-UpUptime: 0d 0h 40mSoftware Version: KB.16.02.0025

Mbr

ID Mac Address Model

Pri Status

1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot ... 128 Commander *2 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot ... 128 Standby 3 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot ... 128 Member 4 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot ... 128 Member ---- Reverse event Log listing: Events Since Boot ----

I 09/21/18 20:39:29 03125 mgr: ST1-CMDR: Startup configuration changed by SNMP. New seq. number 17

I 09/21/18 20:39:29 02682 OOBM: ST4-MMBR: OOBM - Enabled globally.
I 09/21/18 20:39:29 02612 mgr: ST1-CMDR: chassis subsystem saved the whole running config to startup config.
I 09/21/18 20:39:29 03260 stacking: ST4-MMBR: Member booted
M 09/21/18 20:39:29 02797 chassis: ST4-MMBR: Internal power supply 1 is OK. Total fault count: 0.
M 09/21/18 20:39:29 02796 chassis: ST4-MMBR: Internal power supply 1 inserted. Total fault count: 0.
I 09/21/18 20:38:53 00068 chassis: ST4-UKWN: Slot 4/25-48,A Inserted
I 09/21/18 20:38:53 00068 chassis: ST4-UKWN: Slot 4/1-24,A Inserted
I 09/21/18 20:38:49 02558 chassis: ST4-UKWN: Slot 4/1-24,A Inserted
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Member 1: flexible module JL079A in slot Expansion Module A is active.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Stack port 2 cable inserted.
I 09/21/18 20:38:45 05047 chassis: ST4-UKWN: Member 1: flexible module JL079A in slot Stacking Module is active.
I 09/21/18 20:38:32 05045 chassis: ST4-UKWN: Member 1: Flexible Module JL079A inserted in slot Expansion Module A

-- MORE --, next page: Space, next line: Enter, quit: Control-CI 09/21/18 20:38:26 03803 chassis: ST4-UKWN: System Self test completed on Master

I 09/21/18 20:38:26 05046 chassis: ST4-UKWN: Flexible Module JL084A inserted in slot Stacking Module
I 09/21/18 20:38:25 03802 chassis: ST4-UKWN: System Self test started on Master
I 09/21/18 20:38:24 03803 chassis: ST4-UKWN: System Self test completed on Master
I 09/21/18 20:38:24 03802 chassis: ST4-UKWN: System Self test started on Master
I 09/21/18 20:39:28 00539 stacking: ST1-CMDR: Initial sync to member 4 complete
I 09/21/18 20:39:20 00539 stacking: ST1-CMDR: Initial sync to member 4 starting
I 09/21/18 20:39:20 00422 chassis: ST1-CMDR: Slot 4/1-24, A Ready
I 09/21/18 20:39:20 00422 chassis: ST1-CMDR: Slot 4/1-24, A Download Complete
I 09/21/18 20:39:12 00376 chassis: ST1-CMDR: Slot 4/1-24, A Download Complete
I 09/21/18 20:39:11 00375 chassis: ST1-CMDR: Slot 4/1-24, A Downloading
I 09/21/18 20:39:11 00375 chassis: ST1-CMDR: Slot 4/25-48, A Downloading
I 09/21/18 20:39:11 03846 InSysProg: ST1-CMDR: Slot 4/1-24, Checking for firmware updates.
I 09/21/18 20:39:11 03846 InSysProg: ST1-CMDR: Slot 4/25-48, A: Checking for firmware updates.
I 09/21/18 20:39:11 03846 InSysProg: ST1-CMDR: Slot 4/25-48, A: Checking for firmware updates.
I 09/21/18 20:39:11 03846 InSysProg: ST1-CMDR: Slot 4/25-48, A: Checking for firmware updates.

CLI Configurations

Deterministic method

switch2(config)# stacking member 1 type JL073A mac-address f40343-350480 switch2(config)# stacking member 2 priority 200

switch2(config)# show stacking

Stack ID: 000af403-43350480MAC Address: f40343-3504d9Stack Topology: UnknownStack Status: ActiveSplit Policy: One-Fragment-UpUptime: 0d 0h 8mSoftware Version: KB.16.05.0009

Mbr

ID Mac Address Model Pri Status

*1 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 200 Commander

Deterministic method

	Aruba-Stack-3810M(config)# show stacking
Aruba-Stack-3810M(config)# stacking member 4 type JL073A mac-address f40343-34f900	Stack ID : 0001f403-43350580
This will save the current configuration. Continue [y/n]? y	MAC Address : f40343-3505c5
Aruba-Stack-3810M(config)# stacking member 4 priority 255	Stack Topology : Ring
Aruba-Stack-3810M(config)# stacking member 1 type JL074A mac-address 00fd45-75a280	Stack Status : Active
This will save the current configuration. Continue [y/n]? y	Split Policy : One-Fragment-Up
Aruba-Stack-3810M(config)# stacking member 1 priority 200	Uptime : 0d 18h 4m
Aruba-Stack-3810M(config)# stacking member 2 type JL073A mac-address f40343-350480	Software Version : KB.16.06.0006
This will save the current configuration. Continue [y/n]? y	
Aruba-Stack-3810M(config)# stacking member 3 type JL074A mac-address f40343-350580	Mbr
This will save the current configuration. Continue [y/n]? y	ID Mac Address Model Pri Status
	1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot 200 Standby 2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot 150 Member

3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member *4 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 255 Commander

CLI configurations

Aruba-Stack-3810M(config)# show stacking detail Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Ring Stack Status : Active Split Policy : One-Fragment-Up : 0d 18h 7m Uptime Software Version : KB.16.06.0006 : Aruba-Stack-3810M Name Contact : Location :

Member ID :1 Mac Address : 00fd45-75a280 Type : JL074A Model : Aruba JL074A 3810M-48G-PoE+-1-slot Switch Priority : 200 Status : Standby ROM Version : KB.16.01.0008 Serial Number : SG74GYX11D Uptime : 0d 18h 7m CPU Utilization : 0% Memory - Total : 692,510,720 bytes Free : 520,358,672 bytes

Member ID : 2 : f40343-350480 Mac Address Type : JL073A : Aruba JL073A 3810M-24G-PoE+-1-slot Switch Model Priority : 150 Status : Member ROM Version : KB.16.01.0008 Serial Number : SG76GYW02X : 0d 18h 7m Uptime CPU Utilization : 0% Memory - Total : 692,510,720 bytes Free : 535,566,768 bytes

Stack Ports -#1 : Inactive #2 : Active. Peer member 4 #3 : Inactive #4 : Active, Peer member 3

Stack Ports -#1 : Inactive #2 : Active. Peer member 4 #3 : Inactive #4 : Active, Peer member 3

Member ID : 3 Mac Address : f40343-350580 Type : JL074A Model : Aruba JL074A 3810M-48G-PoE+-1-slot Switch Priority : 100 Status : Member ROM Version : KB.16.01.0008 Serial Number : SG76GYX1WR Uptime : 0d 18h 7m CPU Utilization : 0% Memory - Total : 692,510,720 bytes Free : 535,566,216 bytes

Stack Ports -#1 : Active. Peer member 1 #2 : Inactive #3 : Active, Peer member 2 #4 : Inactive

Member ID :4

Mac Address : f40343-34f900 Type : JL073A Model : Aruba JL073A 3810M-24G-PoE+-1-slot Switch : 255 Priority Status : Commander ROM Version : KB.16.01.0008 Serial Number : SG76GYW041 Uptime : 0d 18h 7m CPU Utilization : 0% Memory - Total : 692,510,720 bytes Free : 503,303,368 bytes

Stack Ports -#1 : Inactive #2 : Inactive #3 : Active. Peer member 2 #4 : Active. Peer member 1

Stacking Election:

Commander elected as follows:

Choose the switch with the highest configured priority as the commander. Out of the switches with the same "highest" priority, pick the one that was the previous active commander. If none were the previous active commander, then pick the one that was previous Standby . If none were the previous Standby, then pick the one that has the highest software version . Else pick the switch with the lowest MAC address.

Standby elected as follows

Choose the switch which has the same software version as the commander.

If none have the same software version, then choose the switch with the highest configured priority as the Standby

Out of the switches with the same "highest" priority, pick the one that is at furthest distance from the commander.

Else pick the switch with the lowest MAC address



Stack ID:

This is the identification number of the stack (all switches in the same stack share the same stack ID).

This value set by the commander and stays with the stack. When the stack ID is initially generated, it is created using the current commander MAC address

Adding a switch to stack

Provision^[] the stack for the new switch with the following command on the stack

(config)#: stacking member <n> type <JxxxxA> [mac <MAC-address>]

I,e (config)# stacking member 3 type JL074A mac-address f40343-350580

where: n is the stacking member number for the switch JxxxxA is the product number of the switch (required).

Any supported model can be installed and assume this provisioned configuration. If you specify a value for this parameter, then only a switch of this specific model type can assume this provisioned configuration

(Optional) MAC-address can be specified if you want a specific switch to assume this provisioned configuration. If this value is entered, then the type value for the switch that has this MAC address must be correct, or a configuration error is logged and the switch is not allowed to join the stack.

(Optional) You can pre-configure a priority for the member switch by entering this command: HP Switch(config)#: stacking member N priority X

I,e config)# stacking member 3 priority 100

Where:

n is the stacking member number for the switch.

x is the priority (1 - 255, but should be less than the priority assigned to the Commander — the priority for the Standby should be the second highest in the stack; member switches can be left at the default priority value of 128).

Ensure the new member switch is factory defaulted before connecting it to stack

Redundancy switchover

(config)# stacking member 4 remove The commander cannot be removed. Please failover to standby before trying to remove it.

Commander cannot be removed from the stack, in order to remove it we need to move to to Standby/member using "redundancy switchover"

(config)# stacking member 4 remove The commander cannot be removed. Please failover to standby before trying to remove it.

Console to standby and execute

Aruba-Stack-3810M(config)# redundancy switchover Aruba-Stack-3810M(config)# redundancy switchover The commander will now reboot from the secondary image. The standby will become the commander. Do you want to continue [y/n]? y

Now stack member 1 has become the commander and priority switch has become the standby

Mbr

ID Mac Address Model Pri Status

*1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot... 200 Commander

2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Standby

3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member

4 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 255 Member

Remove and renumber the member

Aruba-Stack-3810M(config)# stacking member 4 remove

The specified stack member will be removed from the stack and

its configuration will be erased. The resulting configuration

will be saved. The stack member will be shutdown. Continue [y/n]? y

Mb	or		
ID	Mac Address	Model	Pri Status
*1	00fd45-75a280	Aruba	JL074A 3810M-48G-PoE+-1-slot 200 Commande
2	f40343-350480	Aruba 、	JL073A 3810M-24G-PoE+-1-slot 150 Standby
3	f40343-350580	Aruba 、	JL074A 3810M-48G-PoE+-1-slot 100 Member

We cannot remove a stack member if that would result in the split stack

Aruba-Stack-3810M(config)# stacking member 3 remove

Reloading this member is not allowed since it would result in a stack split.

Mbr ID Mac Address 	Model	Pri Status
*1 00fd45-75a280	Aruba JL074A 3810M	I-48G-PoE+-1-slot 200 Commander
2 f40343-350480	Aruba JL073A 3810M	I-24G-PoE+-1-slot 150 Standby
3 f40343-350580	Aruba JL074A 3810M	I-48G-PoE+-1-slot 100 Member
4 f40343-34f900	Aruba JL073A 3810M	-24G-PoE+-1-slot 255 Member



Applying redundancy switchover

Will perform a switch over now so we can remove the member

Aruba-Stack-3810M(config)# redundancy switchover

The commander will now reboot from the secondary image	. The standby
--	---------------

will become the commander. Do you want to continue [y/n]?

Mbr

	Model r	rn Status	Ν	1br		
			IC	D Mac Address	Model	Pri Status
1 00fd45-75a280	Aruba JL074A 3810M-48G-	PoE+-1-slot 200 Commander				
2 f40343-350480	Aruba JL073A 3810M-24G	PoE+-1-slot 150 Standby	**	00fd45-75a280 f40343-350480	Aruba JL074A 3810M-480 Aruba JL073A 3810M-24	G-PoE+-1-slot 200 Member G-PoE+-1-slot 150 Commander
3 f40343-350580	Aruba JL074A 3810M-48G-	PoE+-1-slot 100 Member	3	3 f40343-350580	Aruba JL074A 3810M-480	G-PoE+-1-slot 100 Standby
			М	br		
Aruba-Stack-3	810M(config)# stacking mem	ber 1 remove	M	br D Mac Address	Model	Pri Status
Aruba-Stack-3 The specified	810M(config)# stacking mem stack member will be remove	ber 1 remove d from the stack and	M	br D Mac Address	Model	Pri Status
Aruba-Stack-3 The specified its configuratio	810M(config)# stacking mem stack member will be remove on will be erased. The resultin	ber 1 remove d from the stack and g configuration	M 1[br D Mac Address 	Model Aruba JL073A 3810M-240	Pri Status G-PoE+-1-slot 150 Commander

Renumbering the members to join the stack

The removed members will be unresponsive from stack on console

Renumber the stack 4 to 1 and 1 to 4

Aruba-Stack-3810M(config)# stacking member 1 type

JL071A JL072A JL073A JL074A JL075A JL076A

Aruba-Stack-3810M(config)# stacking member 1 type JL073A mac-address f40343-34f900 This will save the current configuration. Continue [y/n]? y

Aruba-Stack-3810M(config)# stacking member 4 type JL074A mac-address 00fd45-75a280 This will save the current configuration. Continue [y/n]?

Pri Status

Mbr

ID Mac Address Model

 1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Not Joined

 2
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander

 *3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Standby

 4
 00fd45-75a280
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Not Joined

After connecting the members to the stack

Aruba-Stack-3810M(config)#

Mbr

ID Mac Address Model Pri Status

1	f40343-34f900	Aruba JL073A 3810M-24G-PoE+-1-slot 128 Member
2	f40343-350480	Aruba JL073A 3810M-24G-PoE+-1-slot 150 Commander
*3	f40343-350580	Aruba JL074A 3810M-48G-PoE+-1-slot 100 Standby
4	00fd45-75a280	Aruba JL074A 3810M-48G-PoE+-1-slot 128 Member



Mb	or			
ID	Mac Address	Model	Pri Status	
1	00fd45-75a280	Aruba JL074A	3810M-48G-PoE+-1-slot 200 Standby	
2	f40343-350480	Aruba JL073A	3810M-24G-PoE+-1-slot 150 Member	
3	f40343-350580	Aruba JL074A	3810M-48G-PoE+-1-slot 100 Member	
*4	f40343-34f900	Aruba JL073A	3810M-24G-PoE+-1-slot 255 Comman	der

Replacing a faulty member

Aruba-Stack-3810M# show stacking
Stack ID : 0001f403-43350580
MAC Address : f40343-3505c5
Stack Topology : Chain
Stack Status : Fragment Active
Split Policy : One-Fragment-Up
Uptime : 1d 0h 37m
Software Version : KB.16.06.0006

Mbr

ID Mac Address Model

(config)# stacking member 4 remove

Pri Status

 *1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Member

 2
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander

 3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Standby

 4
 00fd45-75a280
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Missing

Aruba-Stack-3810M(config)# stacking member 4 type JL074A mac-address 00fd45-78f480

This will save the current configuration. Continue [y/n]? y

Status not joined

Aruba-Stack-3810M(config)# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Active Split Policy : One-Fragment-Up Uptime : 1d 1h 10m Software Version : KB.16.06.0006

Mbr

ID Mac Address	Model	Pri Status	
*1 f40343-34f900	Aruba JL073A	3810M-24G-PoE+-1-slot	128 Member
2 f40343-350480	Aruba JL073A	3810M-24G-PoE+-1-slot 1	150 Commander
3 f40343-350580	Aruba JL074A	3810M-48G-PoE+-1-slot 1	100 Standby
4 00fd45-78f480	Aruba JL074A	3810M-48G-PoE+-1-slot 1	.28 Not Joined

- · Verify the the switch is factory defaulted before connecting
- Check the connecting switch is in the same supported J series using below command

Aruba-Stack-3810M(config)# stacking member 1 type

JL071A JL072A JL073A JL074A JL075A JL076A

• Add the new member to the existing stack which would result in reboot before joining the stack

Member joining the stack

New member trying to join the stack The software version of this switch doesn't match the stack commander, waiting for reboot...

 Mbr
 Pri Status

 ID
 Mac Address
 Model
 Pri Status

 **1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Member

 2
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander

 3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Standby

 4
 00fd45-78f480
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Member

· We can add the new member just by adding the type

Aruba-Stack-3810M(config)# stacking member 5 type JL074A

This will save the current configuration. Continue [y/n]? y

Aruba-Stack-3810M(config)# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Active Split Policy : One-Fragment-Up Uptime : 1d 1h 27m Software Version : KB.16.06.0006 Mbr ID Mac Address Model Pri Status

 *1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Member

 2
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander

 3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Standby

 4
 00fd45-78f480
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Member

5 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Not Joined

MAC address will be learnt once the new member is installed in stack

Stack fragment

This detection logic, when it sees that one or more switches of the stack are missing and unreachable, it takes a decision whether the remaining switches (called a stack fragment) constitute a greater stack than the switches that are missing.

When the lesser fragment is re-connected to the greater stack fragment, the switches will reboot and join the stack with the configuration available on the greater fragment

All-Fragments-Up. With this setting, all fragments of a split-stack would continue forwarding traffic. Configuration changes would also be allowed on all fragments

If the user performs any configuration changes on more than one fragment, the merge of these fragments WILL NOT be automatic when reconnected. The two fragments will continue switching traffic independently. The user would be required to explicitly execute manager-mode command "stacking factory-reset"

If the user has not made any configuration changes on any fragment, the fragments will merge automatically when reconnected.

The stack will never become an "inactive fragment" if the "all-fragments-up"

If user issued a "stacking set-stack" command on the split condition the Inactive fragment can become active



Aruba-Stack-3810M# show stacking Stack ID : 0011f403-43350480 MAC Address : f40343-3505c4 Stack Topology : Chain	
Stack Status : Active	
Split Policy : One-Fragment-Up	
Uptime : 0d 0h 4m	
Software Version : KB.16.06.0006	
Mbr	
ID Mac Address Model	Pri Status
1 f40242 24f000 Amile U 0724 20	
1 140343-341900 Aruba JL073A 38	10M-24G-POE+-1-SIOt 200 Not Joined
3 140343-350580 Aruba JL074A 38	310M-48G-PoE+-1-slot 100 Commander
4 00fd45-78f480 Aruba JL074A 38	10M-48G-PoE+-1-slot 250 Not Joined
*5 f40343-350480 Aruba JL073A 3	810M-24G-PoE+-1-slot 128 Standby

Stack-fragment

Aruba-Stack-3810M(config)# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain			
Stack Status : Active			
Split Policy : One-Fragment-Up			
Uptime : 1d 2h 19m			
Software Version : KB.16.06.0006			
Mbr			
ID Mac Address Model	Pri Status		
*1 f40343-34f900 Aruba JL073A 3810M-24 2 f40343-350480 Aruba JL073A 3810M-24 3 f40343-350580 Aruba JL074A 3810M-48 4 00fd45-78f480 Aruba JL074A 3810M-486	 -G-PoE+-1-slot 128 Member G-PoE+-1-slot 150 Commander G-PoE+-1-slot 100 Standby G-PoE+-1-slot 128 Member		
Aruba-Stack-3810M(config)# stacking split-p	olicy all-fragments-up		
Aruba-Stack-3810M(config)# show stackir	na		
Stack ID : 0001f403-43350580	5		
MAC Address : f40343-3505c5			
Stack Topology : Chain			
Stack Status : Fragment Active			
Split Policy : All-Fragments-Up			
Uptime : 1d 2h 24m			
Soliware Version : KB.16.06.0006			
ID Mac Address Model	Pri Status		

 1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot...
 128 Missing

 2
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot...
 150 Commander

 *3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot...
 100 Standby

 *0
 00f445-30f400
 Aruba JL074A 3810M-48G-PoE+-1-slot...
 100 Standby

4 00fd45-78f480 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Member

Aruba-Stack-3810M(config)# stacking split-policy one-fragment-up

Aruba-Stack-3810M(config)# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Active Split Policy : One-Fragment-Up

Software Version : KB.16.06.0006

Mbr ID Mac Address Pri Status Model Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Missing 1 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander 2 f40343-350480 *3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Standby 4 00fd45-78f480 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Member Aruba-Stack-3810M# show stacking Stack ID :0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Inactive Split Policy : One-Fragment-Up : 0d 4h 5m Uptime Software Version : KB.16.06.0006 Mbr ID Mac Address Pri Status Model 1 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Missing 2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander 3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Missing 4 00fd45-78f480 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Missing

OOBM (Out-Of-Band-Management)

When using stacking, the user often does not know which switch is the "commander switch" at any given point of time; therefore, any OOBM port may be used to manage the whole stack

The Stacking OOBM Discovery Protocol is designed for;

Discovering OOBM ports on the same network Discovering other members of a split stack Helping to make decision on Active Lesser Stack

Thus the overall design of the protocol is Broadcast (at appropriate time) packets from an OOBM port. No acknowledgement of packets. The discovery packets will be Layer 2 packets. They will be broadcasted with commander's OOBM port MAC as source MAC address.

Packets will be sent out with a 30 second interval. Send a packet out of the commander's OOBM port; Mark down all OOBM ports it arrives on as duplicative ports (and don't send out packets from them); Send the next packet out of the next OOBM port that is not marked as duplicative port yet; Repeat (up to 10 times maximum) until all OOBM ports have had a packet sent out, or have been marked as duplicative;

Packets will be resent on:

Any topology change (member joins or leaves stack, commander changes);

Any topology change has been received from another switch, that indicates that the switch is using the commander's OOBM MAC address or commander's OOBM IP address; If switch decides to become an active "lesser" stack.

The commander will have full control of the Stacking OOBM discovery protocol.

The commander will forward the results of the Stacking OOBM Discovery Protocol to all the members if there is a change. As a result, each member will have last information from Stacking OOBM Discovery protocol. The protocol doesn't become active until a commander is elected

OOBM during split situation

Aruba-Stack-3810M# show stacking :0001f403-43350580 Stack ID MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Active Split Policy : One-Fragment-Up Uptime : 0d 1h 41m Software Version : KB.16.06.0006 Mbr ID Mac Address Pri Status Model ___ _____ 1 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Standby 2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Missing 3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member 4 00fd45-78f480 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Commander Aruba-Stack-3810M# show oobm discovery Active Stack Fragment(local)

IP Address : 10.10.10.1 Mbr Mac Address Status

4 00fd45-78f480 Commander 1 f40343-34f900 Member 3 f40343-350580 Member Inactive Stack Fragment(discovered) IP Address : 10.10.10.4 Mbr Mac Address Status ID

2 f40343-350480 Commander

Member console

Aruba-Stack-3810M# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Active Split Policy : One-Fragment-Up Uptime : 0d 1h 44m Software Version : KB.16.06.0006

Mbr						
ID	Mac Address	Model	Pri Status			
1	f40343-34f900	Aruba JL073	A 3810M-24G-PoE+-1-slot 128 Standby			
2	f40343-350480	Aruba JL073	A 3810M-24G-PoE+-1-slot 150 Missing			
3	f40343-350580	Aruba JL074	A 3810M-48G-PoE+-1-slot 100 Member			
*4	00fd45-78f480	Aruba JL074	A 3810M-48G-PoE+-1-slot 128 Commander			

OOBM discovery

From commander:

Aruba-Stack-3810M# show stacking : 0001f403-43350580 Stack ID MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Active Split Policy : One-Fragment-Up Uptime : 0d 5h 34m Software Version : KB.16.06.0006 Mbr ID Mac Address Model Pri Status 1 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Standby 2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Missing 3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member *4 00fd45-78f480 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Commander

From the lost member:

Aruba-Stack-3810M# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Inactive Split Policy : One-Fragment-Up Uptime : Od 4h 1m Software Version : KB.16.06.0006 Mbr ID Mac Address Model Pri Status

 1 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Missing

 *2 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Commander

 3 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Missing

 4 00fd45-78f480
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Missing

Accessed via OOBM ip interface of member

Aruba-Stack-3810M# show stacking Stack ID : 0001f403-43350580 MAC Address : f40343-3505c5 Stack Topology : Chain Stack Status : Fragment Inactive Split Policy : One-Fragment-Up Uptime : 0d 4h 5m Software Version : KB.16.06.0006

Mbr

ID	Mac Address	Model	Pri Status
1	f40343-34f900	Aruba JL073A 3810M-24	4G-PoE+-1-slot 128 Missing
2	f40343-350480	Aruba JL073A 3810M-2	4G-PoE+-1-slot 150 Commander
3	f40343-350580	Aruba JL074A 3810M-4	8G-PoE+-1-slot 100 Missing
4	00fd45-78f480	Aruba JL074A 3810M-4	8G-PoE+-1-slot 128 Missing

Aruba-Stack-3810M# show oobm discovery Inactive Stack Fragment(local) IP Address : 10.10.10.4 Mbr Mac Address Status ID

2 f40343-350480 Commander

Active Stack Fragment(discovered) IP Address : 10.10.10.1 Mbr Mac Address Status ID

4 00fd45-78f480 Commander 1 f40343-34f900 Member 3 f40343-350580 Member

OOBM Global access

Aruba-Stack-3810M# show oobm discovery Active Stack Fragment(local) IP Address : 10.10.10.1 Mbr Mac Address Status ID

4 00fd45-78f480 Commander 1 f40343-34f900 Member 3 f40343-350580 Member

Inactive Stack Fragment(discovered)

IP Address : 10.10.10.4 Mbr Mac Address Status

ID

2 f40343-350480 Commander

Troubleshooting stacking

Here member 2 stack connection was pulled down manually

Run the RMON logs to instantly check the events

Show logging -r -s

I 09/24/18 15:44:27 03260 stacking: ST4-CMDR: Member booted
I 09/24/18 15:44:27 03261 stacking: ST4-CMDR: Member active
I 09/24/18 15:44:27 03401 crypto: ST4-CMDR: Function POWER UP passed selftest.
I 09/24/18 15:44:26 02682 OOBM: ST3-MMBR: OOBM - Enabled globally.
I 09/24/18 15:44:27 00539 stacking: ST4-CMDR: Initial sync to member 3 complete
I 09/24/18 15:44:26 00539 stacking: ST4-CMDR: Initial sync to member 3 starting
I 09/24/18 15:44:26 00539 stacking: ST4-CMDR: Initial sync to standby starting
I 09/24/18 15:44:25 00539 stacking: ST4-CMDR: Initial sync to member 3 starting
I 09/24/18 15:44:25 03260 stacking: ST4-CMDR: Initial sync to member 3 starting
I 09/24/18 15:44:25 03270 stacking: ST4-CMDR: Topology is a Chain
I 09/24/18 15:44:25 03279 stacking: ST4-CMDR: Member 1 (f40343-34f900) chosen as standby. Reason: Highest switch priority
I 09/24/18 15:44:25 00803 usb: ST4-CMDR: port enabled.
I 09/24/18 15:44:25 00110 telnet: ST4-CMDR: telnetd service enabled

1 09/24/18 15:44:25 00110 teinet: ST4-CMDR: teinetd service enabled
1 09/24/18 15:44:25 00116 teinet: ST4-CMDR: teinetd service enabled on OOBM
1 09/24/18 15:44:24 02712 console: ST4-CMDR: USB console cable disconnected
1 09/24/18 15:44:24 02712 console: ST4-CMDR: USB console cable disconnected
1 09/24/18 15:44:24 0061 system: ST4-CMDR:
1 09/24/18 15:44:24 03267 stacking: ST4-CMDR: Failover occurred
1 09/24/18 15:44:24 03272 stacking: ST4-STBY: Stack fragment active

W 09/24/18 15:44:24 03270 stacking: ST4-STBY: Topology is a Chain 09/24/18 15:44:24 03278 stacking: ST4-STBY: Member 4 (00fd45-78f480) elected as commander. Reason: Standby takeover W 09/24/18 15:44:24 03258 stacking: ST4-STBY: Commander switch with Member ID 2 removed due to loss of communication I 09/24/18 15:44:24 02559 chassis: ST1-MMBR: Stack port 4 is now off-line. I 09/24/18 15:44:19 02557 chassis: ST2-CMDR: Stack port 4 cable removed. I 09/24/18 15:44:15 02556 chassis: ST2-CMDR: Stack port 4 cable inserted. W 09/24/18 15:44:10 05227 activate: ST2-CMDR: Time synchronization failed; retry time sync after 60 seconds. W 09/24/18 15:44:10 05626 activate: ST2-CMDR: Time sync with HTTP server failed. 1 09/24/18 15:44:08 05625 activate: ST2-CMDR: Trying to sync switch time with HTTP server. W 09/24/18 15:44:08 05626 activate: ST2-CMDR: Time sync with NTP server failed. 1 09/24/18 15:44:06 05625 activate: ST2-CMDR: Trying to sync switch time with NTP server. I 09/24/18 15:43:35 02557 chassis: ST2-CMDR: Stack port 3 cable removed. I 09/24/18 15:43:35 02559 chassis: ST2-CMDR: Stack port 3 is now off-line. W 09/24/18 15:43:35 03270 stacking: ST2-CMDR: Topology is a Chain W 09/24/18 15:43:06 05227 activate: ST2-CMDR: Time synchronization failed; retry time sync after 60 seconds.

Adding a mismatch MAC-address

Aruba-Stack-3810M(config)# stacking member 2 type JL073A mac-address **f40343-350470** This will save the current configuration. Continue [y/n]? y Aruba-Stack-3810M(config)# show stacking

Stack ID: 0001f403-43350580MAC Address: f40343-3505c5Stack Topology: ChainStack Status: ActiveSplit Policy: One-Fragment-UpUptime: 0d 3h 13mSoftware Version: KB.16.06.0006

Mbr

Stacking added based on the plug & play method

Mbr

 ID
 Mac Address
 Model
 Pri Status

 1
 f40343-34f900
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Standby

 2
 f40343-350470
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Not Joined

 *3
 f40343-350580
 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member

 4
 00fd45-78f480
 Aruba JL074A 3810M-48G-PoE+-1-slot... 128 Commander

 5
 f40343-350480
 Aruba JL073A 3810M-24G-PoE+-1-slot... 128 Member

Upgrade

KB.16.05.0009 to KB.16.06.0006

Load the software on the commander using TFTP/ USB/ Xmodem

Aruba-Stack-3810M# show flash Image

Primary Image : 33518097 06/20/18 KB.16.05.0009 Secondary Image : 33733822 06/22/18 KB.16.06.0006

Boot ROM Version

Primary Boot ROM Version : KB.16.01.0008 Secondary Boot ROM Version : KB.16.01.0008 Default Boot Image : Primary Default Boot ROM : Primary

Commander:

Aruba-Stack-3810M# boot system flash secondary Aruba-Stack-3810M# boot system flash secondary This will reboot the system from the secondary image. Continue (y/n)? Y

All the members will download the firmware from the commander

show stacking
Stack ID : 0001f403-43350580
MAC Address : f40343-3505c5
Stack Topology : Ring
Stack Status : Active
Split Policy : One-Fragment-Up
Uptime : 0d 0h 14m
Software Version : KB.16.06.0006
Mbr
ID Mac Address Model Pri Status

1 00fd45-75a280 Aruba JL074A 3810M-48G-PoE+-1-slot... 200 Standby

2 f40343-350480 Aruba JL073A 3810M-24G-PoE+-1-slot... 150 Member 3 f40343-350580 Aruba JL074A 3810M-48G-PoE+-1-slot... 100 Member

3 140343-330300 ATUBA 3L074A 3010WI-40G-FUET-1-SIUL... 100 WEITIDEI

*4 f40343-34f900 Aruba JL073A 3810M-24G-PoE+-1-slot... 255 Commander

Troubleshooting Stack issues

Check for Bad cabling & LED status Ensure that the cable is firmly connected at both ends If the problem continues replace the cable in connectivity If the problem continues, validate that it's not a faulty module port using a known good cable

Collect:

show stacking show system show modules show boot history show tech

Event Log

Show logging –r –s

Aruba-Stack-3810M# show stacking stack-ports Member Stacking Port State Peer Member Peer Port

1	1	Up	4	1	
1	2	Down	0	0	
1	3	Down	0	0	
1	4	Down	0	0	
3	1	Down	0	0	
3	2	Down	0	0	
3	3	Down	0	0	
3	4	Down	0	0	
4	1	Up	1	1	
4	2	Down	0	0	
4	3	Down	0	0	
4	4	Down	0	0	
5	1	Down	0	0	
5	2	Down	0	0	
5	3	Down	0	0	
5	4	Down	0	0	
	- Ctarl	201014	44		
Aruc Kau		3810101	# shc	w ioggin	g -r -s
key	S: VV=VV	arning		formatio	n
		ovonti	Debu	g E=Erro	nte Since Reat
00/	125 /10 0		OB IIS	7 obocci	NICS SINCE BOOL
09/	25/1804 1/25/1804	2:50:08	0200		ing: ST1-STBY: Stack port 4 cable removed.
v 0:	romov	02.30.0		cc of con	mg. 311-3101. Member switch with Member 10.5
	101				iniunication
V US	remov	ved due	to lo	ss of con	ing: STI-STBY: Member switch with Member ID 3
09/	25/18 02	2:50:08	0255	9 chassis	: ST1-STBY: Stack port 4 is now off-line.
)/JE /10	02.50.0			in a CT4 CMDD. Manshan available with Manshan ID

W 09/25/18 02:50:08 03258 stacking: ST4-CMDR: Member switch with Member ID 5 removed due to loss of communication
I 09/25/18 02:50:08 03272 stacking: ST4-CMDR: Stack fragment active
W 09/25/18 02:50:08 03258 stacking: ST4-CMDR: Member switch with Member ID 3 removed due to loss of communication
I 09/25/18 02:49:01 05101 amp-server: ST4-CMDR: AMP server configuration is disabled due to first configuration.
I 09/25/18 02:47:25 02559 chassis: ST3-MMBR: Stack port 1 is now off-line.
I 09/25/18 02:47:25 02557 chassis: ST4-CMDR: Stack port 4 cable removed.

I 09/25/18 02:47:25 02559 chassis: ST4-CMDR: Stack port 4 is now off-line.

When to choose BPF & FPS

FPS	BPS
Low cost	Performance
Simplicity	Reliability
Multi-wiring	stack up to 10 switches

QUESTIONS?



THANK YOU!

