

7200 Controller Partner Training

Hands-on Lab Guide: Migrating Configs from 3x00 Series Controller to 7200 series Local Controller and Backup Master Migration

 \odot 2012 by Aruba Networks - All rights reserved. This document is CONFIDENTIAL and for Aruba internal use only. Each product, process, and procedure referred to in this document contains the confidential and intellectual property of Aruba Networks. No part of this document may be used, copied, disclosed, or transferred to any party without prior written authorization from Aruba Networks.

CHANGE REVISION HISTORY

Author	Section Revised	Revision Level	Revision Date
Marcus Christensen	Revised student lab access.	1.1	2/2/2013



This page intentionally left blank



Table of Contents

1 /		5
2 S	AMPLE LOCAL CONTROLLER REPLACEMENT	9
2.2	Detailed Steps	0
3 S	AMPLE BACKUP MASTER REPLACEMENT	
3.1	Summarized Steps1	7
3.2	Detailed Steps1	8
4. A	PPENDIX	
4.4	Lab topology	9
4.5	Lab IP addresses and Terminal Server	0
4.6	Controller Licenses	1



This page intentionally left blank



7200 Series Migration Summary

When adding Aruba 7200 series controllers to an existing Aruba deployment all current controllers must match the ArubaOS software version of the new 7200 controllers (AOS 6.2.x or greater).



Migration Summary

- 1. Prior to doing anything backup the controller data from your existing controllers using the "backup flash" command. This is best practice for any software upgrade and allows for a rapid recovery if anything goes wrong.
- 2. Upgrade all controllers on your network to the latest version of ArubaOS 6.2.x. This ensures that the image on your new controllers matches the image of the rest of the controllers in your network.
- 3. Backup the controller data again using the "backup flash". The 6.2 configs and database will be saved. This will be used to bring the new 7200 controller online.
- 4. Transfer existing licenses to your new controller. Using the License Management Server (LMS) at https://licensing.arubanetworks.com/.
- 5. Install your new 7200 controller.
- Install the backed up data on your new 7200 controller using the "restore flash" command.
- 7. Apply transferred and any new licenses.
- 8. Update interface configuration and change the hostname.
- 9. Confirm that your new controller operates as expected.



Important Points to Remember

- Not all Aruba controller models support ArubaOS 6.2.x. The following controllers support ArubaOS 6.2.x:
 - M3
 - 3000 Series (3200XM model only)
 - 600 Series (651 internal AP disabled in 6.2.x; 600 series RAP limit lowers to match CAP limit)
 - 7200 Series
- When replacing **redundant master controllers**, always replace the **backup master** first to avoid unintentional failover
- If you are migrating to a 7200 Series controller from a controller not listed above, please contact Aruba support.

BEFORE YOU BEGIN

Backup Flash

It is important to frequently back up all critical configuration data and files on the compact flash file system to an *external server* or *external mass storage device*.

In the following sections the **Backup flash** command will be used to save the following:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Floor plan JPEGs
- Custom captive portal pages
- x.509 certificates
- Controller Logs

During the Flash backup process an archive file is created called *flashbackup.tar.gz*. When backing up multiple controllers it will be important to rename this file *so you can keep track of which controller it came from*. Ex: 3600_local1_flashbackup.tar.gz

If a custom filename is used, it must be renamed back to the generic **flashbackup.tar.gz** prior to the restore process, or the controller will not accept it.



License Transfer

Feature licenses are created using each controller's unique serial number plus the Certificate ID to generate the Installation Key and are only useable on the intended controller. When *replacing* a controller it is possible to transfer its licenses for use on the substituted controller via the License Management Server (LMS).

Before starting your migration you should transfer your licenses to the new controller platform unless purchasing a new set specifically for the 7200. Licenses are only transferable between "Next-Gen" controllers (65x, 3x00, M3, and 7200 series).

License Transfer Summary

- 1. Open a browser and navigate to <u>https://licensing.arubanetworks.com/</u> and login.
- 2. Navigate to **Certificate Management > Transfer certificate** and select the licenses you want to transfer.
- 3. All the certificates active on the controller of the license certificate you have selected will be displayed. Select all the certificates you would like to transfer.
- 4. Enter the serial number of the new controller and click **Transfer**.
- 5. When the transfer has been completed successfully, you will receive a new set of activation keys.

Upgrading to 6.2.x

ArubaOS 6.x is supported only on the newer MIPS controllers (M3, 3000 Series and 600 Series). Legacy PPC controllers (200, 800, 2400, SC1 and SC2) are NOT supported. DO NOT upgrade to 6.x if your deployments contain a mix of MIPS and PPC controllers in a master-local setup. In this case, any PPC controllers will need to be replaced / consolidated before upgrading to 6.2.x.

The 3200 controller originally shipped with 512MB memory where current 3200XM units ship with 1GB memory. The original 3200s with 512MB memory must have their memory upgraded to 1GB using an upgrade kit from Aruba Networks (3200-MEM-UG) prior to upgrading to AOS 6.2.

For proper operation, all controllers in the network must be upgraded with the same version of ArubaOS. For redundant (VRRP) environments, the controllers should be the same model for matching capacities.



Upgrading From an Older version of ArubaOS to AOS 6.2

As ArubaOS has evolved over recent years, there have been several changes made to the configuration format and the flash partition size (to name a few). For this reason, it *may not* be possible to upgrade a controller directly from an older ArubaOS version to the most current release. To upgrade to the latest ArubaOS version, the controller may have to be upgraded to an *interim* version first before upgrading to AOS 6.2.

Before you begin, verify the version of ArubaOS currently running on your controller. If you are running AOS 6.0.1.x or later you can upgrade directly to AOS 6.2 For versions prior to AOS 6.0.1.x refer to the Release Notes. An intermediate upgrade may be required.

To upgrade an existing multi-controller system to ArubaOS 6.2:

- Load the software image onto all controllers (including redundant master controllers).
- If all the controllers cannot be upgraded with the same software image and reloaded simultaneously, use the following guidelines:
 - 1. Remove the link between the master and local mobility controllers.
 - 2. Upgrade the software image, and then reload the master and local controllers one by one.
 - 3. Verify that the master and all local controllers are upgraded properly.
 - 4. Connect the link between the master and local controllers.
 - 5. Verify successful AP connectivity and expected AP count.

When upgrading the software in a multi-controller network (one that uses two or more Aruba controllers), special care must be taken to upgrade all the controllers in the network and to upgrade them in the proper sequence, as mentioned in the overview and detailed in the following Migration sections

Caveats

Before upgrading to any version of ArubaOS 6.2, take note of these known upgrade caveats.

- Control plane security is disabled when you upgrade from 3.4.x to 6.0.1 (control plane security is disabled in 6.0.1) and then to 6.2.
- If you want to downgrade to a prior version, and your current ArubaOS 6.2 configuration has control plane security enabled, disable control plane security before you downgrade.
- For more information on configuring control plane security and auto-certificate provisioning, refer to the ArubaOS 6.2 User Guide.



Lab 1: 7200 Migration - Local Controller Replacement



Classroom Equipment (remote access)

- a. 3600 running as Master and another 3600 running as Local running AOS 6.2. Only the Local will be modified.
- b. 7210 controller running AOS 6.2 to replace the 3600 Local.
- c. Connect to the "Guest-Demo" SSID. Launch a web browser to get to the Captive Portal page for guest access. Register and put your instructors e-mail for the Sponsor. After registering, wait for the instructor to approve the request before continuing.

Lab 1 Objectives

- In this exercise remote equipment located in Aruba Networks SE Enablement Lab, located in our Sunnyvale HQ, will be utilized. There are 5 identically configured pods for student use. Please refer to the topology and IP information located in the Appendix. The instructor will assign Pod numbers prior to beginning the exercise.
- This lab will replace the 3600 Local with a 7200.

Lab 1 Summarized steps:

- 1. Take a *flash backups* from existing controllers BEFORE upgrading (for safety)
- 2. Upgrade existing controllers to 6.2.x (MIPS controllers only)
- 3. Take a *flash backup* from the controller to be replaced; copy to PC and/or USB drive
- 4. Stage/rack/install new 7200 controller
- 5. Install transferred/new licenses on 7200
- 6. Backup newly installed licenses on 7200
- 7. Copy/restore flash backup on new 7200
 - Confirm data restored
- 8. Restore license backup on 7200
- 9. Update port/VLAN/IP config on 7200
- 10. Fallback/failsafe is to reconnect the old controller



Lab 1: Detailed Steps

- 1. Make sure all existing controllers have been upgraded to 6.2.x.
 - a. Connect to the console on all three controllers in your Pod per the IP / Console document in the Appendix.
 - b. Use the command "show version" to view the running version of AOS.
- 2. Back-up flash from the existing 3600 Local controller using the CLI command "backup flash".

a. TFTP the file flashbackup.tar.gz to <u>your TFTP server</u> on your PC.

```
(3600_local_P1) #backup flash
Please wait while we tar relevant files from flash...
Please wait while we compress the tar file...
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the switch and delete it when done.
(3600_local_P1) #dir
-rw-r--r-- 1 root root 17338 Dec 6 08:34 default.cfg
drwxr-xr-x 4 root root 1024 Dec 6 08:34 fieldCerts
-rw-r--r-- 1 root root 21760 Dec 6 09:29 flashbackup.tar.gz
-rw-r--r-- 1 root root 1796 Dec 6 06:23 licenses_3600P1_2
drwx----- 2 root root 1024 Dec 5 08:20 tpm
(3600_local_P1) #
(3600_local_P1) #
(3600_local_P1) #copy flash: flashbackup.tar.gz tftp:<TFTP Server IP>flashbackup.tar.gz
```

3. Stage the new 7200 for your individual pod. Connect to your assigned pod via the console and set the IP address for Vlan 1 per the IP guide in the appendix. The instructor will have reset the 7200 to factory default for you. Run through the Default Startup Script.

```
Enter System name [Aruba7210]:
Enter Switch Role (master | local | standalone) [master]:
Enter VLAN 1 interface IP address [172.16.0.254]: 10.79.51.10
Enter VLAN 1 interface subnet mask [255.255.255.0]:
Enter IP Default gateway [none]: 10.79.51.1
Enter Country code (ISO-3166), <ctrl-I> for supported list: US
You have chosen Country code US for United States (yes|no) ?: yes
Enter Time Zone [PST-8:0]:
Enter Time in UTC [10:53:30]: 02:57:45
Enter Date (MM/DD/YYYY) [12/2/2012]: 12/1/2012
Enter Password for admin login (up to 32 chars): ******
Re-type Password for admin login: ******
Enter Password for enable mode (up to 15 chars): ******
Re-type Password for enable mode: ******
Do you wish to shutdown all the ports (yes|no)? [no]:
If you accept the changes the switch will restart!
Type <ctrl-P> to go back and change answer for any question
Do you wish to accept the changes (yes|no)yes
Creating configuration... Done.
System will now restart!
```



4. Add licenses to the 7200 using the CLI command "license add". Licenses are located in the License section of the appendix. This step will save you one reboot later.

```
(Aruba7210) #
(Aruba7210) #license add < license # >
```

5. Backup newly installed licenses on the 7200 using the CLI command "license export"

```
(Aruba7210) #
(Aruba7210) #license export < file name >
```

Restore the Flash Backup from the 3600 Local to the new 7200 using TFTP on the CLI.

```
(Aruba7210) #copy tftp: <your TFTP server IP> flashbackup.tar.gz flash: flashbackup.tar.gz
(Aruba7210) #
```

```
(Aruba7210) #restore flash
Please wait while we uncompress /flash/config/flashbackup.tar.gz...
Please wait while we untar /flash/config/flashbackup.tar.gz...
Flash restored successfully.
Please reload (reboot) the switch for the new files to take effect.
(Aruba7210) #
```



The controller may prompt to reboot for the changes to take effect, but...DO NOT SAVE / write mem, or REBOOT YET!

7. Restore Licenses & REBOOT. The 3600 licenses were included as part of the flash backup and are specific to the 3600. A reload of the 7200 licenses is now required using the CLI command "license import". This is the file created in step 5.

```
(Aruba7210) #
(Aruba7210) #license import < file name >
Successfully imported 4 licenses to the license database from license_backup.db; please reload to make licenses take effect
```

Reboot the 7200 using the CLI command "reload".



DO NOT SAVE! This will cause the factory default config to be saved to flash rather than the restored config.

(Aruba7210) #reload Do you want to save the configuration (y/n): n Do you really want to restart the system(y/n): y System will now restart!



9. Verify Flash Restore. As the 7200 reboots, connect to the serial console. Verify that the *same Vlans, IP interfaces, hostname, etc.*, as the 3600 local controller being replaced. The VLANs and IP interfaces from the 3600 Local should have been restored.

(3600_local_P1) #show vlan									
VLAN CONFIGURATION									
VLAN Description 1 Default 10 VLAN0010 172 VLAN0172 192 VLAN0192 VLAN0192 AAA Profile Pc1-7 R/A N/A N/A N/A									
(3600_local_P1) #show ip interface brief									
Interface IP Address / IP Netmask vlan 10 10.79.51.100 / 255.255.255.0 vlan 1 unassigned / unassigned vlan 172 172.16.0.254 / 255.255.0 vlan 192 192.168.0.254 / 255.255.0 loopback unassigned / unassigned mgmt unassigned / unassigned	Admin up up up up down	Protocol up down up up up down							
(3600_local_P1) #show interface port-channel 0									
Port-Channel 0 is administratively up Hardware is Port-Channel, address is 00:0B:86:6E:4D:44 (bi Description: Link Aggregate Spanning Tree is disabled Switchport priority: 0 Fember port: GE 1/2, Admin is up, line protocol is down GE 1/3. Admin is up. line protocol is down	a 00:0B:	:86:6E:4D:44)							

3600 Local Vlan and port assignment – before move

(3600	_standby_P1)	#show vlan				
VLAN	CONFIGURATION	N				
VLAN	Description	Ports	AAA Pr	ofile		
1	Default	GE0/0/0-0/1 GE0/0/2-0/5 Pc1-7	N/A			
172 192	VLAN0172 VLAN0192	PCO	N/A N/A N/A			
(3600	_standby_P1)	#show ip interface br				
Inter vlan vlan vlan vlan loopb	face 10 1 172 192 Jack	IP Address / IP Netm 10.79.51.12 / 255.255 unassigned / unassig 172.16.0.254 / 255.255 192.168.0.254 / 255.255 unassigned / unassign	ask 255.0 ned 255.0 255.0 ned	Admin up up up up up up	Protocol up up down down up	
(3600	_standby_P1)	#show interface port-channel 0				
Port- Hardw Descr Spanr Switc Membe	Channel 0 is ware is Port-(iption: Link ing Tree is (boort priorit r port:	administratively up Channel, address is 00:1A:1E:00 Aggregate disabled ty: 0	:11:F8 (b	ia 00:1A:	1E:00:11:F8)	

7200 after Flash Restore. Note port changes



10. Modify Interface Settings & Hostname .The 7200 Series controllers use a different port numbering scheme than other Aruba controllers. Ports on the 7200 Series are numbered *slot/module/port*. Older controller ports are numbered *slot/port*. As a result the *flash backups* restored from older controllers to a 7200 will cause a loss of network connectivity since the ports don't match and all ports on the 7200 wind up assigned to the default Vlan (Vlan 1). Additionally, all ports will become untrusted. You must connect to your new controller using a serial connection to reconfigure port settings.

The 7200 now needs to have its VLANs and interfaces modified to match the new 7200 port scheme. This will need to done with the new 7200 "out of band" and disconnected from the management network to avoid IP address conflicts.

a. Change the hostname from 3600_Local_P1 to 7200_Local_P1.

```
(3600 local P1) #
(3600_local_P1) #configure terminal
Enter Configuration commands, one per line. End with CNTL/Z
(3600_local_P1) (config) #hostname 7210_local_P1
(7210_local_P1) (config) #
(7210_local_P1) (config) #
```

- b. Disable the ports on the 7200 to prevent an IP conflict with the current 3600 in the lab. Use the command "interface gigabitethernet 0/0/0 shutdown"
- c. Adjust the port configuration and port-trust on the 7200 accordingly then write mem. The ports do not transfer properly due to the different port config in the 7200. Note: Port-trust status can be viewed with the command "show port status".

```
(7210_standby_P1) #configure t
Enter Configuration commands, one per line. End with CNTL/Z
(7210_standby_P1) (config) #interface range gigabitethernet 0/0/0-0/1
(7210_standby_P1) (config-range) # switchport access vlan 10
(7210_standby_P1) (config-range) #trusted
(7210_standby_P1) (config-range) #show vlan
VLAN CONFIGURATION
VLAN Description Ports
                                                         AAA Profile
____
                           GE0/0/2-0/5 Pc1-7
                                                         N/A
        Default
1
10
        VLAN0010 GE0/0/0-0/1
                                                         N/A
172
        VLAN0172
                           Pc0
                                                         N/A
192
        VLAN0192
                                                         N/A
```



d. Correct the Port-Channel / LAG group ports and port-trust. The ports do not transfer properly due to the different port config in the 7200. Note: Port-trust status can be viewed with the command "show port status".

```
(7210_standby_P1) (config-range) #interface port-channel 0
(7210_standby_P1) (config-channel)#add gigabitethernet 0/0/2
(7210_standby_P1) (config-channel)#dd gigabitethernet 0/0/3
(7210_standby_P1) (config-channel)#trusted
(7210_standby_P1) (config) channel)#exit
(7210_standby_P1) (config) #show interface port-channel 0
Port-Channel 0 is administratively up
Hardware is Port-Channel, address is 00:1A:1E:00:11:F8 (bia 00:1A:1E:00:11:F8)
Description: Link Aggregate
Spanning Tree is disabled
Switchport priority: 0
Member port:
    GE 0/0/2, Admin is up, line protocol is down
    GE 0/0/3, Admin is up, line protocol is down
    Ort-Channel 0 is TRUSTED
(7210_standby_P1) (config) #
```

11. The new 7200 controller should now be ready for the physical switchover.

Disconnect the existing local. Connect the new 7200 local.

- a. On the 3600 Local use the command "interface gigabitethernet 1/0 shutdown"
- b. On the 7200 enable the ports "interface gigabitethernet 0/0/0 no shutdown"



12. After the new 7200 local has been up a few minutes, check to confirm the master has synced its WLAN config and data. Check to see if the AP groups have been pushed from the master.

MOBILITY CONTROLLER Aruba7200											
Dashboard Monitoring	Configuration	Diagnostics	Maintenance	Master Switch							
WIZARDS AP	Configuration >	AP Group									
Controller	AP Group AP	Specific									
NETWORK Controller VLANs	Back9_APG	Delete									
Ports Cellular Profile	NoAuthApGroup	Delete									
IP SECURITY Authentication	New										
Access Control											
WIRELESS > AP Configuration AP Installation											
Configuration> Wireless>	AP Configuration			Ð							

The 3600 Master controller should also now show the 7200 as a local.

ARURA MOBI	LITY CONTROL	LER 3600_m	aster_P1						
Dashboard Monitoring	Configuration	Diagnostics M	aintenance P	lan					Log out admin
NETWORK	Network >	All WLAN Contro	ollers						
Network Summary	Network Co	ontrollers							
> All WLAN Controllers	IP Address	Name	Location	Туре	Model	Version	Status	Configuration State	Config Sync Ti
All Access Points	10.79.51.99	3600_master_P1	Building1.floor	1 master	Aruba3600	6.2.0.0_36322	up	UPDATE SUCCESSFUL	0
All Mesh Nodes	10.79.51.100	7210_local_P1	Building1.floor	1 local	Aruba7210	6.2.0.0_36322	up	UPDATE SUCCESSFUL	7
All Air Monitors						1			
All Wired Access Points									
All Routers									



This page intentionally left blank



Lab 2: 7200 Migration - Redundant Master Controller Replacement

7200 as Master controller

This exercise demonstrates migration of an existing Backup Master controller to a 7200 controller.



Classroom Equipment (remote access)

- a. 3600 running as Master and another 3600 running as Backup Master running AOS6.2. Only the Backup Master will be modified.
- b. 7210 controller running AOS 6.2 to replace the 3600 Backup Master.

Lab 2 Objectives

- In this exercise remote equipment located in Aruba Networks SE Enablement Lab, located in our Sunnyvale HQ, will be utilized. There are 5 identically configured pods for student use. Please refer to the topology and IP information located in the Appendix. The instructor will assign Pod numbers prior to beginning the exercise.
- This lab will replace a 3600 Backup Master with a 7200.



Lab 2 Summarized Steps

Replace Backup-Master

- 1. Take a *flash backups* from existing controllers BEFORE upgrading (for safety)
- 2. Upgrade existing controllers to 6.2.x (*MIPS controllers only*)
- 3. Take a *flash backup* from the controller to be replaced; copy to PC and/or USB drive
- 4. Stage/rack/install new 7200 controller
- 5. Install transferred/new licenses on 7200
- 6. Backup newly installed licenses on 7200
- 7. Copy/restore flash backup on new 7200
 - o Confirm data restored
- 8. Restore license backup on 7200
- 9. Update port/VLAN/IP config on 7200
- 10. Fallback/failsafe is to reconnect the old controller

Lab 2 Detailed Steps

- 1. Make sure all existing controllers have been upgraded to 6.2.x.
 - a. Connect to the console on all three controllers in your Pod per the IP / Console document in the Appendix.
 - b. Use the command "show version" to view the running version of AOS.
- 2. Back-up flash from the existing 3600 Backup Master controller using the CLI command "backup flash".
 - a. TFTP the file flashbackup.tar.gz to your TFTP server on your PC.

```
(3600_standby_P2) #backup flash
Please wait while we tar relevant files from flash...
Please wait while we compress the tar file...
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the switch and delete it when done.
(3600_standby_P2) #dir
-rw-r--r-- 1 root
drwxr-xr-x 4 root
                                         17338 Dec 6 08:34 default.cfg
                           root
                           root
                                           1024 Dec 6 08:34 fieldCerts
-rw-r--r--
               1 root
                            root
                                          21760 Dec 6 09:29 flashbackup.tar.gz
               2 root
                           root
                                          1024 Dec 5 08:20 tpm
drwx-----
(3600_standby_P2) #
(3600_standby_P2) #copy flash: flashbackup.tar.gz tftp: <your TFTP server IP> flashbackup.tar.gz
```



3. Stage the new 7200 for your individual pod. Connect to your assigned pod via the console and set the IP address for Vlan 1 per the IP guide in the appendix. Run through the Default setup script.



4. Add licenses to the 7200 using the CLI command "license add". Licenses are located in the License section of the appendix. This will save you a reboot later.

```
(Aruba7210) #
(Aruba7210) #license add < license # >
Please reload the switch for the new service key to take effect.
```

5. Backup newly installed licenses on the 7200 using the CLI command "license export".

```
(Aruba7210) #
(Aruba7210) #license export < filename >
Successfully exported 4 licenses from the license database to license backup.db
```

6. Copy/Restore Flash Backup from the 3600 Backup Master to the new 7200 using TFTP on the CLI.

```
(Aruba7210) \sharp copy tftp: <your TFTP server IP> flashbackup.tar.gz flash: flashbackup.tar.gz (Aruba7210) <math display="inline">\ddagger
```

```
(Aruba7210) #restore flash
Please wait while we uncompress /flash/config/flashbackup.tar.gz...
Please wait while we untar /flash/config/flashbackup.tar.gz...
Flash restored successfully.
Please reload (reboot) the switch for the new files to take effect.
```

(Aruba7210) #



The controller may prompt to reboot for the changes to take effect, but...DO NOT SAVE / write mem, or REBOOT YET!



7. Restore Licenses & REBOOT. The 3600 licenses were included as part of the flash backup and are specific to the 3600. A reload of the 7200 licenses is now required using the CLI command "license import". The file name is the name given in step 5.

```
(Aruba7210) #
(Aruba7210) #
(Aruba7210) #license import < filename >
Successfully imported 4 licenses to the license database from license backup.db; please reload to make licenses take effect
```

8. Reboot the 7200 using the CLI command "reload".

DO NOT SAVE! This will cause the factory default config to be saved to flash rather than the restored config.

(Aruba7210) #reload Do you want to save the configuration(y/n): n Do you really want to restart the system(y/n): y System will now restart!

- 9. Disable the 3600 Backup Master's connection to the network using the command "interface gigabitethernet 1/0 shutdown" to prevent an IP conflict with the newly restored 7200.
- 10. Verify Flash Restore. As the 7200 reboots, connect to the serial console and verify that the *same Vlans, IP interfaces, hostname, etc.*, were copied from the 3600 Backup Master controller being replaced.



3600 Local Vlan and port assignment - before move



(2600 stap	dby p1) (c	ontia) #chow	vlan										
(3000_Standby_PI) (coning) #Snow vian													
VLAN CONFIGURATION													
VLAN Desc	/LAN Description Ports AAA Profile												
1 Defa 10 VLAN 172 VLAN 192 VLAN	L Default GE0/0/0-0/1 GE0/0/2-0/5 Pc1-7 N/A L0 VLAN0010 L72 VLAN0172 Pc0 N/A L92 VLAN0192												
(3600_standby_P1) (config) #show ip interface br													
Interface vlan 10 vlan 1 vlan 172 vlan 192 loopback		IP A 10.79 unas 172.16 192.168 unas	ddress / IP .51.12 / 25 signed / un .0.254 / 25 .0.254 / 25 signed / un	Netmask 5.255.255 assigned 5.255.255 5.255.255 assigned	. 0 . 0	Admin up up up up up	Protocol up up up up up						
(3600_standby_P1) (config) #show interface port-channel 0													
Port-Chann Hardware i Descriptio Spanning T Switchport Member por Port-chann (3600 stap	Port-Channel 0 is administratively up Hardware is Port-Channel, address is 00:1A:1E:00:11:F8 (bia 00:1A:1E:00:11:F8) Description: Link Aggregate Spanning Tree is disabled Switchport priority: 0 Member port: Port-Channel 0 is TROSTED												
(3600_standby_P1) (contig) #show port status													
Port Statu	-												
Slot-Port	PortType	adminstate	operstate	poe	Truste	ed Span	ningTree	PortMode					
0/0/0 0/0/1 0/0/2 0/0/3 0/0/4 0/0/5	GE GE GE GE GE GE	Enabled Enabled Enabled Enabled Enabled Enabled	Up Down Down Down Down Down	Enablec Enablec Enablec Enablec Enablec Enablec	NO NO NO NO NO	Disa Disa Disa Disa Disa Disa	bled bled bled bled bled bled bled	Access Access Access Access Access Access					

7200 after Flash Restore. Note port changes

The following example shows campus AP whitelist entries restored from the previous controller with Control Plane Security (CPSec) enabled.

(3600_standby_P2)	#show whi	telist-db cpsec				
Control-Plane Secu	urity Whit	elist-entry Details				
MAC-Address	Enable	State	Cert-Type	Description	Revoke Text	Last Updated
00:24:6c:c9:30:84 d8:c7:c8:c9:99:0d 00:24:6c:c3:3c:50 00:24:6c:c9:30:80 d8:c7:c8:c9:82:13 d8:c7:c8:c2:14:9b d8:c7:c8:c0:fc:d8	Enabled Enabled Enabled Enabled Enabled Enabled	certified-factory-cert certified-factory-cert certified-factory-cert certified-factory-cert certified-factory-cert certified-factory-cert certified-factory-cert	factory-cert factory-cert factory-cert factory-cert factory-cert factory-cert factory-cert			Fri Nov 30 09:09:06 2012 Fri Nov 30 09:09:05 2012 Fri Nov 30 09:09:05 2012 Fri Nov 30 09:09:05 2012 Fri Nov 30 09:09:05 2012 Fri Nov 30 09:09:02 2012 Fri Nov 30 09:09:20 2012
d8:c7:c8:cb:37:b6 d8:c7:c8:cb:36:de	Enabled Enabled	certified-factory-cert certified-factory-cert	factory-cert factory-cert			Fri Nov 30 09:56:48 2012 Fri Nov 30 09:56:32 2012



 Verify AP database restore. Although no APs have ever connected to this controller, the AP database for the existing redundant cluster has been restored on the new 7200

(3600_standby_P2) #show ap database											
AP Database											
Name	Group	AP Type	IP Address	Status	Flags	Switch IP					
00:24:6c:c3:3c:50 Back9 APG 105 10.79.252.3 Down 2 10.79.100.113 00:24:6c:c9:30:80 Back9 APG 105 10.79.252.1 Down 2 10.79.100.113 00:24:6c:c9:30:84 Back9 APG 105 10.79.252.5 Down 2 10.79.100.113 00:24:6c:c9:30:84 Back9 APG 105 10.79.252.5 Down 2 10.79.100.113 d8:c7:c8:c0:fc:d8 Back9 APG 135 10.79.252.6 Down 2 10.79.100.113 d8:c7:c8:c2:14:9b Back9 APG 105 10.79.252.2 Down 2 10.79.100.113 d8:c7:c8:c9:99:0d Back9 APG 105 10.79.252.2 Down 2 10.79.100.113 d8:c7:c8:c9:99:0d Back9 APG 105 10.79.252.4 Down 2 10.79.100.113 d8:c7:c8:cb:36:de Back9 APG 135 10.79.252.9 Down 2 10.79.100.113 d8:c7:c8:cb:36:de Back9 APG 135 10.79.252.9 Down 2 10.79.100.113 d8:c7:c8:cb:37:b6 Back9 APG 135 10.79.252.8 Down 2											
<pre>Flags: U = Unprovisioned; N = Duplicate name; G = No such group; L = Unlicensed I = Inactive; D = Dirty or no config; E = Regulatory Domain Mismatch X = Maintenance Mode; P = PPPoE AP; B = Built-in AP R = Remote AP; R- = Remote AP requires Auth; C = Cellular RAP; c = CERT-based RAP; 1 = 802.1x authenticated AP; 2 = Using IKE version 2 u = Custom-Cert RAP M = Mesh node; Y = Mesh Recovery</pre>											

12. Modify Interface Settings & Hostname. The 7200 Series controllers use a different port numbering scheme than other Aruba controllers. Ports on the 7200 Series are numbered *slot/module/port*. Older controller ports are numbered *slot/port*. As a result the *flash backups* restored from older controllers to a 7200 controller will cause a loss of network connectivity since the ports don't match up. All ports on the 7200 will wind up assigned to the default Vlan (Vlan 1). Additionally, all ports will become untrusted. You must connect to your new controller using a serial connection to reconfigure port settings.

The 7200 now needs to have its VLANs and interfaces modified to match the new 7200 port scheme. This will need to done with the new 7200 "out of band" and disconnected from the management network to avoid IP address conflicts.

a. Change the hostname from 3600_standby_px to 7200_standby_<pod#>.

```
(3600_standby_P2) #
(3600_standby_P2) #configure terminal
Enter Configuration commands, one per line. End with CNTL/Z
(3600_standby_P2) (config) #hostname 7210_standby_P2
(7210_standby_P2) (config) #
(7210_standby_P2) (config) #
```

b. Disable the ports on the 7200 to prevent an IP conflict with the current 3600 in the lab. Use the command "interface gigabitethernet 0/0/0 shutdown"



c. Adjust the port configuration and port-trust on the 7200 accordingly then write mem. The ports do not transfer properly due to the different port config in the 7200. Note: Port-trust status can be viewed with the command "show port status".

```
(7210_standby_P1) #configure t
Enter Configuration commands, one per line. End with CNTL/Z
(7210_standby_P1) (config) #interface range gigabitethernet 0/0/0-0/1
(7210_standby_P1) (config-range) # switchport access vlan 10
(7210_standby_P1) (config-range) #trusted
(7210_standby_P1) (config-range) #show vlan
VLAN CONFIGURATION
VLAN Description Ports
                                                                AAA Profile
____
         Default GE0/0/2-0/5 Pc1-7
VLAN0010 GE0/0/0-0/1
VLAN0172 Pc0
1
                                                                N/A
10
                                                                N/A
172
                                                                N/A
192
         VLAN0192
                                                                N/A
```

d. Correct the Port-Channel / LAG group ports and port-trust. The ports do not transfer properly due to the different port config in the 7200. Note: Port-trust status can be viewed with the command "show port status".

(7210_standby_P1) (config-range) #interface port-channel 0 (7210_standby_P1) (config-channel)#add gigabitethernet 0/0/2 (7210_standby_P1) (config-channel)#add gigabitethernet 0/0/3 (7210_standby_P1) (config-channel)#trusted (7210_standby_P1) (config-channel)#exit
(7210_standby_P1) (config) #show interface port-channel 0
Port-Channel 0 is administratively up Hardware is Port-Channel, address is 00:1A:1E:00:11:F8 (bia 00:1A:1E:00:11:F8) Description: Link Aggregate Spanning Tree is disabled Switchport priority: 0 Member port: GE 0/0/2, Admin is up, line protocol is down GE 0/0/3, Admin is up, line protocol is down Port-Channel 0 is TRUSTED
(7210_standby_P1) (config) #

11. The new 7200 controller should now be ready for the physical switchover.

Disconnect the existing local. Connect the new 7200 local.

- a. On the 3600 Local use the command "interface gigabitethernet 1/0 shutdown"
- b. On the 7200 enable the ports "interface gigabitethernet 0/0/0 no shutdown"



12. The virtual router configuration from the existing backup master should have been added to the 7200 with the flash restore...

```
(7210_standby_P2) (config) #show vrrp
Virtual Router 10:
    Description backup-master
    Admin State UP, VR State MASTER
    IP Address 10.79.100.251, MAC Address 00:00:5e:00:01:0a, vlan 1
    Priority 100, Advertisement 1 sec, Preemption Disable Delay 0
    Auth type PASSWORD, Auth data: *******
    tracking is not enabled
```

The 7200 should now have the *Standby* controller role.

Dashboard Monitoring Configuration Diagnostics Maintenance Master Switch Save Configuration Log out admit WIZARDS AP Controller Network > Controller > System Settings System Settings Controller System Settings Controller Not Standby (To change Controller role, please remove Master Controller redundancy configuration) Network > Controller role, please remove Master Controller redundancy configuration NETWORK Controller Role Standby (To change Controller role, please remove Master Controller redundancy configuration) Network > Controller role, please remove Master Controller redundancy configuration VLANs IPSec Key (IKE PSK) n/a Retype IPSec Key (IKE PSK) n/a Ports Retype IPSec Key (IKE PSK) n/a FQDN (optional) n/a		NO8	BILITY CONTROLL	ER 721	0_standby_P2			
WIZARDS Network > Controller > System Settings AP System Settings Control Plane Security Licenses Controller System Settings Controller cole Standby (To change Controller role, please remove Master Controller redundancy configuration NETWORK Controller Role Standby (To change Controller role, please remove Master Controller redundancy configuration VLANs IPSec Key (IKE PSK) n/a Ports Retype IPSec Key (IKE PSK) n/a Collider Brofile FQDN (optional) n/a	Dashboard	Monitoring	Configuration	Diagnostics	Maintenance	Master Switch	Save Configuration	Log out admin
AP System Settings Control Plane Security Licenses NETWORK Controller Role Standby (To change Controller role, please remove Master Controller redundancy configuration > Controller Master IP Address 10.79.52.100 VLANs IPSec Key (IKE PSK) n/a Ports Retype IPSec Key (IKE PSK) n/a Calida Brofile FQDN (optional) n/a	WIZARDS		Network > Control	ler > Syste	m Settings			
NETWORK Controller Role Standby (To change Controller role, please remove Master Controller redundancy configuration > Controller Master IP Address 10.79.52.100 VLANs IPSec Key (IKE PSK) n/a Ports Retype IPSec Key (IKE PSK) n/a Calluda Brofile FQDN (optional) n/a	AP Controller		System Settings	Control	Plane Security	Licenses		
Cellular Profile	NETWORK Controller VLANs Ports Cellular Pro	file	Controller Role Master IP Address IPSec Key (IKE P Retype IPSec Key FQDN (optional)	s SK) (IKE PSK)	Stan 10.79 n/a n/a	dby (To change C 9.52.100	iontroller role, please remove l	Master Controller redundancy configuration.)

15. Verify Successful Database Sync. Another view from the current *Active-Master* controller showing the 7200 as the *backup-master*. Note the status for the 7200 in the *Configuration State* column. If *UPDATE SUCCESSFUL* is listed there, then the controller sync is working.

ARUBA MOBILITY CONTROLLER | 3600_active_P2 networks Dashboard Monitoring Configuration Diagnostics Maintenance Plan Log out Network > All WLAN Controllers NETWORK Network Summary **Network Controllers** > All WLAN Controllers IP Address Name Location Type Model Version Status Configuration State Config All Access Points 10.79.52.11 3600_active_P2 Building1.floor1 master Aruba3600 6.2.0.0_36322 up UPDATE SUCCESSFUL 0 10.79.52.12 7210_standby_P2 Building1.floor1 standby Aruba7210 6.2.0.0_36322 up UPDATE SUCCESSFUL 17 All Mesh Nodes All Air Monitors All Wired Access Points All Routers 60 Controller Sync is GOOD!

Monitoring --> Network --> ALL WLAN Controllers



Replace *Active-master*

Now that the 7200 is up and running as the Backup Master the Active Master VRRP Priority can be changed to a lower priority than that configured on the Backup Master to trigger a failover.

Once failed over follow the same steps as moving the Master Backup.....



This page intentionally left blank



Appendix



This page intentionally left blank





Lab Topology



Lab IP addresses and Terminal Server Ports

Terminal Serv	er: 10.79.10.12	! <port#></port#>	Controller pwd.	user:	admin	pwd:	admin1	
TFTP Server:	10.79.254.1	0						
-								
	Flash Backup			Telnet		Flash Backup	MASTER/MASTER	
Controller	File	MASTER/LOCAL	Stack/Slot/Port	Port	VLAN ID	File	Redundant	
			Pod 1 : 10.79.5	51.0/24	Def. GW 10.79	.51.1		
7200	(recet only)	10 70 51 10		7001	1 (all parts)	(recet only)	10 70 51 10	
7200	(reset only)	10.79.51.10	GE 0/0/0	7001		(reset only)	10.79.51.10	
3600 Master	masterP1bak	10.79.51.99 (master)	GE 1/0	7002	10	activeP1bak	10.79.51.11 (active)	
		172 46 0 4	GE 1/2-3 (Pc0)		4 10		172 46 0 4	
		172.16.0.1			172		172.16.0.1	
		192.168.0.1	N/A		192		192.168.0.1	
3600 Local /	localP1bak	10.79.51.100 (local)	GE 1/0-1	7003	10	backupP1bak	10.79.51.12 (backup)	10.79.51.100 (VIP)
Iviaster Backup		172 16 0 254	GF 1/2-3 (Pc0)		172		172 16 0 254	
		192.168.0.254	N/A		192		192.168.0.254	
			,					
			Pod 2 : 10.79.	2.0 /24 [Def. GW 10.79	.52.1		
7200	(reset only)	10.79.52.10	GE 0/0/0	7004	1 (all ports)	(reset only)	10.79.52.10	
3600 Master	masterP2bak	10.79.52.99 (master)	GE 1/0	7005	10	activeP2bak	10.79.52.11 (active)	
		172.16.0.1	GE 1/2-3 (Pc0)		172		172.16.0.1	
		192.168.0.1	N/A		192		192.168.0.1	
3600 Local /	localP2bak	10 79 52 100 (local)	GE 1/0-1	7006	10	backupP2bak	10 79 52 12 (backup)	10 79 52 100 (V/IP)
Master Backup	IOCAIF 2 Dak	10.79.32.100 (local)	GL 1/0-1	7000	10	backupr 2bak	10.79.52.12 (backup)	10.79.52.100 (VIP)
		172.16.0.254	GE 1/2-3 (Pc0)		172		172.16.0.254	
		192.168.0.254	N/A		192		192.168.0.254	
	1	1	Pod 3 : 10.79.5	53.0 /24	Def. GW 10.79	.53.1		
7200	(reset only)	10.79.53.10	GE 0/0/0	7007	1 (all ports)	(reset only)	10.79.53.10	
3600 Master	masterP3bak	10.79.53.99 (master)	GE 1/0	7008	10	activeP3bak	10.79.53.11 (active)	
		172.16.0.1	GE 1/2-3 (Pc0)		172		172.16.0.1	
3600 Local /		192.168.0.1	N/A		192		192.168.0.1	
Master Backup	localP3bak	10.79.53.100 (local)	GE 1/0-1	7009	10	backupP3bak	10.79.53.12 (backup)	10.79.53.100 (VIP)
		172.16.0.254	GE 1/2-3 (Pc0)		172		172.16.0.254	
		192.168.0.254	N/A		192		192.168.0.254	
			Pod 4 : 10.79.5	54.0 /24	Def. GW 10.79	.54.1		
7200	(reset only)	10.79.54.10	GE 0/0/0	7010	1 (all ports)	(reset only)	10.79.54.10	
3600 Master	masterP4bak	10.79.54.99 (master)	GE 1/0	7011	10	activeP4bak	10.79.54.11 (active)	
		1/2.16.0.1	GE 1/2-3 (PCU)		1/2		172.16.0.1	
3600 Local /		192.168.0.1	N/A		192		192.108.0.1	
Master Backup	localP4bak	10.79.54.100 (local)	GE 1/0-1	7012	10	backupP4bak	10.79.54.12 (backup)	10.79.54.100 (VIP)
		172.16.0.254	GE 1/2-3 (Pc0)		172		172.16.0.254	
		192.168.0.254	N/A		192		192.168.0.254	
					-			
	1		Pod 5 : 10.79.5	5.0 /24	Def. GW 10.79	.55.1		
7200	(reset only)	10.79.55.10	GE 0/0/0	7013	1 (all ports)	(reset only)	10.79.55.10	
3600 Master	masterP5bak	10.79.55.99 (master)	GE 1/0	7014	10	activeP5bak	10.79.55.11 (active)	
		172 16 0 1	GE 1/2-3 (Pc0)		172		172 16 0 1	
		192,168,0,1	N/A		192		192,168,0,1	
3600 Local /	local DE bals	10 70 FE 100 (local)	GE 1 /0.1	7015	10	backupBEbale	10 70 EE 12 (backur)	
Master Backup	IUCaiPSDak	10.79.55.100 (local)	GE 1/0-1	7015	10	раскирезрак	10.79.55.12 (backup)	10.79.55.100 (VIP)
			a = 1 /a = 1 =					
		172.16.0.254	GE1/2-3(Pc0)		172		172.16.0.254	
		172.16.0.254 192.168.0.254	GE1/2-3(Pc0) N/A		172 192		172.16.0.254 192.168.0.254	



Controller Licenses

Controller	Serial #	Keys	Service Type	License File			
Pod 1							
7200	BA0001097	7pWLyZ3J-HAfPQR9c-5C7GdiMQ-LJIKdDMn-lpgUckfU-9EM	PEFV	Lic P1 7200			
			RFProtect:				
		eAEKKWXZ-MepaleWH-3GPKnZ8N-QHUN8mKg-JF5ZNOJU-MqQ	Access				
		3WOvBWrQ-HmmrANqp-8m4SbLYJ-XFGuGAJd-dCleoSov-vcA	Points: 512				
3600-1	AK0023686	Js8pZkpM-79kxD0G+-Uu4Usp6z-GTNw7OTH-hC+a/wf6-UsY	PEFV	lic_P1_3600-1			
		dzkgvE6I-HgJSwGCS-a02/oGdi-P3xKAU60-LK4xzP/3-t4Q	RFProtect: 512				
		aU61yMx/-WNioPn/a-mcgtzhgK-Y0u2kk4i-5slWdu1H-Ces	PEFNG: 512				
		fYSeADuN-Rwn1FIiv-fW6Wv7RM-FzmfY0zM-r7uDW5Bm-oMs	Access Points: 512				
			REProtect:				
3600-2	AK0024015	Ijdj3mfb-cH11SwmI-O4ZZIpqt-sBuN51hO-rWLc8+By-R0c	512	lic_P1_3600-2			
		uLboMsmG-r48VReDr-PD7n3FJq-d9WNbAI4-MJ/jrTVZ-oYU	PEFNG: 512				
		tuYvygWq-R4m1Bjft-YwOr0wk+-SYKXj+I1-zDUkabjh-4XE	PEFV				
		RECIELYG-PwpN9C9D-SzyE0E80-+Sit6taf-Tpl.ysOIT-KHk	Access Points: 512				
			101103. 512				
		Pod 2					
7200	BA0001011	hasfWm2M-3pBT5cFB-AS7OZH5a-bly13Gpm-xEDrIl3v-NjM	PEFV	Lic_P2_7200			
		VHC+T6Cm 1+6flOV/t superingl_0i4V12v0_NH1v0w4c p20	RFProtect:				
		m1209rv3-unvi0kgf-X1ufKaER-OSKO0ii]-w0Z6PhrG-IZO	PEFNG: 512				
			Access				
2600.1	480033680	IjcT9zOk-+73YgJMs-sfsBKTAX-hsjuIDIa-5a/D5WGJ-eCs	Points: 512	lia D2 2600 1			
3600-1	AKUU23689	CSOWCe9g-SI+0DKp5-x1loZnNz-GOY4N0MIN-PJ08WrVF-ArM	RFProtect:	IIC_P2_3600-1			
		obt8LBUu-vY9ksJOk-9i0YqQMt-x46It0Hm-cFlzgMi7-A88	512				
		Ci7xzyYm-oudqTR5Z-dBdaryUN-mA5E2Akh-0QPnbjDX-X1s	PEFNG: 512				
		DkbwLLOK-KnPCDvKT-ZhQthuix-VQ8EyICG-TfVCiXeE-Kfw	Access Points: 512				
			RFProtect:				
3600-2	AK0023706	pdVgxzSZ-p91/DMav-7nXTKdEC-m9srQiT9-GD6tZLKO-Z8E	512	lic_P2_3600-2			
		IIKN/MRN-NYTOYHKD-Bd2nzvq9-ICS41rnt-VpFnA/cr-sKA	PEFNG: 512				
		/oyzewng-fYRPeGAf-Rz/vuwqw-UMgfCKfS-xyBC11n4-+PM	PEFV				
		iMBzkuh6-QouhOdtx-B4m/3Iiz-02fF8GgN-gyVDpdVV-SMs	Points: 512				
Pod 3							
7200	BA0001031	z+oCI1aw-R79SkVaU-9c1Eq7QF-Mu+CovMf-Jh9i8ifr-9ak	PEFV	Lic_P3_7200			
			RFProtect:				
		1NjArHY/-0/iS6H7e-qQqLy4Lu-nAicOwyS-yEGwULCA-+z4	PEFNG: 512				
			Access				
		qC1/mRiX-80emBySV-h1Rp/jpJ-6vHmHUfU-aYGnIP6Z-rzs	Points: 512				
3600-1	AK0023703	UlmmQ6Un-PIQVVF+q-B1SKL6wU-dUgBq+Jt-cNZjP872-YFs	PEFV	lic_P3_3600-1			
		4hMQcGtE-fCkAgkOr-gfrwguoW-364ae00k-4+LaaJm4-AvA	REProtect: 512				



		Ye0ORiqO-/pzE0UgR-xgjnHGmi-NIitM1RP-B2HXemof-dos	PEFNG: 512			
		aboWGzG1_XK0VIID7V-DavA7EN1-MWz11s3r-CSachNsO-1uw	Access			
			RFProtect:			
3600-2	AK0023464	sfBDrP5h-SEf1YXbN-G4TWrJf3-Vym4NcwD-lU8vrm90-Wz4	512	lic_P3_3600-2		
		Biztry/x-Qd+ylMxR-FdSI4eKO-u0EpqDoF-K+OZwQs6-1KY	PEFNG: 512			
		qXu0fqVG-iruGLIG7-2bZNFIn9-mPpA8514-+u9C3Dah-Dyg	PEFV			
		LARLU1ij-TPD/Cg47-0wIhY4x/-d9pTtGsm-HKw8DqBN-9d0	Access Points: 512			
Pod 4						
7200	BA0000150	8UmtCxMI-CeC5Cjex-Tw0hUd0o-SrQMzIDz-dQBL6FDt-17w	PEFV	Lic_P4_7200		
		khkoaCVR-uBGaYCPV-vZzhCS9W-TRuElOii-cb6ntxX0-vSo	REProtect: 512			
		www./LIXS_zOOgNbl0_pOXCyrfy_QW6rmPIk-Licdgubl-oPw	DEENIC: 512			
		Wildy 01X3-200gNDi0-DOXGX1X-9W0111K1K-Elcuguiii-0PW	Access			
		ZEFpsydo-7cc6bcFR-UitXUbkQ-AG7UdaME-XcDQTSiS-ZmQ	Points: 512			
2000 1	AV0022667			lic_P4_3600-		
3600-1	AKUU23667	S3tWmjzy-taHtraQY-rH61CM/U-nwn4UmmE-u2Y+wVi11-Exg	PErv RFProtect:	1		
		HpwA82//-PcRrJbY5-wf7OZ0+r-5MLRPTc9-CUhq/bwU-D4I	512			
		mQBdGbU3-scDQHd/7-+INwDI8d-wq8A2swl-WaqCMPZ5-TAE	PEFNG: 512			
			Access			
		EFJDWZII-/GEDLV19-9CU2Pg1J-wr/GI+W1-0075272e+wo	POINTS: 512	lic P4 3600-		
3600-2	AK0024030	Z1Ts/PfN-TO9xh2jN-Ygnxawtm-yEA+BSgM-1A3m1KzH-J+8	512	2		
		ioiaaIrt-qci10oIs-Y5s6wf3r-05m+IzHz-DL/PRSB5-vJ4	PEFNG: 512			
		RIhTzicI-BNM7ZYLz-7wfPbBB/-9ikcuKlX-rh/5RxY/-unc	PEFV			
			Access			
		buWk5C+2-S46YFmNH-ZIUEmTia-dfkH4oca-kOOQk3/k-LZQ	Points: 512			
Pod 5						
7200	BA0001022	K+ELisIZ-AuLatSaI-YEP2N+uh-ZinCktx6-AM9sbOSx-TDU	PEFV	Lic_P5_7200		
			RFProtect:			
		EBU9vKfG-tIbcWZd4-Wn7+71Ux-H7ggJkNA-a66fg+4+-o+I	512			
		I8zPfVSc-NcZ61vt9-EVVUMBek-sG2GBsNJ-QHrKGbq1-Ih8	PEFNG: 512			
		kobsW7Ic_U03KmCAn_AMPnb6t+-+a5YC+si-83M1+XXP-t1U	Access			
			PUIIItS: J12	lic P5_3600-		
3600-1	AK0023694	2TDGfE4v-ICjYWlNx-VNqkw94A-vI6oJe4/-UES0wPd1-rSk	PEFV	1		
		2fcB2Atu-17a7D51m-7DddDE2x-3+E41 ikK-f9il 571 0-40w	RFProtect: 512			
		SISDARUTIZY/FJIII-ZDUUFFax-JTL4LIKK-IJILJZLU-40W	DEENG: 512			
			Access			
		w4kB2H1L-oILrXSMN-fBXo4ybr-EoPaWZJ5-ois2Bivd-J3o	Points: 512			
3600-2	AK0023665	AMN1v1s2-TFoCki08-UVT8uIGI-KMV72LER-sMltCPTI-oBc	RFProtect: 512	lic_P5_3600- 2		
		OfGoJluI-YkYwBJbx-XTFJY/rl-vvHr6mvl-sS34JGoR-Ayg	PEFNG: 512			
		I/hYH7nU-ZZinoHnv-93v48WUU-uovbiM4v-5AKe8vYX-SOs	PEFV			
			Access			
		KbAqJ3Qj-dIZBs7hL-z0C7EOVY-LcaZfx/6-YJ7KkAT/-6IA	Points: 512			



This page intentionally left blank