

ArubaOS 6.3.1



Release Notes

Copyright Information

© 2013 Aruba Networks, Inc. Aruba Networks trademarks include  airwave, Aruba Networks®, Aruba Wireless Networks®, the registered Aruba the Mobile Edge Company logo, Aruba Mobility Management System®, Mobile Edge Architecture®, People Move. Networks Must Follow®, RFPProtect®, Green Island®. All rights reserved. All other trademarks are the property of their respective owners.

Open Source Code

Certain Aruba products include Open Source software code developed by third parties, including software code subject to the GNU General Public License (GPL), GNU Lesser General Public License (LGPL), or other Open Source Licenses. Includes software from Litech Systems Design. The IF-MAP client library copyright 2011 Infoblox, Inc. All rights reserved. This product includes software developed by Lars Fenneberg et al. The Open Source code used can be found at this site:

http://www.arubanetworks.com/open_source

Legal Notice

The use of Aruba Networks, Inc. switching platforms and software, by all individuals or corporations, to terminate other vendors' VPN client devices constitutes complete acceptance of liability by that individual or corporation for this action and indemnifies, in full, Aruba Networks, Inc. from any and all legal actions that might be taken against it with respect to infringement of copyright on behalf of those vendors.

Warranty

This hardware product is protected by the standard Aruba warranty of one year parts/labor. For more information, refer to the ARUBACARE SERVICE AND SUPPORT TERMS AND CONDITIONS.

Altering this device (such as painting it) voids the warranty.

Contents	3
Release Overview	9
Chapter Overview	9
Release Mapping	9
Supported Browsers	9
Contacting Support	10
What's New in this Release	11
6.3.0.0 Feature Support	11
Feature Support by Controller Platform	11
AP Support	11
Changes to Controller Communication with AirWave/ALE	12
Adaptive Radio Management	12
Dynamic Scanning Enhancements	12
Enhanced Client Health Metric	12
Cellular Handoff Assist	13
AP Platform	13
Support for the AP-110 Series	13
Link Aggregation Support on AP-220 Series	13
AP-220 Series Functionality Improvements when Powered Over 802.3af (POE)	13
RAP mode support on AP-220 Series	13
Netgear Cellular Modem Support	13
Franklin Wireless U770 4G Modem Support	14
AP-220 Series Legacy Feature Support	14
Dashboard Monitoring	14
Airgroup Enhancements	14
Lync interoperation with Microsoft Lync Server SDN API	14
In the CLI	14
Security	14

Support for RADIUS Framed-IP-Address for VPN Clients	14
Advertisement of VPN Client Host Routes through OSPF	15
In the CLI	15
Off-Loading a Controller RAP Whitelist to CPPM	15
Serviceability	15
AP-220 Series Serviceability Enhancements	15
Spectrum Analysis	16
Enhanced Support for Spectrum Monitor and Hybrid AP Modes	16
Regulatory Updates	16
Limitations and Deprecated Features	18
Resolved Issues	18
802.1X	18
AirGroup	18
Air Management - IDS	19
AP-Datapath	19
AP-Platform	19
AP-Wireless	19
ARM	21
Authentication	21
Base OS Security	21
Controller - Datapath	22
High Availability	22
Local Database	23
Multicast	23
Platform	23
RADIUS	24
Remote AP	24
Startup Wizard	24
UI Monitoring	25
Voice-SCCP	25
WMM	25
Known Issues and Limitations	25

Air Management	26
Advanced Monitoring	26
AP - Platform	26
AP - Wireless	26
Base OS Security	27
Captive Portal	27
Controller-Datapath	28
Controller-Platform	28
ESI	28
Hardware-Management	28
High Availability	29
IPSec	29
Licensing	29
Master-Redundancy	29
Remote AP	30
Station Management	30
Voice	30
WebUI	30
Issues Under Investigation	31
AP Management	31
AP Wireless	31
AP Platform	31
Controller - Datapath	31
Controller - Platform	32
Configuration	32
RAP	32
Station Management	32
Features Added in Previous 6.3 Releases	33
Support for the AP-220 Series	33
RF 802.11a/g Radio Profiles	33
RF ARM Profile Changes	34
Regulatory Domain Profile Changes	34

Centralized Licensing	34
Primary and Backup Licensing Servers	35
Communication between the License Server and License Clients	35
AirGroup	35
High Availability: Fast Failover	36
Active/Active Deployment model	36
1:1 Active/Standby Deployment model	37
N:1 Active/Standby Deployment model	38
AP Communication with Controllers	38
Known Issues and Limitations in Previous 6.3 Releases	41
Air Management -IDS	41
AP Platform	41
Base OS Security	41
Controller Datapath	42
Master-Redundancy	42
RAP	42
Remote AP	43
Station Management	43
WebUI	43
Upgrade Procedures	45
Upgrade Caveats	45
Installing the FIPS Version of ArubaOS 6.3.1.0	46
Before Installing FIPS Software	46
Important Points to Remember and Best Practices	46
Memory Requirements	47
Backing up Critical Data	48
Back Up and Restore Compact Flash in the WebUI	48
Back Up and Restore Compact Flash in the CLI	48
Upgrading in a Multi-Controller Network	49
Upgrading to 6.3.x	49
Install using the WebUI	49
Upgrading From an Older version of ArubaOS	49

Upgrading From a Recent version of ArubaOS	49
Upgrading With RAP-5 and RAP-5WN APs	50
Install using the CLI	51
Upgrading From an Older version of ArubaOS	51
Upgrading From a Recent version of ArubaOS	51
Downgrading	53
Before you Begin	53
Downgrading using the WebUI	53
Downgrading using the CLI	54
Before You Call Technical Support	55

ArubaOS 6.3.1.0 is a software patch release that introduces fixes to the issues identified in the previous ArubaOS releases. For details on the features described in the following sections, see the *ArubaOS 6.3 User Guide*, *ArubaOS 6.3 CLI Reference Guide*, and *ArubaOS 6.3 MIB Reference Guide*.



See the [Upgrade Procedures on page 45](#) for instructions on how to upgrade your controller to this release.


Chapter Overview

- [What's New in this Release on page 11](#) describes the new fixes, known issues, and enhancements introduced in this release.
- [Features Added in Previous 6.3 Releases on page 33](#) provides description of features and enhancements added in ArubaOS 6.3.
- [Known Issues and Limitations in Previous 6.3 Releases on page 41](#) provides description and workaround for the outstanding issues in ArubaOS 6.3.
- [Upgrade Procedures on page 45](#) covers the procedures for upgrading a controller to ArubaOS 6.3.

Release Mapping

The following illustration shows the patch and maintenance releases that are included in their entirety in ArubaOS 6.3.1.0:

Figure 1 *ArubaOS Releases and Code Stream Integration*



Supported Browsers

The following browsers are officially supported for use with the ArubaOS 6.3.1.0 WebUI:

- Microsoft Internet Explorer 9.x and 10.x on Windows XP, Windows Vista, Windows 7, and Windows 8

- Mozilla Firefox 17 or higher on Windows XP, Windows Vista, Windows 7, and MacOS
- Apple Safari 5.1.7 or higher on MacOS

Contacting Support

Table 1: *Contact Information*

Website Support	
Main Site	http://www.arubanetworks.com
Support Site	https://support.arubanetworks.com
Airheads Social Forums and Knowledge Base	http://community.arubanetworks.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	http://www.arubanetworks.com/support-services/aruba-support-program/contact-support/
Support Email Addresses	
Americas and APAC	support@arubanetworks.com
EMEA	emea_support@arubanetworks.com
Wireless Security Incident Response Team (WSIRT)	wsirt@arubanetworks.com

This chapter describes the features introduced in ArubaOS 6.3.1.

6.3.0.0 Feature Support

All features that were considered "beta quality" in ArubaOS 6.3.0.0 is now fully supported in ArubaOS 6.3.1.

Feature Support by Controller Platform

The table below lists the ArubaOS 6.3 features supported by hardware platform.

Table 2: 6.3 Feature Support by Platform

Features	Controller			
	7200 Series	3600/M3	3400/3200	650/620
AirGroup	Yes	Yes	Yes	No
AppRF 1.0/Firewall Visibility	Yes	Yes	Yes	No
IF-MAP	Yes	Yes	Yes	No
AP Image Preload	Yes	Yes	No	No
Centralized Image Upgrade	Yes	Yes	Yes	No
IAP-VPN	Yes	Yes	Yes	No
RF Planning (Controller)	No	No	No	No
Access Points	All Access Points Supported			

AP Support

ArubaOS 6.3.x.x will be the last release to support the a/b/g only APs as well as the RAP-5 and AP-120 Series. ArubaOS 6.3 will be supported at least through October 31st 2018. Individual AP support dates will vary based on their end of sale date. Please see the Aruba end of support page, <http://www.arubanetworks.com/support-services/end-of-life-products/> for additional details.

Table 3: AP Support

AP Model	End of Sale Dates (Standard Variants)	Last ArubaOS Version Supported
AP-60, AP-61, AP-65, AP-65WB, AP-70 (All Variants)	31-May-2011	ArubaOS 6.3
AP-85 (All Variants)	30-Apr-2013	ArubaOS 6.3

AP Model	End of Sale Dates (Standard Variants)	Last ArubaOS Version Supported
AP-124, AP-125 (All Variants)	31-Jul-2013	ArubaOS 6.3
AP-120, AP-121 (All Variants)	31-Jan-2012	ArubaOS 6.3
RAP-2WG	31-Oct-2013	ArubaOS 6.3
RAP-5WN	31-Oct-2013	ArubaOS 6.3
RAP-5	31-Jan-2012	ArubaOS 6.3

Changes to Controller Communication with AirWave/ALE

This release of ArubaOS provides support for profile-based AMON message filtering for the configured management servers such as AirWave and Analytics Location Engine (ALE). Using this feature, you can filter the AMON messages sent to a configured destination server (AirWave or ALE) based on the message types enabled in the profile.

It is now mandatory to include the filtering profile while configuring the management server. The management server type **XC** in ArubaOS 6.3 is now updated to ALE. In addition, the ArubaOS 6.3.1 upgrade script automatically applies the pre-defined profile (default-amp and default-ale) for both AirWave and XC servers. For more information on configuring the management server and applying message filtering, see the *ArubaOS 6.3.x CLI Reference Guide*.



If you delete a management server profile that is applied to a destination server, you must re-apply a different profile to the server or re-create the same profile for the message filtering process to continue.

Adaptive Radio Management

Dynamic Scanning Enhancements

The Adaptive Radio Management (ARM) feature is improved with an enhanced scanning technique to better identify the best channels for AP channel assignments. In previous releases, when ARM performed a 40 MHz or 80 MHz scan of a channel with a high level of noise or interference (such as that caused by a video bridge), ARM also reported a high noise floor the entire 40 MHz or 80 MHz channel set. This could prevent ARM from assigning an AP to a secondary channel.

Starting with ArubaOS 6.3.1, if ARM reports a high noise floor on a channel within a 40 MHz channel pair or 80 MHz channel set, ARM performs an additional 20 MHz scan on each channel within that channel pair or set, to determine the actual noise floor of each affected channel. This allows ARM to avoid assigning the overutilized channel, while still allowing channel assignments to the other unaffected channels in that channel pair or set.

Enhanced Client Health Metric

An AP's client health is the efficiency at which that AP transmits downstream traffic to a particular client. This value is determined by comparing the amount of time the AP spends transmitting data to a client to the amount of time that would be required under ideal conditions, that is, at the maximum Rx rate supported by client, with no data retries. Starting with ArubaOS 6.3.1, AP-220 Series access points support the client health metric introduced in ArubaOS 6.3.

A client health metric of 100% means the actual airtime the AP spends transmitting data is equal to the ideal amount of time required to send data to the client. A client health metric of 50% means the AP is taking twice as long as is

ideal, or is sending one extra transmission to that client for every packet. A metric of 25% means the AP is taking four times longer than the ideal transmission time, or sending 3 extra transmissions to that client for every packet.

The client health metric appears on the **Dashboard > Performance** page of the controller WebUI, or in the output of the CLI command **show ap debug client-health**.

Cellular Handoff Assist

When both the client match and cellular handoff assist features are enabled, the cellular handoff assist feature can help a dual-mode, 3G/4G-capable Wi-Fi device such as an iPhone, iPad, or Android client at the edge of Wi-Fi network coverage switch from Wi-Fi to an alternate 3G/4G radio that provides better network access.

This feature is disabled by default, and is recommended only for Wi-Fi hotspot deployments. Enable this feature using the ARM profile in the WebUI, or through the following command in the command-line interface:

```
rf arm <profile> cellular-handoff-assist
```

AP Platform

Support for the AP-110 Series

The ArubaAP-114 and AP-115 wireless access points support the IEEE 802.11n standard for high-performance WLAN. These dual radio access points use 3x3 MIMO (Multiple-in, Multiple-out) technology and other high-throughput mode techniques to deliver high-performance, 802.11n 2.4 GHz and 5 GHz functionality while simultaneously supporting existing 802.11a/b/g wireless services.

Link Aggregation Support on AP-220 Series

AP-220 Series access points support link aggregation using either standard port-channel (configuration based) or Link Aggregation Control Protocol (protocol signaling based). AP-220 Series access points can optionally be deployed with LACP configuration to benefit from the higher (greater than 1 Gbps) aggregate throughput capabilities of the two radios.

To enable and configure LACP on AP-220 Series access points configure the **LMS IP** parameter and the **GRE Striping IP** parameter in the **AP System profile**. The **GRE Striping IP** value must be an IPv4 address owned by the controller that has the specified **LMS IP**. The **GRE Striping IP** does not belong to any physical or virtual interface on the controller but the controller can transmit or receive packets using this IP. For more information on Link Aggregation Support on AP-220 Series, see the *ArubaOS 6.3.x User Guide*.



LACP configuration is not applicable to the other AP models.

AP-220 Series Functionality Improvements when Powered Over 802.3af (POE)

Internal AP power optimization allows for increased functionality in the AP-220 Series when powered over 802.3af power. Starting in ArubaOS 6.3.1, the AP-220 Series will have full 802.11ac functionality when powered over 802.3af power. On standard 802.3af power, the USB port and second Ethernet port will be disabled. The 2.4 GHz radio runs with a single stream. The 5 GHz 11ac radio runs with full functionality. All features of the AP-220 Series functions on 802.3at or POE+ power.

RAP mode support on AP-220 Series

This release of ArubaOS allows AP-220 Series access points to be deployed as remote APs (RAPs).

Netgear Cellular Modem Support

ArubaOS 6.3.1 introduces support for the Netgear 313U, 320U, and 330U 4G USB cellular modems on RAP-155.

Franklin Wireless U770 4G Modem Support

ArubaOS 6.3.1 introduces support of the Franklin Wireless U770 4G USB cellular modem for the Sprint LTE service on RAP-3WN, RAP-5WN, RAP-108, and RAP-109.

AP-220 Series Legacy Feature Support

The following legacy features have been added to the AP-220 Series:

- **max-tx-fail:** The number of consecutive unacknowledged transmit frames from a client, that when reached, the AP internally clears up the client state under the assumption that the client is not reachable.
- **probe response threshold:** Indicates the signal strength of the incoming probe request packet, below which the AP will not respond and send probe responses.

Dashboard Monitoring

Airgroup Enhancements

The **Dashboard** tab of the controller WebUI contains an **AirGroup** link that displays the information about AirGroup clients and servers. In previous releases that supported the AirGroup feature, this information was not available in the WebUI, and could only be displayed using the **show airgroupusers** and **show airgroup servers** commands in the command-line interface,

Lync interoperation with Microsoft Lync Server SDN API

Starting from ArubaOS 6.3.1, support for Microsoft® Lync SDN API 1.2, the Microsoft® plug-in that works with Microsoft® Lync server, is added to export details about voice or video calls, desktop-sharing, and file-transfer to Aruba Controller's web server. The communication between Lync SDN API 1.2 and web server occurs over any of the following protocols:

- http
- https

Microsoft® Lync supports the mobile devices that are running on the following operating systems:

- Windows
- Android
- iOS

In the CLI

Under the web-lync-listen-port, the following two parameters are introduced:

- http
- https

Security

Support for RADIUS Framed-IP-Address for VPN Clients

IP addresses are usually assigned to VPN clients from configured local address pools. This feature provides another way to do this by using the Framed-IP-Address attribute that is returned from a RADIUS server to assign the address.

VPN clients use different mechanisms to establish VPN connections with the controller such as IKEv1, IKEv2, EAP or a user certificate. Regardless of how the RADIUS server is contacted for authentication the Framed-IP-Address attribute is assigned the IP address as long as the RADIUS server returns the attribute. The Framed-IP-Address value always has a higher priority than the local address pool.

Advertisement of VPN Client Host Routes through OSPF

This feature allows VPN client addresses to be exported to OSPF and be advertised as host routes (/32). Exporting applies to any VPN client address regardless of how it is assigned.

In the CLI

Use this command to export the VPN client's assigned address to OSPF using IPC.ai

```
(host) (config) #aaa authentication vpn default
(host) (VPN Authentication Profile "default") #
(host) (VPN Authentication Profile "default") # export-route
```

Use the **show ip ospf database** command to show LSA types that are generated.

Off-Loading a Controller RAP Whitelist to CPPM

This feature allows a global whitelist to be maintained on ClearPass Policy Manager (CPPM) instead of on an individual controller. When a RAP or an IAP attempts to authenticate, the controller constructs a radius access request message for CPPM to validate. On a successful authentication, CPPM sends back a radius accept message along with the appropriate Aruba Vendor Specific Attributes (VSA).

For RAPs, the appropriate VSAs are **Aruba-AP-Group** and **Aruba-Location-Id**.

This feature allows whitelist entries to be maintained externally in CPPM for RAPs. The controller, if configured to use an external server, can send a RADIUS access request to a CPPM server. The RAP MAC address is used as a username and password to construct the access request packet and the CPPM validates the RADIUS message and returns the relevant parameters for the authorized RAPs.

If the RAP was initially an Instant AP (IAP) then the RADIUS access request is sent to the CPPM server with the IAP Ethernet address as the username. CPPM verifies if the corresponding entry exists in its local database. Depending on the configured policy, CPPM sends an access reject or accept with attributes that are applicable to the controller.

Serviceability

AP-220 Series Serviceability Enhancements

The following enhancements have been added to the AP-220 Series to improve AP troubleshooting, and used under the supervision Aruba Technical Support.

- **Packet Capture Raw Mode:** Raw packet capture mode is now supported on the AP-220 Series. To enable raw packet capture, use the `ap packet-capture raw-start`.
- **Crash Dump Improvements:** The number of associated clients at the time of the crash has been added to the AP kernel crash information. This enhancement is seen in the output of the command `show ap debug crash-info`.
- **Driver Log Improvements:** The log buffer and show command buffer length has been increased from 4k to 16k. This will prevent the logs from rolling over and causing a loss of information. This enhancement is seen in the output of the command `show ap debug driver-log`.

Spectrum Analysis

Enhanced Support for Spectrum Monitor and Hybrid AP Modes

AP-220 Series and AP-110 Series access points can now be configured as spectrum monitors (AP radios that gather spectrum data but do not service clients), or as hybrid APs (APs that serve clients as access points while analyzing spectrum analysis data for the channel the radio uses to serve clients).

Regulatory Updates

The following table describes regulatory enhancements introduced in ArubaOS 6.3.1.

Table 4: *Regulatory Domain Updates*

Regulatory Domain	Change
FCC DFS Support	Added support for AP-224, AP-225, RAP-108, and RAP-109.
United States, Japan, Canada, all European countries	Added support for AP-114 and AP-115 access points.
Chad, Mali	ArubaOS 6.3.1 introduces support for the Chad (TD) and Mali (ML) country domains. These domains follow the EU country domain settings.
Brazil, Mexico, South Africa, Algeria, Bosnia and Herzegovina, Dominican Republic, Ukraine, South Korea, Macedonia, Malaysia, Puerto Rico	Added support for the AP-104 access point.
Algeria, Colombia, Bolivia, Ecuador, El Salvador, Colombia, Guatemala, Nicaragua, Panama, Puerto Rico, Venezuela, Zambia	Added support for the AP-105 access point.
Algeria, Colombia, Russia	Added support for AP-92 and AP-93 access points.
Columbia, Dominican Republic, Mexico, Puerto Rico, Singapore	Added support for the AP-93H access point.
India	Added support for the 5 GHz band on AP-175P access points.
Russia, Indonesia, Bolivia, Bosnia, Columbia, Croatia, Dominican Republic, El Salvador, Guatemala, Macedonia, Panama, Puerto Rico, Ukraine, Bermuda, Venezuela, Trinidad and Tobago	Added support for the AP-175P access point.
Bermuda, Bosnia and Herzegovina, Colombia, Croatia, Dominican Republic, Macedonia, Russia	Added support for the AP-175DC access point.
Malaysia, Brazil, Venezuela, Bermuda, Bosnia and Herzegovina, Colombia, Croatia, Dominican Republic, Uganda, Macedonia, Russia	Added support for the AP-175AC access point.
Azerbaijan, Belarus, Bosnia and Herzegovina, Colombia, Croatia, Kazakhstan, Peru, Russia, Trinidad and Tobago	Added support for the AP-135 access point.
Argentina	Added support for the RAP-5WN access point.

Regulatory Domain	Change
Macau	Added support for the following access points: <ul style="list-style-type: none"> ● AP-92 ● AP-93 ● AP-104 ● AP-105 ● AP-134 ● AP-135 ● AP-68 (2.4 GHz only) ● AP-175 ● AP-175AC ● AP-175DC ● RAP-2WG (2.4 GHz only) ● RAP-3WN (2.4 GHz only) ● RAP-3WNP (2.4 GHz only) ● RAP-5WN (5 GHz only)
Thailand	Added support for the following access points: <ul style="list-style-type: none"> ● AP-92 ● AP-93 ● AP-93H ● AP-104 ● AP-105 ● AP-134 ● AP-135 ● AP-175P ● AP-175AC ● AP-175DC ● RAP-3WN ● RAP-3WNP
South Korea, Saudi Arabia, UAE, India, Puerto Rico, Columbia, Dominican Republic, Macau, Pakistan, Qatar	Added support for RAP-108 and RAP-109 access points.
Canada	Channel 165 is no longer supported on AP-105 access points. DFS channels are enabled for the following access points: <ul style="list-style-type: none"> ● AP-175 ● AP-175P ● AP-175AC ● AP-175DC
Egypt	Removed support for DFS channels on the AP-125 access point.
Cyprus	Added support for DFS channels on the AP-125 access point.
Bolivia, Sri Lanka	Removed support for the AP-135 access point.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the controller command-line interface and issue the command **show ap allowed-channels country-code <country-code> ap-type <ap-model>**.

The following example shows indoor, outdoor and DFS channels supported by an AP-105 in the **United States** domain.

```
(host) #show ap allowed-channels country-code us ap-type 105
Allowed Channels for AP Type 105 Country Code "US" Country "United States"
-----
```

PHY Type	Allowed Channels
802.11g (indoor)	1 2 3 4 5 6 7 8 9 10 11
802.11a (indoor)	36 40 44 48 52 56 60 64 100 104 108 112 116 132 136 140 149 153 157 161 165
802.11g (outdoor)	1 2 3 4 5 6 7 8 9 10 11
802.11a (outdoor)	52 56 60 64 100 104 108 112 116 132 136 140 149 153 157 161 165
802.11g 40MHz (indoor)	1-5 2-6 3-7 4-8 5-9 6-10 7-11
802.11a 40MHz (indoor)	36-40 44-48 52-56 60-64 100-104 108-112 132-136 149-153 157-161
802.11g 40MHz (outdoor)	1-5 2-6 3-7 4-8 5-9 6-10 7-11
802.11a 40MHz (outdoor)	52-56 60-64 100-104 108-112 132-136 149-153 157-161
802.11a (DFS)	52 56 60 64 100 104 108 112 116 132 136 140

Limitations and Deprecated Features

- RF Plan has been deprecated from ArubaOS 6.3.
- ArubaOS 6.3.1.0 is not recommended for customers with AP-120 Series APs that routinely see over 70 clients associated to an AP. Please contact support if you have any questions.
- On the AP-220 Series, regardless of what is configured on the , the DTIM value for all virtual APs (VAP) is set to one (1).
- On the AP-220 Series, AMSDU is supported in decrypt-tunnel and bridge forwarding modes. It is currently *not* supported in tunnel forwarding mode deployments.

Resolved Issues

The following issues are resolved in ArubaOS 6.3.1:

802.11X

Table 5: 802.11X Fixed Issues

Bug ID	Description
86162	<p>Symptom: Users experienced authentication failures with WPA2-PEAP.</p> <p>Scenario: This issue was triggered by some 2k server certificates. This issue was observed on 6000 series controllers platforms with XLR/XLS processors, 3000 Series, and 600 Series controllers running ArubaOS 6.X.</p>

AirGroup

Table 6: AirGroup Fixed Issues

Bug ID	Description
88239	<p>Symptom: The command-line interface and the WebUI was not accessible on a controller when there was a large number of users supported multicast Domain Name System (mDNS) on the network and advertised different mDNS service IDs. This issue has not affected the client connectivity. This issue is fixed by upgrading to ArubaOS 6.3.1.</p> <p>Scenario: This issue occurred only when the AirGroup Status parameter was enabled in the Configuration > Advanced Services > AirGroup > AirGroup Settings tab of the WebUI with a large number (above 400) of AirGroup service IDs listed under allowall service. This issue was observed in controllers running ArubaOS 6.3.</p>

Air Management - IDS

Table 7: *Air Management-IDS Fixed Issues*

Bug ID	Description
75039 77380	<p>Symptom: AP-224 and AP-225 access points generated frequent false Intrusion Detection System (IDS) alarm Beacon Frame With Incorrect Channel. Changes to the internal code of AP-224 and AP-225 access points fixed the issue.</p> <p>Scenario: Due to the way AP-224 and AP-225 access points scan a channel, it received frames from an alternate channel in the 80 MHz channel set. This triggered a false IDS alarm. This issue was observed in AP-224 and AP-225 access points running ArubaOS 6.3.0.0 or later.</p>

AP–Datapath

Table 8: *AP–Datapath Fixed Issues*

Bug ID	Description
85279	<p>Symptom: In a Master-local setup, all the users connected in bridge or split tunnel mode experienced a low throughput when no bandwidth contracts were configured.</p> <p>Scenario: This issue occurred on controllers running ArubaOS 6.2 or later due to incorrect mapping of the role to bandwidth contract when the ACL IDs in the master and local controllers were different for the same role. It was also observed during an authentication process restart.</p>

AP–Platform

Table 9: *AP–Platform Fixed Issues*

Bug ID	Description
78289	<p>Symptom: Crashes observed in the kernel in the node leave path, when the STA is disconnected. This issue is fixed by using appropriate reference counter protection.</p> <p>Scenario: This issue was triggered by aggressive STATION roams and power saves. This issue is not specific to any AP model and release version.</p>
87359	<p>Symptom: Users were unable to connect to the AP-225 every few hours.</p> <p>Scenario: Enabling the 802.11k feature caused this issue. The action frame was not freed up in the driver sent by the AP. This caused outstanding data frames in the driver to be dropped if the count exceeded a threshold. This issue was observed on the AP-225 and release version ArubaOS 6.3.</p>

AP–Wireless

Table 10: *AP-Wireless Fixed Issues*

Bug ID	Description
88227 88286 88449 88509 88510 88561 88765 88767 88768 88770 88773 89133	<p>Symptom: AP-125 stopped responding and rebooted due to lack of memory when the traffic was heavy. This issue is resolved by removing lldp support on AP-125, thereby reducing the memory consumed.</p> <p>Scenario: This issue was observed only on AP-125.</p>
88282	<p>Symptom: AP-225 running ArubaOS 6.3.0.1 stopped responding and rebooted. The log files for the event listed the reason for the crash as kernel panic: Fatal exception. Changes to the internal code fixed this issue.</p> <p>Scenario: This issue occurred in a master-local 7200 Series controller topology where the AP-225 terminated on both the controllers in a campus mode.</p>
86063	<p>Symptom: The Max Tx Fail feature was not supported on the AP-220 Series in ArubaOS 6.3.</p> <p>Scenario: When a user attempted to enable Max Tx Fail, the feature did not work on the AP-220 Series in ArubaOS 6.3. This feature has now been implemented.</p>
87890	<p>Symptom: The Service Set Identifier (SSID) was not hidden even after the Hide-SSID and the deny-bcast parameters were enabled. This issue is fixed by limiting the broadcast probe response if the Hide-SSID parameter is enabled.</p> <p>Scenario: This issue was observed in AP-225 associated with 7200 Series controllers.</p>
88288	<p>Symptom: An AP-134 crashed with a Fatal exception in interrupt error.</p> <p>Scenario: This issue was observed on 11n APs running ArubaOS 6.3 upon client disassociation.</p>
88512	<p>Symptom: An AP-225 access point transmitting A-MPDU aggregate traffic can perform excessive retries.</p> <p>Scenario: This issue occurred on an AP-225 in a network environment with a busy channel and a large number of intel clients.</p> <p>Workaround: None.</p>
80426 77834 81672 85186 85381 85396 85400 85658 85713 80426 85186 80426 86821	<p>Symptom: An AP crashed and rebooted frequently and the log files for the event listed the reason for the crash as kernel panic.</p> <p>Scenario: This issue occurred in remote APs (RAPs) or campus APs (CAPs) with CPsec enabled, when the VPN tunnel terminated and re-established with traffic on the tunnel. This issue was observed in AP-134, AP-135, and RAP-155 models.</p>

ARM

Table 11: *ARM–Datapath Fixed Issues*

Bug ID	Description
86084	<p>Symptom: A wireless client remained associated to an AP-220 Series even though the signal strength was weak.</p> <p>Scenario: This issue occurred on AP-220 Series running ArubaOS 6.3. When the hand off assist feature is enabled on AP-220 Series, packets were not sent over the air to the client.</p>

Authentication

Table 12: *Authentication–Datapath Fixed Issues*

Bug ID	Description
81035	A client driver upgrade resolved the issue.

Base OS Security

Table 13: *Base OS Security Fixed Issues*

Bug ID	Description
83776	<p>Symptom: Atheros based client devices were unable to connect to WPA-TKIP networks after ArubaOS 6.1.3.7. This issue is fixed by disabling use of multiple Traffic Identifier (TID) for WPA-TKIP.</p> <p>Scenario: This issue was observed when Wireless Multimedia Extensions (WMM) was enabled and the Atheros clients did not support multiple relay counters.</p>
84456	<p>Symptom: Remote APs (RAPs) kept rebooting and did not come up on the controller.</p> <p>Scenario: This issue occurred as two RAPs using a static IP address tried to establish sessions using the same RAP credentials. This issue was not limited to any specific controller or RAP model.</p>
84628 86814 87497 88406 88571	<p>Symptom: An M3 controller module in a 6000 series controller unexpectedly rebooted. Log files for the event listed the reason for the reboot as Datapath timeout. This issue is fixed by validating the bridge entries for VoIP clients.</p> <p>Scenario: This issue occurred when an invalid bridge value was computed and stored in an internal module (datapath). This issue was observed in an M3 controller module running ArubaOS 6.2.0.0.</p>
85519	<p>Symptom: One or more SSH (Secure Shell) sessions to a controller failed when multiple simultaneous SSH sessions occurred. The updates are made to sshd (SSH Daemon) process in ArubaOS 6.3.1.0 to avoid this issue .</p> <p>Scenario: This issue was observed in ArubaOS 6.1.x, 6.2.x, and 6.3.x.</p>
85688	<p>Symptom: The Virtual Intranet Access VPN (VIA-VPN) Authentication using RSA SecureID was not functioning for both New PIN and Next Tokencode modes. This issue was resolved by changes to the code that maintain the state of radius exchange.</p> <p>Scenario: This issue was observed in ArubaOS 6.3.0.0 while performing VIA-VPN authentication with an RSA server using RSA SecureID.</p>
86687	<p>Symptom: The controller’s SSH configuration has been modified to reduce a potential vulnerability to DOS attacks.</p> <p>Scenario: This issue was identified on controllers running ArubaOS 6.3.0.0.</p>

Table 13: Base OS Security Fixed Issues

Bug ID	Description
86867	<p>Symptom: When a user-role and the ACL configured as the ip access-group on the interface for APs/RAPs have the same name, the AP/RAP traffic is hitting the user-role ACL instead of the ip access-group ACL.</p> <p>Scenario: This issue was observed on a controller running ArubaOS 6.2.1.2.</p> <p>Workaround: Do not create an ACL for the IP access-group that has a name matching that of any user-role in the configuration.</p>
88165	<p>Symptom Clients using a wired connection are assigned an incorrect user role</p> <p>Scenario: This bug is applicable for wired clients, and is not specific to a controller type of software version. This issue occurs when information about an AP wired connection gets overwritten by similar information from another AP, resulting in a loss of wired information on the first AP, and preventing users associated with that AP from falling into an their user role.</p>
88386	<p>Symptom : User roles disappeared randomly after a controller reloaded. Internal code changes fixed this issue.</p> <p>Scenario : The issue occurred when many user roles were added or roles with heavy configurations exceeded the buffer space on the controller .This issue was not specific to any ArubaOS version or controller model.</p>

Controller - Datapath

Table 14: Controller Datapath Fixed Issues

Bug ID	Description
84071	<p>Symptom: A controller stopped responding and unexpectedly rebooted. The log files for the event listed the reason for the reboot as “Datapath exception.” This issue occurred on 3000 Series, and 7200 Series controller running ArubaOS 6.2.1.0.</p> <p>Scenario: This issue occurred when an SSL encapsulated invalid ESP frame was received and processed by the controller.</p>

High Availability

Table 15: High Availability Fixed Issues

Bug ID	Description
86798	<p>Symptom: When APs were connected to controllers using the high availability: fast failover feature in a master\master topology , AirWave could not see information about rogue APs from the active master controller. Improvements to the way master IP information for each controller is saved resolves this issue.</p> <p>Scenario: When the high availability:fast failover feature was enabled between two master controllers acting as HA-Active and HA-Standby controllers, the active controller's master IP address stored in the AP was overwritten by the master IP address from the standby controller. This caused WMS information to be sent to the standby controller instead of the active controller.</p>

Local Database

Table 16: *Local Database Fixed Issues*

Bug ID	Description
84494	<p>Symptom: A controller unexpectedly rebooted, with the log files for the event listing the reason for the reboot as Nanny rebooted machine - udbserver process died.</p> <p>Scenario: This issue occurred on a standalone master 7210 controller with one associated AP-135 access point, and was resolved by internal code changes.</p>
88019	<p>Symptom: A warning message WARNING: This controller has RAP whitelist data stored in pre-6.3 format, which is consuming running the command 'local-userdb-ap del all appeared, when a user logged into a controller. This issue is fixed by deleting the warning file, when all the old entries are deleted.</p> <p>Scenario: This issue occurred when a controller was upgraded from previous version of ArubaOS to 6.3 or later. This issue was not specific to any controller model or release version.</p>

Multicast

Table 17: *Multicast Fixed Issues*

Bug ID	Description
88138	<p>Symptom: One of the proxy group entries aged out after issuing the show ip igmp proxy-group command. This crashed the multicast module in the controller. Changes to the internal code of the multicast module fixed the issue.</p> <p>Scenario: This issue was not limited to a specific controller model and was observed in ArubaOS 6.3.0.1.</p>

Platform

Table 18: *Platform Fixed Issues*

Bug ID	Description
76447	<p>Symptom: AnM3controller stopped responding and rebooted. The controller listed the reason for the crash as a controller processor kernel panic. This issue was resolved by internal improvements to hardware register access.</p> <p>Scenario: This issue was observed in local M3 controllers running ArubaOS 6.1.3.5.</p>
81555	<p>Symptom: A controller crashed and rebooted after upgrading the software from ArubaOS 6.1.3.6 to ArubaOS 6.1.3.7. The log files for the event listed the reason for the crash as a watchdog timeout. The interrupt handler for packet parsing was modified to ensure that CPU was not overwhelmed with the traffic packets.</p> <p>Scenario: In a high traffic deployment, a race condition triggered the controller crash. This issue was not specific to any controller model.</p>

RADIUS

Table 19: *RADIUS Fixed Issues*

Bug ID	Description
85848	<p>Symptom: The Calling_Station_Id was sent as IP address instead of MAC address even though the option “Use IP address for calling station ID” was not selected in the AAA server. A new check box has been added for the MAC address, which fixed this issue in 6.3.1.0.</p> <p>Scenario: This issue was observed when the user executed the aaa authentication-server radius x command, and was not specific to any controller model.</p>
87814	<p>Symptom: On client disconnection, the RADIUS accounting STOP record packet counter reset to zero. Changes to the internal code fixed the issue.</p> <p>Scenario: This issue occurred when an AP was provisioned in decrypt-tunnel mode with RADIUS accounting enabled. This issue was not limited to a specific controller model and was observed in ArubaOS 6.3.0.0 or later.</p>

Remote AP

Table 20: *Remote AP Fixed Issues*

Bug ID	Description
85473	<p>Symptom: A RAP-3WN AP using a USB modem was unable to come up until it rebooted. Changes to how the RAP-3WN determines the modem product ID has resolved this issue.</p> <p>Scenario: This issue occurred on a RAP-3WN AP running ArubaOS 6.2.1.2 connected to a Huawei E156 modem.</p>
86082	<p>Symptom: An AP-225 failed to respond. Enhancements in the internal code fixed this issue.</p> <p>Scenario: This issue was observed on when Point-to-point protocol over Ethernet (PPPoE) was enabled on AP-220 Series access points.</p>
86934	<p>Symptom: The AP failed during boot up when the Huawei modem E1371 was used. An internal code error when using this modem caused the issue.</p> <p>Scenario: This issue was observed on a RAP-108 and RAP-109 running ArubaOS 6.3.</p>
87105	<p>Symptom: Printers connected to the wired port of a remote AP (RAP) in tunnel mode intermittently fall into the wrong VLAN. This issue is resolved by improvements that ensure that the remote AP configuration state is properly cleared when its connection is reset.</p> <p>Scenario: This issue occurred on a RAP-5 remote AP running ArubaOS 6.2.1.2, when configuration settings were not properly cleared on a remote AP that reset its connection to the controller. As a result, the RAP's ethernet interface was brought up in bridge mode first, then changed to tunnel mode. This caused a configuration conflict between the controller and the RAP, as the controller managed the RAP as a remote bridge user, and the RAP operated as a user in tunnel mode.</p>

Startup Wizard

Table 21: *Startup Wizard Fixed Issues*

Bug ID	Description
85312	<p>Symptom: An error message Error: Very high throughput must be enabled to enable 80 MHz channel usage appeared on the Finish page of the Campus WLAN wizard. This issue was resolved by enabling the high-throughput or very-high-throughput settings in the 802.11a or 802.11g radio profiles before enabling 40MHz and 80MHz, and disabling 80MHz and 40MHz, before disabling the throughput setting.</p> <p>Scenario: This error occurred when a WLAN is configured with a, a+n, b/g, or b/g+n radio types.</p>

UI Monitoring

Table 22: *UI Monitoring Fixed Issues*

Bug ID	Description
80233	<p>Symptom: The Monitoring > Access Points and Monitoring > Network > All Access Points page of the controller WebUI showed APs as down, even if they are showed as up in the command-line interface. This issue is fixed by improvements to the local management switch (LMS) IP on the master controller and now the status of APs is displayed accurately on the WebUI.</p> <p>Scenario: This issue was observed on a 6000 master controller with two local controllers running ArubaOS 6.2.0.2 in a master/local topology.</p>
83820	<p>Symptom: Dashboard page was not getting loaded in the WebUI. This issue was fixed by disabling the compatibility mode on the IE.</p> <p>Scenario: The issue occurred when the user tried to access WebUI in IE8 in compatibility mode (This mode is used to support websites that was developed for older Version of IE browser). The issue was not specific to a controller model or a software version.</p>
84151 85229 85569 86554	<p>Symptom: The Security Summary page in the WebUI timed out if the event table in the WMS database became very large. This issue was resolved by enabling a periodic clean-up of the WMS event table entries.</p> <p>Scenario: This issue was observed when too many APs where terminating on a controller. This issue was not limited to any specific controller model.</p>

Voice-SCCP

Table 23: *Voice-SCCP Fixed Issues*

Bug ID	Description
83403 86180 86369	<p>Symptom: The clients were disconnected from the network due an internal module crash. This issue was resolved by not prioritizing the subsequent RTP sessions for the SCCP calls for the clients.</p> <p>Scenario: This issue was observed while handling SCCP state transition hence an internal module (STM) crashed. This issue occurred on controllers running ArubaOS 6.1 and 6.2 versions, and was not limited to a specific controller model.</p>
86224	<p>Symptom: Calls dropped after 30 seconds when performing a blindly transferred SIP call.</p> <p>Scenario: This issue was observed on the M3 controller module running ArubaOS version 6.2.1. It occurred when Ascom phones sent a DELTS request upon receiving either an "invite" message from the SIP server or after sending a "180 Ringing" message back to the server.</p>

WMM

Table 24: *WMM Fixed Issues*

Bug ID	Description
68503	<p>Symptom: When the same Differentiated Service Code Point (DSCP) value is mapped to two different access categories, the lower of the two is used for the downstream traffic. This issue was resolved, by mapping the higher value to the downstream traffic.</p> <p>Scenario: This issue was observed on controllers running ArubaOS 6.2 or earlier in tunnel and decrypt-tunnel forwarding modes.</p>

Known Issues and Limitations

The following are known issues and limitations observed in ArubaOS 6.3.1. Bug IDs and applicable workarounds are included.

Air Management

Table 25: *Air Management Known Issues*

Bug ID	Description
86804	<p>Symptom: The master controller reboots periodically and displays the message "Nanny rebooted machine - low on free memory."</p> <p>Scenario: This issue is observed on the 3200XM controllers running ArubaOS version 6.3. It occurs when the 3200XM controller is near its memory limit and the customer upgrades to a newer version of ArubaOS software that requires more memory than the 3200XM controller is capable of handling.</p> <p>Workaround: Tune or disable some features in order to use less memory.</p>

Advanced Monitoring

Table 26: *AMON Known Issues*

Bug ID	Description
88392	<p>Symptom: The Reference count column in the output of the show mgmt-server profile <profile-name> command displays an incorrect reference count value due to an architectural limitation.</p> <p>Scenario: This issue is not limited to any specific controller model.</p> <p>Workaround: None.</p>
88752 87809	<p>Symptom: A crash observed in the firewall visibility due to DNS cache corruption.</p> <p>Scenario: The trigger of this issue is not known and this issue is not limited to any specific controller model or release version.</p> <p>Workaround: None.</p>

AP - Platform

Table 27: *AP - Platform Known Issues*

Bug ID	Description
87138	<p>Symptom: .The show running-config command output does not display the default rf ht-radio profiles (default-a and default-g).</p> <p>Scenario: This issue was observed on 3000 Series controllers running ArubaOS 6.3 in an all master deployment.</p> <p>Workaround: Make any minor configuration change to the default rf ht-radio profiles (default-a and default-g) and revert it.</p>

AP - Wireless

Table 28: *AP - Wireless Known Issues*

Bug ID	Description
84884	<p>Symptom: Fragmented EAP frames are not sent with the same data rate as a non-fragmented EAP frames.</p> <p>Scenario: This issue occurs on 802.11ac access points running ArubaOS 6.3.0.0 or later.</p> <p>Workaround: None.</p>

Bug ID	Description
87231	<p>Symptom: A high CPU utilization is noticed on an AP-105 after upgrading to 6.3. However, the client performance is not impacted.</p> <p>Scenario: This issue is observed on an AP-105 running ArubaOS 6.3 deployed in a high Wi-Fi or non-Wi-Fi interference environment.</p> <p>Workaround: None</p>
88512	<p>Symptom: An AP-225 access point transmitting A-MPDU aggregate traffic can perform excessive retries.</p> <p>Scenario: This issue occurred on an AP-225 in a network environment with a busy channel and a large number of intel clients.</p> <p>Workaround: None.</p>

Base OS Security

Table 29: *Base OS Security Known Issues*

Bug ID	Description
86867	<p>Symptom: When a user-role and the ACL configured as the ip access-group on the interface for APs/RAPs have the same name, the AP/RAP traffic is hitting the user-role ACL instead of the ip access-group ACL.</p> <p>Scenario: This issue was observed on a controller running ArubaOS 6.2.1.2.</p> <p>Workaround: Do not create an ACL for the IP access-group that has a name matching that of any user-role in the configuration.</p>
88271	<p>Symptom: It is not possible to configure a deny any any protocol ACL that overrides a statically configured permit any any protocol ACL.</p> <p>Scenario: This issue was observed on a controller running ArubaOS 6.3.0.1. This action is expected behavior and is prevented by ArubaOS so the user cannot disrupt controller functions.</p> <p>Workaround: None. However, it is possible to configure user defined ACLs on the subnet to override static ACLs.</p>

Captive Portal

Table 30: *Captive Portal Known Issues*

Bug ID	Description
87294	<p>Symptom: Captive Portal (CP) whitelist mapped to the user-role does not get synchronized with the standby controller.</p> <p>Scenario: The administrator creates a net-destination and adds it to the CP profile whitelist mapped to the user-role in the master controller. This configuration does not get synchronized with the standby controller. This issue is observed in ArubaOS 6.2.1.2 and not limited to a specific controller model.</p> <p>Workaround: None</p>
88405	<p>Symptom: After successfully authenticating a client using Captive Portal, the browser does not automatically redirect the client to the original URL.</p> <p>Scenario: This issue is observed in 7200 Series controller running ArubaOS 6.3.0.0.</p> <p>Workaround: Set the welcome-page parameter to the desired URL under aaa authentication captive-portal profile.</p>

Controller-Datapath

Table 31: *Controller-Datapath Known Issues*

Bug ID	Description
87271	<p>Symptom: When the port speed is automatically set to 10/100/1000 mbps on the dual personality RJ45 ports 0/0/0 and 0/0/1, occasionally, the traffic forwarding on the port stops.</p> <p>Scenario: This issue occurs in 7210, 7220, and 7240 series controllers running ArubaOS 6.2.</p> <p>Workaround: Shutdown the port, change the port speed, and then turn on the port again.</p>

Controller-Platform

Table 32: *Controller-Platform Known Issues*

Bug ID	Description
88321	<p>Symptom: A local controller crashes and reboots and log files for the event lists the reason for the crash as watchdog timeout.</p> <p>Scenario: The trigger of this issue is not known. This issue occurs in M3controllers running ArubaOS 6.3.0.1 in a master-local topology.</p> <p>Workaround: None.</p>

ESI

Table 33: *ESI Known Issues*

Bug ID	Description
88042	<p>Symptom: The http traffic from a user is not redirected to the ESI server, even when the ESI server is reachable and http traffic redirection for the corresponding user role is enabled.</p> <p>Scenario: The trigger of this issue is not known. This issue is observed on 7240-US controllers running ArubaOS 6.3 in a master-local topology.</p> <p>Workaround: None</p>

Hardware-Management

Table 34: *Hardware-Management Known Issues*

Bug ID	Description
87481	<p>Symptom: The 7200 Series controllers return an invalid value when SNMP walk is performed on the internal temperature details (OID .1.3.6.1.4.1.14823.2.2.1.2.1.10).</p> <p>Scenario: The trigger of this issue is not known. This issue is observed on 7200 Series controllers running ArubaOS 6.3.</p> <p>Workaround: Use the show inventory command in the CLI or navigate to the Monitoring > Controller > Inventory tab of the WebUI to view the Card and CPU temperatures.</p>

High Availability

Table 35: *High Availability Known Issues*

Bug ID	Description
80206	<p>Symptom: The high availability:fast failover feature introduced in ArubaOS 6.3 does not support a deployment model where a VRRP-based redundant master pair (a master controller and standby-master controller) is also configured as high availability active-standby pair.</p> <p>Scenario: This topology is not supported because the high availability: fast failover feature does not allow the APs to form standby tunnels to the standby master.</p> <p>Workaround: None</p>

IPSec

Table 36: *IPSec Known Issues*

Bug ID	Description
80460	<p>Symptom: Remote client and Site-to-Site VPN performance is low and does not scale to the controller's limit when IKEv2 with GCM256-EC384 encryption algorithm configured.</p> <p>Scenario: This issue impacts the 651, 3600, and 7200 Series controllers and occurs when the IKE session is established to a standby unit in a failover deployment.</p> <p>Workaround: None.</p>

Licensing

Table 37: *Licensing Known Issues*

Bug ID	Description
87424	<p>Symptom: The licenses are lost on a standby master causing the configuration on the local controller to be lost.</p> <p>Scenario: This issue occurs when the standby comes up before the master after a reboot. This may also occur in an all master scenario when running ArubaOS 6.3.</p> <p>Workaround: None</p>

Master-Redundancy

Table 38: *Master Redundancy Known Issues*

Bug ID	Description
80041 87946 87032 88067	<p>Symptom: The <code>show database synchronize</code> command from the CLI displays FAILED message. The standby controller database is out-of-sync with the master controller and any switchover during out-of-sync state causes the controller to be in inconsistent state.</p> <p>Scenario: This issue may occur in on any controller running ArubaOS 6.3.0.0 in a master-standby configuration.</p> <p>Workaround: None</p>

Remote AP

Table 39: *Remote AP Known Issues*

Bug ID	Description
89861	<p>Symptom: If a RAP-108/ RAP-109 with a USB modem is powered with a Power over Ethernet (PoE) injector, the remote AP might not have sufficient power to activate the USB port, preventing the AP from detecting the USB modem.</p> <p>Scenario: This issue was identified on RAP-108/ RAP-109 remote APs powered only by PoE, without an external power source.</p> <p>Workaround: Connect a RAP-108/ RAP-109 remote AP with a USB modem to an external power source.</p>
88497	<p>Symptom: A RAP-5WN AP using a Sierra Wireless AirCard 313U modem can stop responding when an associated client sends traffic.</p> <p>Scenario: This issue only occurs in a 3G network when the AP's cellular network preference setting is configured to use auto mode.</p> <p>Workaround: Configure the cellular network preference settings in the RAP-5WN AP to use 4G-only mode to connect to the network.</p>

Station Management

Table 40: *Station Management Known Issues*

Bug ID	Description
86620	<p>Symptom: The show ap association client-mac command shows client MAC addresses for clients that aged out beyond the idle timeout value.</p> <p>Scenario: This issue is not limited to a specific controller or ArubaOS release version.</p> <p>Workaround: Issue aaa user fast-age command to age out the inactive clients.</p>

Voice

Table 41: *Voice Known Issues*

Bug ID	Description
89258	<p>Symptom: Lync SDN API-based ALG does not work when clients are behind NAT.</p> <p>Scenario: When the user VLANs to which Lync clients are connected have IP NAT inside or the Lync users are behind a NAT, the Lync SDN API based Lync ALG will not be able to prioritize the lync traffic. Apart from this, it will not provide the visibility information to these calls through either CLI or dashboard. This issue was observed on a controller running ArubaOS 6.3.1.</p> <p>Workaround: None.</p>

WebUI

Table 42: *WebUI Known Issues*

Bug ID	Description
89225	<p>Symptom: Configuration of a mgmt-server (ALE or AirWave) using the WebUI is not supported.</p> <p>Workaround: Use the CLI to configure mgmt-servers.</p>

Issues Under Investigation

The following issues have been reported in ArubaOS 6.3.1 but not confirmed. The issues have not been able to be reproduced and the root cause has not been isolated. They are included here because they have been reported to Aruba and are being investigated. In the tables below, similar issues have been grouped together.

AP Management

Table 43: *Air Management Known Issues*

Bug ID	Description
86804	<p>Symptom: The master controller reboots periodically and displays the message "Nanny rebooted machine - low on free memory."</p> <p>Scenario: This issue is observed on the 3200XM controllers running ArubaOS version 6.3. It occurs when the 3200XM controller is near its memory limit and the customer upgrades to a newer version of ArubaOS software that requires more memory than the 3200XM controller is capable of handling.</p> <p>Workaround: Tune or disable some features in order to use less memory.</p>

AP Wireless

Table 44: *AP Wireless Observed Issues*

Bug ID	Description
82813	<p>Symptom: An old generation Sony PlayStation® 3 randomly stops passing traffic after upgrading from ArubaOS 6.1.4.1 to 6.2.0.3.</p> <p>Scenario: The issue occurs when a user tries to stream videos, download movies, and log into a Netflix account. This issue is observed after upgrading the controller from 6.1.4.1 to 6.2.0.3.</p>

AP Platform

Table 45: *AP Platform Observed Issues*

Bug ID	Description
88009	<p>Symptom: Although the APs are shown as down in the master controller, they are functional in the local controller and are associated to clients.</p>
88044 88569	<p>Symptom: AP-135 access point stops responding and reboots. The output of the show ap debug system-status command lists the reason for the crash as kernel panic.</p>

Controller - Datapath

Table 46: *Controller - Datapath Observed Issues*

Bug ID	Description
85591	<p>Symptom: Clients that are running Linux 6.2.1.x and associated to a 7200 Series controller periodically fail to pass traffic.</p>
85628	<p>Symptom: A 3000 Series controller running ArubaOS 6.2.1.2 stops responding and reboots. The log files for the event list the reason for the crash as Control Processor Kernel Panic.</p>
87410	<p>Symptom: A 3000 Series controller running ArubaOS 6.2.1.1 stops responding and reboots. The log files for the event list the reason for the crash as Watchdog Timeout.</p>

Controller - Platform

Table 47: *Controller - Platform Observed Issues*

Bug ID	Description
82402 84212 86636 87552	Symptom: A controller unexpectedly stops responding and reboots. The log files for the event lists the reason for the crash as httpd_wrap process died . This issue occurs in 3400 Series controllers running ArubaOS 6.2.1.0 and later, and is under investigation.
88107	Symptom: A 3600 controller running ArubaOS 6.2.1.2 stops responding and reboots. The log files for the event listed the reason for the crash as User pushed reset .
88241 88240 88242 88243	Symptom: An unexpected reboot of an M3 controller due to an internal process (WMS) error has been observed.

Configuration

Table 48: *Configuration Observed Issues*

Bug ID	Description
85628	Symptom: The write mem command in the command-line interface of a 3000 Series controller running ArubaOS 6.2.1.1 fails to save the configuration, and triggers the error Save failed: Error: Unable to generate config .
87410	Symptom: A 3000 Series controller running ArubaOS 6.2.1.1 stops responding and reboots. The log files for the event list the reason for the crash as Watchdog Timeout .

RAP

Table 49: *RAP Observed Issues*

Bug ID	Description
86650	Symptom: A controller sends continuous RADIUS requests for the clients connected behind wired port of a remote AP (RAP). The wired AP is in split-tunnel mode and uses both MAC and 802.1X authentication. This issue occurs after upgrading from ArubaOS 6.1.3.6 to 6.2.1.1 or 6.2.1.2. This issue is under investigation.

Station Management

Table 50: *Station Management Observed Issues*

Bug ID	Description
88314	Symptom: An internal module on a 7240 local controller configured with voice ALGs stops responding then restarts after idle voice clients age out. This issue causes network disruptions.

This chapter lists the major features introduced in ArubaOS 6.3.0.0.

Support for the AP-220 Series



On the AP-220 Series, regardless of what is configured on the controller, the DTIM value for all virtual APs (VAP) is set to one (1).



In ArubaOS 6.3, the MPDU Aggregation option under the HT SSID Profile does not affect the AP-220 Series AP. This means that aggregation is always enabled on the AP-220 Series and disabling the MPDU Aggregation option will have no effect. If you need to disable aggregation, you must disable High Throughput and Very High Throughput in the 802.11a and 802.11g radio profiles under RF Management.

The new AP-220 Series of access points support 802.11ac on the 5 GHz band using 80 MHz channels. The following new features and configuration parameters have been introduced to support configuration of Very High Throughput (VHT) settings.

Table 51: WLAN HT-SSID Profile Settings for VHT

Parameter	Description
80MHz-enable	Enables or disables the use of 80 MHz channels on Very High Throughput (VHT) APs.
very-high-throughput-enable	Enable/Disable support for Very High Throughput (802.11ac) on the SSID. Default: Enabled
vht-supported-mcs-map	Modulation Coding Scheme (MCS) values or ranges of values for spatial streams 1 through 3. Valid values for the maximum MCS settings are 7, 8, 9 or a dash (-) if a spatial stream is not supported. If a MCS is not valid for a particular combination of bandwidth and number of spatial streams, it will not be used. Default: 9,9,9
vht-txbf-explicit-enable	Enable or disable VHT Explicit Transmit Beamforming. When this feature is enabled, the AP requests information about the MIMO channel and uses that information to transmit data over multiple transmit streams using a calculated steering matrix. The result is higher throughput due to improved signal at the beamformee (the receiving client). If this setting is disabled, all other transmit beamforming settings will not take effect. Default: Enabled
vht-txbf-sounding-interval	Time interval in seconds between channel information updates between the AP and the beamformee client. Default 25 seconds

RF 802.11a/g Radio Profiles

The following parameters were added to the RF 802.11a radio profile:

Table 52: 802.11a Radio Settings for VHT

Parameter	Description
very-high-throughput-enable	Enable/Disable support for Very High Throughput (802.11ac) on the radio. Default: Enabled

RF ARM Profile Changes

The following parameter was added to the RF ARM profile:

Table 53: RF ARM Settings for VHT

Parameter	Description
80MHz-support	If enabled, this feature allows ARM to assign 80 MHz channels on APs that support VHT. Default: Enabled

Regulatory Domain Profile Changes

The following parameters was added to the regulatory domain profile:

Table 54: Regulatory Domain Settings for VHT

Parameter	Description
valid-11a-80mhz-channel-group	<p>This parameter defines which 80MHz channels on the “a” band are available for assignment by ARM and for controller to randomly assign if user has not specified a channel. The channel numbers below correspond to channel center frequency.</p> <ul style="list-style-type: none">● Possible choices in US: 42, 58, 106, 122, 138, 155● Possible choices in EU: 42, 58, 106, 122● Possible choices in JP: 42, 58, 106, 122● Possible choices global: 42, 58, 106, 122, 138, 155

Centralized Licensing

Centralized licensing simplifies licensing management by distributing AP, PEFNG, RF Protect, xSec and ACR licenses installed on one controller to other controllers on the network. One controller to act as a centralized license database for all other controllers connected to it, allowing all controllers to share a pool of unused licenses. The primary and backup licensing server can share single set of licenses, eliminating the need for a redundant license set on the backup server. Local licensing client controllers maintain information sent from the licensing server even if licensing client controller and licensing server controller can no longer communicate.

You can use the centralized licensing feature in a master-local topology with a redundant backup master, or in a multi-master network where all the masters can communicate with each other (for example, if they are all connected to a single AirWave server). In the master-local topology, the master controller acts as the primary licensing server, and the redundant backup master acts as the backup licensing server. In a multi-master network, one controller must be designated as a primary server and a second controller configured as a backup licensing server.

Enable and configure this feature using the **Configuration > Controller > Centralized Licenses** tab in the WebUI, or using the **licensingprofile** commands in the command-line interface.

Primary and Backup Licensing Servers

Centralized licensing allows the primary and backup licensing server controllers share a single set of licenses. If you do not enable this feature, the master and backup master controller each require separate, identical license sets. The two controllers acting as primary and backup license servers must use the same version of ArubaOS, and must be connected on the same broadcast domain using the Virtual Router Redundancy Protocol (VRRP). Other client controllers on the network connect to the licensing server using the VRRP virtual IP address configured for that set of redundant servers. By default, the primary licensing server uses the configured virtual IP address. However, if the controller acting as the primary licensing server becomes unavailable, the secondary licensing server will take ownership of the virtual IP address, allowing licensing clients to retain seamless connectivity to a licensing server.



Only one backup licensing server can be defined for each primary server.

Communication between the License Server and License Clients

When you enable centralized licensing, information about the licenses already installed on the individual client controllers are sent to the licensing server, where they are added into the server's licensing table. The information in this table is then shared with all client controllers as a pool of available licenses. When a client controller uses a license in the available pool, it communicates this change to the licensing server master controller, which updates the table before synchronizing it with the other clients.

Client controllers do not share information about factory-installed or built-in licenses to the licensing server. A controller using the centralized licensing feature will use its built-in licenses before it consumes available licenses from the license pool. As a result, when a client controller sends the licensing server information about the licenses that client is using, it only reports licenses taken from the licensing pool, and disregards any built-in licenses used. For example, if a controller has a built-in 16-AP license and twenty connected APs, it will disregard the built-in licenses being used, and will report to the licensing server that it is using only four AP licenses from the license pool.

When centralized licensing is first enabled on the licensing server, its licensing table only contains information about the licenses installed on that server. When the clients contact the server, the licensing server adds the client licenses to the licensing table, then it sends the clients back information about the total available licenses for each license type. In the following example, the licenses installed on two client controllers are imported into the license table on the license server. The licensing server then shares the total number of available licenses with other controllers on the network.

When new AP associates with a licensing client, the client sends updated licensing information to the server. The licensing server then recalculates the available total, and sends the revised license count back to the clients. If a client uses an AP license from the license pool, it also consumes a PEFNG and RF Protect license from the pool, even if that AP has not enabled any features that would require that license.

AirGroup

AirGroup is a unique enterprise-class capability that leverages zero configuration networking to allow mobile device technologies, such as the AirPrint wireless printer service and the AirPlay mirroring service, to communicate over a complex access network topology.

With AirGroup:

- End users can register their personal devices and define a group of other users, such as friends and roommates, who are allowed to share their registered devices.
- Administrators can register and manage an organization's shared devices (like printers and conference room Apple TVs). An administrator can grant global access to each device, or limit access to users with a specified user name, role, or user location.

For more information on AirGroup, see the *ArubaOS 6.3 User Guide*.

High Availability: Fast Failover

ArubaOS 6.3 introduces the High Availability: Fast Failover feature. This WLAN redundancy solution allows a campus AP to rapidly fail over from an active to a standby controller without needing to rebootstrap, and significantly reduces network downtime and client traffic disruption during network upgrades or unexpected failures. APs using the High Availability: Fast Failover feature regularly communicate with the standby controller, so the standby controller has only a light workload to process if an AP failover occurs. This results in very rapid failover times, and a shorter client reconnect period. Previous redundancy solutions (like a backup-LMS) put a heavy load on the backup controller during failover, resulting in slower failover performance.



This feature supports failover for campus APs in tunnel forwarding mode only. It does not support failover for remote APs or campus APs in bridge forwarding mode.

A controller using this feature can have one of three high availability roles - active, standby or dual. An **active** controller serves APs, but cannot act as a failover standby controller for any AP except the ones that it serves as active. A **standby** controller acts as a failover backup controller, but cannot be configured as the primary controller for any AP. A **dual** controller can support both roles, and acts as the active controller for one set of APs, and also acts as a standby controller for another set of APs.

The High Availability: Fast Failover feature supports redundancy models with an active controller pair, or an active/standby deployment model with one backup controller supporting one or more active controllers. Each of these clusters of active and backup controllers comprises a high-availability group. Note that all active and backup controllers within a single high-availability group must be deployed in a single master-local topology.


High Availability groups support the following deployment modes.


- [Active/Active Deployment model on page 36](#)
- [1:1 Active/Standby Deployment model on page 37](#)
- [N:1 Active/Standby Deployment model on page 38](#)

Active/Active Deployment model

In this model, two controllers are deployed in dual mode. Controller one acts as standby for the APs served by controller two, and vice-versa. Each controller in this deployment model supports approximately 50% of its total AP capacity, so if one controller fails, all the APs served by that controller would fail over to the other controller, thereby providing high availability redundancy to all APs in the cluster.

Figure 2 Active-Active HA Deployment







1:1 Active/Standby Deployment model

In this model, the active controller supports up to 100% of its rated AP capacity, while the other controller in standby mode is idle. If the active controller fails, all APs served by the active controller would failover to the standby controller.

Figure 3 1:1 Active/Standby Deployment



N:1 Active/Standby Deployment model


In this model, the active controller supports up to 100% of its rated AP capacity, while the other controller in standby mode is idle. If an active controller fails, all APs served by the active controller would failover to the standby controller.



This model requires that the AP capacity of the standby controller is able to support the total number of APs distributed across all active controllers in the cluster.

In the cluster shown in the example below, the standby controller has enough AP capacity to support the total number of APs terminating on the active controllers. (Controller1 and Controller2)

Figure 4 1:1 Active/Standby Deployment



AP Communication with Controllers

The High Availability: Fast Failover features works across Layer-3 networks, so there is no need for a direct Layer-2 connection between controllers in a high-availability group.

When the AP first connects to its active controller, the active controller provides the IP address of a standby controller, and the AP attempts to establish a tunnel to the standby controller. If an AP fails to connect to the first standby controller, the active controller will select a new standby controller for that AP, and the AP will attempt to connect to that standby controller.

An AP will failover to its backup controller if it fails to contact its active controller through regular heartbeats and keepalive messages, or if the user manually triggers a failover using the WebUI or CLI.

Configure the High Availability feature in the WebUI using the **Configuration > Advanced Services > All Profiles > HA profile** page or using the ha-group-profile in the command-line interface.

The following are the known issues and limitations found in ArubaOS 6.3. Applicable Bug IDs and workarounds are included.

Air Management -IDS

Table 55: *Air Management- IDS Known Issues*

Bug ID	Description
79913	<p>Symptom: When configuring an AP in Air Monitor (AM) mode, a user has the option to select the rare scan-mode, causing the AP to scan most frequencies in the spectrum, even if they are non-standard channels. Currently some AP-220 Series APs configured to use the rare scan mode cannot scan non-standard channels that do not belong to some country's regulatory domain.</p> <p>Scenario: This issue occurs on AP-220 Series access points running ArubaOS 6.3.</p> <p>Workaround: None.</p>

AP Platform

Table 56: *AP Platform Known Issues*

Bug ID	Description
82015 84757	<p>Symptom: An AP associated with a controller does not age out as expected when you change the heartbeat threshold and interval parameters.</p> <p>Scenario: This issue occurs when you change the heartbeat threshold and interval parameters in the AP's system profile while the AP's status is UP in the controller. This issue is not specific to a controller, AP model, or ArubaOS release version.</p> <p>Workaround: Reboot the AP after changing the heartbeat threshold and interval parameters. Alternatively, configure the heartbeat threshold and interval parameters before associating the AP with the controller.</p>

Base OS Security

Table 57: *Base OS Security Known Issues*

Bug ID	Description
50206	<p>Symptom: Secure Shell (SSH) access to a controller fails to authenticate local database when the RADIUS server is not responsive.</p> <p>Scenario: This issue occurs when multiple authentication servers are configured with local authentication enabled. This issue is not specific to any controller model and release version.</p> <p>Workaround: None.</p>

Controller Datapath

Table 58: *Controller Datapath Known Issues*

Bug ID	Description
74428, 88758	<p>Symptom: On the RJ45 ports 0/0/0 and 0/0/1, if the port speed is forced from 1Gbps to 10/100Mbps when traffic is flowing, traffic forwarding on the port can stop in an unintended manner.</p> <p>Scenario: This issue has been observed on 7200 Series controllers running ArubaOS 6.2 in configurations or topologies where traffic is flowing. The trigger is unknown.</p> <p>Workaround: Change the speed on the port following these steps:</p> <ol style="list-style-type: none">1. Shut the port.2. Change the speed on the port.3. Open the port.
82824	<p>Symptom: In some cases, when the number of users is high (more than 16k), a user may be flagged as IP spoofed user with the Enforce DHCP parameter is enabled in the AP group's AAA profile.</p> <p>Scenario: This issue is observed in controllers running ArubaOS 6.3.</p> <p>Workaround: Disable the enforce_dhcp parameter in the AP group's AAA profile.</p>
85368	<p>Symptom: After booting up and logging into the controller, the configured message of the day banner does not display. Instead, a portion of the configuration displays.</p> <p>Scenario: This issue is observed in controllers running ArubaOS 6.2 and 6.3, after upgrading a controller with a "banner motd" config that has more than 255 characters in one line. This issue occurs in old versions such as ArubaOS 6.1.X-FIPS that do not validate the length per line.</p> <p>Workaround: Change the banner to comply with new the character limit per line. You can have more than 1 line of 255 characters. Run the write-mem command afterward to fix this issue.</p>

Master-Redundancy

Table 59: *Master-Redundancy Known Issues*

Bug ID	Description
75367	<p>Symptom: Enabling web-server debug logging using the CLI command logging level debugging system subcat webserver does not take effect until you restart the HTTPD process.</p> <p>Scenario: This happens on all controller models running ArubaOS 3.x, 5.x and 6.x software versions when web-server debug logging mode is enabled.</p> <p>Workaround: Restart the HTTPD process in order to enable debug logging.</p>

RAP

Table 60: *RAP Known Issues*

Bug ID	Description
85249	<p>Symptom: A degradation of Transmission Control Protocol (TCP) throughput by 9 to 11 Mbps is observed on a RAP.</p> <p>Scenario: This issue occurs in RAPs with any forwarding mode and not specific to any AP model.</p> <p>Workaround: None.</p>

Remote AP

Table 61: *Remote AP Known Issues*

Bug ID	Description
83002	<p>Symptom: A wireless client connected to a backup virtual AP configured in bridge forwarding mode is unable to get an IP address from an assigned VLAN.</p> <p>Scenario: This issue occurred when the controller upgraded to ArubaOS 6.2.</p> <p>Workaround: Once the AP connects to the controller, remove the virtual AP profile from the ap-group/ap-name configuration, then return the virtual AP profile to the ap-group/ap-name settings.</p>

Station Management

Table 62: *Station Management Known Issues*

Bug ID	Description
82012	<p>Symptom: An internal controller process kept restarting, preventing the controller from servicing clients.</p> <p>Scenario: This issue was identified when the controller upgraded its image, and was triggered when the controller expected IKEv2 information that was missing from the mysql global AP database.</p> <p>Workaround: None.</p>

WebUI

Table 63: *WebUI Known Issues*

Bug ID	Description
55981	<p>Symptom: When a user views the Spectrum UI with saved preferences from a newer version of ArubaOS, the UI will display charts incorrectly.</p> <p>Scenario: After downgrading from a newer version of ArubaOS, such as from 6.2.x to 6.1.x with saved Spectrum preferences, will cause the Spectrum UI to display charts incorrectly. This is due to the difference between the Spectrum UI in 6.2 and previous versions.</p> <p>Workaround: Use the command ap spectrum clear-webui-view-settings on the controller to delete the saved preferences.</p>
77542	<p>Symptom: Upgrading from a local file does not work on the 600 Series controller.</p> <p>Scenario: For the local file upgrade to be successful, the controller must have at least 75 MB of free memory. When upgraded to ArubaOS 6.2, the 600 Series controller has only 77 MB of free memory remaining. And when the browser UI is launched, the free memory is decreased to 75 MB. In this case, the local file upgrade will fail. It is recommended that you do not use the local file upgrade function in the controller has less than 80 MB of free memory.</p> <p>Workaround: None. Use the USB, TFTP, SCP, or CLI option to upgrade instead.</p>
82611	<p>Symptom: The Dashboard > Access Points page of the WebUI of a controller running ArubaOS 6.2.0.3 does not correctly display AP information.</p> <p>Scenario: Accessing the Dashboard > Access Points page can trigger the following error in the controller log files: An internal system error has occurred at file mon_mgr.c function mon_mgr_proc_trend_query line 4142 error PAPI_Send failed: Cannot allocate memory. This issue was not related to a memory allocation error.</p> <p>Workaround: None.</p>

This chapter details software upgrade procedures. Aruba best practices recommend that you schedule a maintenance window for upgrading your controllers.



Read all the information in this chapter before upgrading your controller.

Topics in this chapter include:

- [Upgrade Caveats on page 45](#)
- [Installing the FIPS Version of ArubaOS 6.3.1.0 on page 46](#)
- [Important Points to Remember and Best Practices on page 46](#)
- [Memory Requirements on page 47](#)
- [Backing up Critical Data on page 48](#)
- [Upgrading in a Multi-Controller Network on page 49](#)
- [Upgrading to 6.3.x on page 49](#)
- [Downgrading on page 53](#)
- [Before You Call Technical Support on page 55](#)

Upgrade Caveats

Before upgrading to any version of ArubaOS 6.3, take note of these known upgrade caveats.

- ArubaOS 6.3.1.0 is not recommended for customers with AP-120 Series APs that routinely see over 70 clients associated to an AP. Please contact support if you have any questions.
- Beginning in ArubaOS 6.3.1, the local file upgrade option in the 620 and 650 controller WebUI has been disabled.
- The ArubaOS WebUI will not support the following special characters for AP Name and AP Group in ArubaOS 6.3.1:
 - AP Name: % = + \ | ' " &
 - AP Group: * () + [? \ = | ' " &
- The local file upgrade option in the 7200 Series controller WebUI does not work when upgrading from ArubaOS 6.2. When this option is used, the controller displays the error message “Content Length exceed limit” and the upgrade fails. All other upgrade options work as expected.
- Aruba AirGroup
 - Starting from ArubaOS 6.3, AirGroup is enabled by default. Upgrading the access controller from any version of ArubaOS to ArubaOS 6.3 converts the access controller to integrated mode controller. To continue to be in overlay mode, you must disable AirGroup on the access controller running ArubaOS 6.3.
 - If you migrate from an overlay mode to an integrated mode, you must remove the already configured redirect ACLs from the user roles and remove the L2 GRE tunnel from the access controller. Aruba recommends to remove the overlay controller from the network or disable AirGroup on it.
- ArubaOS 6.3 does not allow you to create redundant firewall rules in a single ACL. ArubaOS will consider a rule redundant if the primary keys are the same. The primary key is made up of the following variables:
 - source IP/alias
 - destination IP/alias

- proto-port/service

If you are upgrading from ArubaOS 6.1 or earlier and your configuration contains an ACL with redundant firewall rules, upon upgrading, only the last rule will remain.

For example, in the below ACL, both ACE entries could not be configured in ArubaOS 6.3. Once the second ACE entry is added, the first would be over written.

```
(host) (config) #ip access-list session allowall-laptop
(host) (config-sess-allowall-laptop)# any any any permit time-range test_range
(host) (config-sess-allowall-laptop)# any any any deny
(host) (config-sess-allowall-laptop)#end
(host) #show ip access-list allowall-laptop
```

```
ip access-list session allowall-laptop
allowall-laptop
-----
Priority  Source  Destination  Service  Action  TimeRange
-----  -
1         any     any          any      deny
```

- ArubaOS 6.3 is supported only on the newer MIPS controllers (7200 Series, M3, 3200MXM, 3400, 3600, and 600 Series).
Legacy PPC controllers (200, 800, 2400, SC1/SC2 and 3200XM are *not* supported. DO NOT upgrade to 6.3.x if your deployments contain a mix of MIPS and PPC controllers in a master-local setup.
- When upgrading the software in a multi-controller network (one that uses two or more Aruba controllers), special care must be taken to upgrade all the controllers in the network and to upgrade them in the proper sequence. (See [Upgrading in a Multi-Controller Network on page 49.](#))

Installing the FIPS Version of ArubaOS 6.3.1.0

Download the FIPS version of software from <https://support.arubanetworks.com>.

Before Installing FIPS Software

Before you install a FIPS version of software on a controller that is currently running a non-FIPS version of the software, you must reset the configuration to the factory default or you will not be able to login to the CLI or WebUI. Do this by running the **write erase** command just prior to rebooting the controller. This is the only supported method of moving from non-FIPS software to FIPS software.

Important Points to Remember and Best Practices

Ensure a successful upgrade and optimize your upgrade procedure by taking the recommended actions listed below. You should save this list for future use.

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any other changes to your network during the upgrade, such as configuration changes, hardware upgrades, or changes to the rest of the network. This simplifies troubleshooting.
- Know your network and verify the state of your network by answering the following questions.

- How many APs are assigned to each controller? Verify this information by navigating to the **Monitoring > Network All Access Points** section of the WebUI, or by issuing the **show ap active** and **show ap database** CLI commands.
- How are those APs discovering the controller (DNS, DHCP Option, Broadcast)?
- What version of ArubaOS is currently on the controller?
- Are all controllers in a master-local cluster running the same version of software?
- Which services are used on the controllers (employee wireless, guest access, remote AP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load software images to the controller. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If problems occur during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path should it be required.
- Before you upgrade to ArubaOS 6.3.1.0, assess your software license requirements and load any new or expanded licenses you require. For a detailed description of these new license modules, refer to the “Software Licenses” chapter in the user guide.

Memory Requirements

All Aruba controllers store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the controller. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. To maintain the reliability of your WLAN network, Aruba recommends the following compact memory best practices:

- Issue the **show memory** command to confirm that there is at least 40 MB of free memory available for an upgrade using the CLI, or at least 60 MB of free memory available for an upgrade using the WebUI. Do not proceed unless this much free memory is available. To recover memory, reboot the controller. After the controller comes up, upgrade immediately.
- Issue the **show storage** command to confirm that there is at least 60 MB of flash available for an upgrade using the CLI, or at least 75 MB of flash available for an upgrade using the WebUI.



In certain situations, a reboot or a shutdown could cause the controller to lose the information stored in its compact flash card. To avoid such issues, it is recommended that you issue the **halt** command before power cycling.

If the output of the **show storage** command indicates that insufficient flash memory space is available, you must free up additional memory. Any controller logs, crash data or and flash backups should be copied to a location off the controller, then deleted from the controller to free up flash space. You can delete the following files from the controller to free memory before upgrading:

- **Crash Data:** Issue the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 48](#) to copy the **crash.tar** file to an external server, then issue the command **tar clean crash** to delete the file from the controller.
- **Flash Backups:** Use the procedures described in [Backing up Critical Data on page 48](#) to back up the flash directory to a file named **flash.tar.gz**, then issue the command **tar clean flash** to delete the file from the controller.
- **Log files:** Issue the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 48](#) to copy the **logs.tar** file to an external server, then issue the command **tar clean logs** to delete the file from the controller.

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the compact flash file system to an external server or mass storage device. At the very least, you should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Floor plan JPEGs
- Custom captive portal pages
- x.509 certificates
- Controller Logs

Back Up and Restore Compact Flash in the WebUI

The WebUI provides the easiest way to back up and restore the entire compact flash file system. The following steps describe how to back up and restore the compact flash file system using the WebUI on the controller:

1. Click on the **Configuration** tab.
2. Click the **Save Configuration** button at the top of the page.
3. Navigate to the **Maintenance > File > Backup Flash** page.
4. Click **Create Backup** to back up the contents of the compact flash file system to the flashbackup.tar.gz file.
5. Click **Copy Backup** to copy the file to an external server.

You can later copy the backup file from the external server to the compact flash file system using the file utility in the **Maintenance > File > Copy Files** page.

6. To restore the backup file to the Compact Flash file system, navigate to the **Maintenance > File > Restore Flash** page. Click **Restore**.

Back Up and Restore Compact Flash in the CLI

The following steps describe the back up and restore procedure for the entire compact flash file system using the controller's command line:

1. Enter **enable** mode in the CLI on the controller, and enter the following command:

```
(host) # write memory
```

2. Use the backup command to back up the contents of the Compact Flash file system to the flashbackup.tar.gz file.

```
(host) # backup flash
Please wait while we tar relevant files from flash...
Please wait while we compress the tar file...
Checking for free space on flash...
Copying file to flash...
File flashbackup.tar.gz created successfully on flash.
```

3. Use the copy command to transfer the backup flash file to an external server or storage device:

```
(host) copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword> <remote directory>
```

```
(host) copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can later transfer the backup flash file from the external server or storage device to the Compact Flash file system with the copy command:

```
(host) # copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) # copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Use the restore command to untar and extract the flashbackup.tar.gz file to the compact flash file system:

```
(host) # restore flash
```

Upgrading in a Multi-Controller Network

In a multi-controller network (a network with two or more Aruba controllers), special care must be taken to upgrade all controllers based on the controller type (master or local). Be sure to back up all controllers being upgraded, as described in [Backing up Critical Data on page 48](#).



For proper operation, all controllers in the network must be upgraded with the same version of ArubaOS software. For redundant (VRRP) environments, the controllers should be the same model.

To upgrade an existing multi-controller system to ArubaOS 6.3.1.0:

1. Load the software image onto all controllers (including redundant master controllers).
2. If all the controllers cannot be upgraded with the same software image and reloaded simultaneously, use the following guidelines:
 - a. Remove the link between the master and local mobility controllers.
 - b. Upgrade the software image, then reload the master and local controllers one by one.
 - c. Verify that the master and all local controllers are upgraded properly.
 - d. Connect the link between the master and local controllers.

Upgrading to 6.3.x

Install using the WebUI



Confirm that there is at least 60 MB of free memory and at least 75 MB of flash available for an upgrade using the WebUI. For details, see [Memory Requirements on page 47](#)

Upgrading From an Older version of ArubaOS

Before you begin, verify the version of ArubaOS currently running on your controller. If you are running one of the following versions of ArubaOS, you must download and upgrade to an interim version of ArubaOS before upgrading to ArubaOS 6.3.1.

- For ArubaOS 3.x versions earlier than ArubaOS 3.4.4.1, download the latest version of ArubaOS 3.4.5.x.
- For ArubaOS RN-3.x or ArubaOS 5.0.x versions earlier than ArubaOS 5.0.3.1, download the latest version of ArubaOS 5.0.4.x.
- For ArubaOS versions 6.0.0.0 or 6.0.0.1, download the latest version of ArubaOS 6.0.1.x.

Follow step 2 to step 11 of the procedure described in [Upgrading From a Recent version of ArubaOS](#) to install the interim version of ArubaOS, then repeat step 1 to step 11 of the procedure to download and install ArubaOS 6.3.

Upgrading From a Recent version of ArubaOS

The following steps describe the procedure to upgrade from one of the following recent versions of ArubaOS:

- 6.0.1.x or later
- 5.0.3.1 or later (If you are running ArubaOS 5.0.3.1 or the latest 5.0.x.x, review [Upgrading With RAP-5 and RAP-5WN APs on page 50](#) before proceeding further.)
- 3.4.4.1 or later

Install the ArubaOS software image from a PC or workstation using the Web User Interface (WebUI) on the controller. You can also install the software image from a TFTP or FTP server using the same WebUI page.

1. Download ArubaOS 6.3.1.0 from the customer support site.
2. Upload the new software image(s) to a PC or workstation on your network.
3. Validate the SHA hash for a software image:
 - a. Download the file **Aruba.sha256** from the download directory.
 - b. To verify the image, load the image onto a Linux system and execute the command **sha256sum <filename>** or use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the support site.



The ArubaOS image file is digitally signed, and is verified using RSA2048 certificates pre-loaded onto the controller at the factory. Therefore, even if you do not manually verify the SHA hash of a software image, the controller will not load a corrupted image.

4. Log in to the ArubaOS WebUI from the PC or workstation.
5. Navigate to the **Maintenance > Controller > Image Management** page. Select the **Upload Local File** option, then click **Browse** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. In the **partition to upgrade** field, select the non-boot partition.
8. In the **Reboot Controller After Upgrade** option field, best practices is to select **Yes** to automatically reboot after upgrading. If you do not want the controller to reboot immediately, select **No**. Note however, that the upgrade will not take effect until you reboot the controller.
9. In **Save Current Configuration Before Reboot** field, select **Yes**.
10. Click **Upgrade**.
11. When the software image is uploaded to the controller, a popup window displays the message **Changes were written to flash successfully**. Click **OK**. If you chose to automatically reboot the controller in step 7, the reboot process starts automatically within a few seconds (unless you cancel it).
12. When the reboot process is complete, log in to the WebUI and navigate to the **Monitoring > Controller > Controller Summary** page to verify the upgrade.

Once your upgrade is complete, perform the following steps to verify that the controller is behaving as expected.

1. Log in into the WebUI to verify all your controllers are up after the reboot.
2. Navigate to **Monitoring > Network Summary** to determine if your APs are up and ready to accept clients.
3. Verify that the number of access points and clients are what you would expected.
4. Test a different type of client for each access method that you use and in different locations when possible.
5. Complete a back up of all critical configuration data and files on the compact flash file system to an external server or mass storage facility. See [Backing up Critical Data on page 48](#) for information on creating a backup.

Upgrading With RAP-5 and RAP-5WN APs

If you have completed the first upgrade hop to the latest version of ArubaOS 5.0.4.x and your WLAN includes RAP-5/RAP-5WN APs, do not proceed until you complete the following process. Once complete, proceed to [step 5 on page 50](#). Note that this procedure can only be completed using the controller's command line interface.

1. Check the provisioning image version on your RAP-5/RAP-5WN Access Points by executing the **show ap image version** command.
2. If the flash (Provisioning/Backup) image version string shows the letters *m*, for example, 3.3.2.11-m-3.0, note those AP names and IP addresses.

- For each of the RAP-5/RAP-5WN APs noted in the step 2, upgrade the provisioning image on the backup flash partition by executing the following command:

```
apflash ap-name <Name_of_RAP> backup-partition
```

The RAP-5/RAP-5WN reboots to complete the provisioning image upgrade.

- When all the RAP-5/RAP-5WN APs with a 3.3.2.x-based RN provisioning image have successfully upgraded, verify the provisioning image by executing the following command:

```
show ap image version
```

The flash (Provisioning/Backup) image version string should now show a version that does not contain the letters “m”, for example, 5.0.4.8.

If you omit the above process or fail to complete the flash (Provisioning/Backup) image upgrade to 5.0.4.x and the RAP-5/RAP-5WN was reset to factory defaults, the RAP will not be able to connect to a controller running ArubaOS 6.3.1 and upgrade its production software image.

Install using the CLI



Confirm that there is at least 40 MB of free memory and at least 60 MB of flash available for an upgrade using the CLI. For details, see [Memory Requirements on page 47](#)

Upgrading From an Older version of ArubaOS

Before you begin, verify the version of ArubaOS currently running on your controller. If you are running one of the following versions of ArubaOS, you must download and upgrade to an interim version of ArubaOS before upgrading to ArubaOS 6.3.1.0.

- For ArubaOS 3.x versions earlier than ArubaOS 3.4.4.1, download the latest version of ArubaOS 3.4.5.x.
- For ArubaOS RN-3.x or ArubaOS 5.0.x versions earlier than ArubaOS 5.0.3.1, download the latest version of ArubaOS 5.0.4.x.
- For ArubaOS versions 6.0.0.0 or 6.0.0.1, download the latest version of ArubaOS 6.0.1.x.

Follow step 2 - step 7 of the procedure described in [Upgrading From a Recent version of ArubaOS](#) to install the interim version of ArubaOS, then repeat step 1 to step 7 of the procedure to download and install ArubaOS 6.3.

Upgrading From a Recent version of ArubaOS

The following steps describe the procedure to upgrade from one of the following recent versions of ArubaOS:

- 6.0.1.x or later
- 5.0.3.1 or later. (If you are running ArubaOS 5.0.3.1 or the latest 5.0.x.x, review [Upgrading With RAP-5 and RAP-5WN APs on page 50](#) before proceeding further.)
- 3.4.4.1 or later

To install the ArubaOS software image from a PC or workstation using the Command-Line Interface (CLI) on the controller:

- Download ArubaOS 6.3.0 from the customer support site.
- Open a Secure Shell session (SSH) on your master (and local) controller(s).
- Execute the **ping** command to verify the network connection from the target controller to the SCP/FTP/TFTP server:

```
(hostname) # ping <ftphost>
```

or

```
(hostname) # ping <tftphost>
```

or

```
(hostname) # ping <scphost>
```

4. Use the **show image version** command to check the ArubaOS images loaded on the controller's flash partitions. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(hostname) #show image version
-----
Partition           : 0:0 (/dev/ha1)
Software Version    : ArubaOS 6.1.1.0 (Digitally Signed - Production Build)
Build number        : 28288
Label               : 28288
Built on            : Thu Apr 21 12:09:15 PDT 2012
-----
Partition           : 0:1 (/dev/ha1)**Default boot**
Software Version    : ArubaOS 6.1.3.2 (Digitally Signed - Production Build)
Build number        : 33796
Label               : 33796
Built on            : Fri May 25 10:04:28 PDT 2012
```

5. Use the **copy** command to load the new image onto the non-boot partition:

```
(hostname)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
or
(hostname)# copy tftp: <tftphost> <image filename> system: partition <0|1>
or
(hostname)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
or
(hostname)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```



The USB option is only available on the 7200 Series controllers.

6. Execute the **show image version** command to verify the new image is loaded:

```
(hostname)# show image version
-----
Partition           : 0:1 (/dev/ha1) **Default boot**
Software Version    : ArubaOS 6.3.1.0 (Digitally Signed - Production Build)
Build number        : 38319
Label               : 38319
Built on            : Fri June 07 00:03:14 PDT 2013
-----
Partition           : 0:1 (/dev/ha1)
Software Version    : ArubaOS 6.1.3.2 (Digitally Signed - Production Build)
Build number        : 33796
Label               : 33796
Built on            : Fri May 25 10:04:28 PDT 2012
```

7. Reboot the controller:

```
(hostname)# reload
```

8. Execute the **show version** command to verify the upgrade is complete.

```
(hostname)# show version
```

Once your upgrade is complete, perform the following steps to verify that the controller is behaving as expected.

1. Log in into the command-line interface to verify all your controllers are up after the reboot.
2. Issue the command **show ap active** to determine if your APs are up and ready to accept clients.

3. Issue the command **show ap database** to verify that the number of access points and clients are what you would expect.
4. Test a different type of client for each access method that you use and in different locations when possible.
5. Complete a backup of all critical configuration data and files on the compact flash file system to an external server or mass storage facility. See [Backing up Critical Data on page 48](#) for information on creating a backup.

Downgrading

If necessary, you can return to your previous version of ArubaOS.



If you upgraded from 3.3.x to 5.0, the upgrade script encrypts the internal database. New entries created in ArubaOS 6.3.1 are lost after the downgrade (this warning does not apply to upgrades from 3.4.x to 6.1).



If you do not downgrade to a previously-saved pre-6.1 configuration, some parts of your deployment may not work as they previously did. For example, when downgrading from ArubaOS 6.3.1 to 5.0.3.2, changes made to WIPS in 6.x prevents the new predefined IDS profile assigned to an AP group from being recognized by the older version of ArubaOS. This unrecognized profile can prevent associated APs from coming up, and can trigger a profile error.

These new IDS profiles begin with `ids-transitional` while older IDS profiles do not include `transitional`. If you think you have encountered this issue, use the `show profile-errors` and `show ap-group` commands to view the IDS profile associated with AP Group.



When reverting the controller software, whenever possible, use the previous version of software known to be used on the system. Loading a release not previously confirmed to operate in your environment could result in an improper configuration.

Before you Begin

Before you reboot the controller with the pre-upgrade software version, you must perform the following steps:

1. Back up your controller. For details, see [Backing up Critical Data on page 48](#).
2. Verify that control plane security is disabled.
3. Set the controller to boot with the previously-saved pre-6.3 configuration file.
4. Set the controller to boot from the system partition that contains the previously running ArubaOS image.

When you specify a boot partition (or copy an image file to a system partition), the software checks to ensure that the image is compatible with the configuration file used on the next controller reload. An error message displays if system boot parameters are set for incompatible image and configuration files.

5. After downgrading the software on the controller:
 - Restore pre-6.3 flash backup from the file stored on the controller. Do not restore the ArubaOS 6.3.1.0 flash backup file.
 - You do not need to re-import the WMS database or RF Plan data. However, if you have added changes to RF Plan in ArubaOS 6.3.1.0, the changes do not appear in RF Plan in the downgraded ArubaOS version.
 - If you installed any certificates while running ArubaOS 6.3.1.0, you need to reinstall the certificates in the downgraded ArubaOS version.

Downgrading using the WebUI

The following sections describe how to use the WebUI to downgrade the software on the controller.

1. If the saved pre-upgrade configuration file is on an external FTP/TFTP server, copy the file to the controller by navigating to the **Maintenance > File > Copy Files** page.

- a. For **Source Selection**, select FTP/TFTP server, and enter the IP address of the FTP/TFTP server and the name of the pre-upgrade configuration file.
- b. For **Destination Selection**, enter a filename (other than default.cfg) for Flash File System.
2. Set the controller to boot with your pre-upgrade configuration file by navigating to the **Maintenance > Controller > Boot Parameters** page.
 - a. Select the saved pre-upgrade configuration file from the Configuration File menu.
 - b. Click **Apply**.
3. Determine the partition on which your previous software image is stored by navigating to the **Maintenance > Controller > Image Management** page. If there is no previous software image stored on your system partition, load it into the backup system partition (you cannot load a new image into the active system partition):
 - a. Enter the FTP/TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Click **Upgrade**.
4. Navigate to the **Maintenance > Controller > Boot Parameters** page.
 - a. Select the system partition that contains the pre-upgrade image file as the boot partition.
 - b. Click **Apply**.
5. Navigate to the **Maintenance > Controller > Reboot Controller** page. Click **Continue**. The controller reboots after the countdown period.
6. When the boot process is complete, verify that the controller is using the correct software by navigating to the **Maintenance > Controller > Image Management** page.

Downgrading using the CLI

The following sections describe how to use the CLI to downgrade the software on the controller.

1. If the saved pre-upgrade configuration file is on an external FTP/TFTP server, use the following command to copy it to the controller:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
or
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```

2. Set the controller to boot with your pre-upgrade configuration file.


```
# boot config-file <backup configuration filename>
```
3. Execute the **show image version** command to view the partition on which your previous software image is stored. You cannot load a new image into the active system partition (the default boot).

In the following example, partition 0, the backup system partition, contains the backup release 6.1.3.2. Partition 1, the default boot partition, contains the ArubaOS 6.3.1.0 image:

```
#show image version
-----
Partition           : 0:1 (/dev/hal)
Software Version    : ArubaOS 6.3.1.0 (Digitally Signed - Production Build)
Build number        : 33796
Label               : 33796
Built on            : Fri May 25 10:04:28 PDT 2012
-----
Partition           : 0:1 (/dev/hda2) **Default boot**
Software Version    : ArubaOS 6.3.1.0 (Digitally Signed - Production Build)
Build number        : 38319
Label               : 38319
Built on            : Fri June 07 00:03:14 2013
```

4. Set the backup system partition as the new boot partition:

```
# boot system partition 0
```

5. Reboot the controller:

```
# reload
```

6. When the boot process is complete, verify that the controller is using the correct software:

```
# show image version
```

Before You Call Technical Support

Before you place a call to Technical Support, follow these steps:

1. Provide a detailed network topology (including all the devices in the network between the user and the Aruba controller with IP addresses and Interface numbers if possible).
2. Provide the wireless device's make and model number, OS version (including any service packs or patches), wireless NIC make and model number, wireless NIC's driver date and version, and the wireless NIC's configuration.
3. Provide the controller logs and output of the **show tech-support** command via the WebUI Maintenance tab or via the CLI (**tar logs tech-support**).
4. Provide the syslog file of the controller at the time of the problem. Aruba strongly recommends that you consider adding a syslog server if you do not already have one to capture logs from the controller.
5. Let the support person know if this is a new or existing installation. This helps the support team to determine the troubleshooting approach, depending on whether you have an outage in a network that worked in the past, a network configuration that has never worked, or a brand new installation.
6. Let the support person know if there are any recent changes in your network (external to the Aruba controller) or any recent changes to your controller and/or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
7. Provide the date and time (if possible) when the problem first occurred. If the problem is reproducible, list the exact steps taken to recreate the problem.
8. Provide any wired or wireless sniffer traces taken during the time of the problem.
9. Provide the controller site access information, if possible.

