RF Health Report for All Groups and Folders

1/1/2015 12:00 AM to 2/28/2015 12:00 AM
Generated on 3/5/2015 3:40 PM

Most Noise (5 GHz)

Rank	Device	Avg Noise (dBm)	Channel Changes	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	MS103-0412	-87.50	0	-	2	222.81 Kbps	MS103-0412	Aruba3600-Local	Top > MiddleSchool	Access Points
2	US110-1810	-89.00	8	-	2	363.24 Kbps	US110-1810	Aruba3600-Master	Top > UpperSchool	Access Points
3	US211-1774	-89.00	199	-	1	103.63 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
4	MS203-10ae	-90.00	0	-	1	172.36 Kbps	MS203-10ae	Aruba3600-Local	Top > MiddleSchool	Access Points
5	US201-1532	-90.00	9	-	2	339.23 Kbps	US201-1532	Aruba3600-Master	Top > UpperSchool	Access Points
6	LSADMIN-13f2	-90.50	11	-	1	4.94 Kbps	LSADMIN-13f2	Aruba3600-Local	Top > LowerSchool	Access Points
7	LS20-0482	-90.50	0	-	5	58.59 Kbps	LS20-0482	Aruba3600-Local	Top > LowerSchool	Access Points
8	US204-15be	-91.00	37	-	1	71.12 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
9	US106-0dae	-91.00	110	-	1	159.99 Kbps	US106-0dae	Aruba3600-Master	Top > UpperSchool	Access Points
10	VASC23-14a4	-91.00	1	-	3	104.94 Kbps	VASC23-14a4	Aruba3600-Local	Top > VisualArts	Access Points
11	LS14-0406	-91.00	1	-	13	94.82 Kbps	LS14-0406	Aruba3600-Local	Top > LowerSchool	Access Points
12	LS4-KINDER-2-1456	-91.00	0	-	3	8.67 Kbps	LS4-KINDER-2-1456	Aruba3600-Local	Top > Kindergarten	Access Points
13	GYM-WTROOM-1382	-91.00	0	-	1	53.69 Kbps	GYM-WTROOM-1382	Aruba3600-Master	Top > GymTheater	Access Points
14	PAVILION-SBAR-3b0a	-91.50	10	-	0	2.59 Kbps	PAVILION-SBAR-3b0a	Aruba3600-Local	Top > Pavilion	Access Points
15	PAVILION-CSO-143e	-91.50	2	-	0	4.64 Kbps	PAVILION-CSO-143e	Aruba3600-Local	Top > Pavilion	Access Points
16	MS111-052c	-91.50	2	-	3	52.23 Kbps	MS111-052c	Aruba3600-Local	Top > MiddleSchool	Access Points
17	MS207-0402	-91.50	3	-	0	135.43 Kbps	MS207-0402	Aruba3600-Local	Top > MiddleSchool	Access Points
18	ACL-IT-0512	-91.50	5	-	6	143.53 Kbps	ACL-IT-0512	Aruba3600-Master	Top > AdminLibrary	Access Points
19	ACL-ADM-RCP-0ba6	-91.50	8	-	2	31.94 Kbps	ACL-ADM-RCP-0ba6	Aruba3600-Master	Top > AdminLibrary	Access Points
20	ACL-IT-TEST124AP-295a	-91.50	5	-	1	79 bps	-	Aruba3600-Master	Top > AdminLibrary	Access Points
21	VASC12-1088	-92.00	9	-	0	44.06 Kbps	VASC12-1088	Aruba3600-Local	Top > VisualArts	Access Points
22	ECC-02fc	-92.00	0	-	1	22.43 Kbps	ECC-02fc	Aruba3600-Local	Top > LowerSchool	Access Points
23	VASC15-14d2	-92.00	1	-	1	4.68 Kbps	VASC15-14d2	Aruba3600-Local	Top > VisualArts	Access Points
24	US-ADMIN-NEW-HALLWAY-1428	-92.00	3	-	2	195.16 Kbps	US-ADMIN-NEW-HALLWAY-1428	Aruba3600-Master	Top > UpperSchool	Access Points
25	VASCBREAK-1108	-92.00	11	-	0	15.82 Kbps	VASCBREAK-1108	Aruba3600-Local	Top > VisualArts	Access Points

Most Noise (2.4 GHz)

Rank	Device	Avg Noise (dBm)	Channel Changes	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	FFTAVBOOTH-10f8	-87.00	0	-	1	3.01 Kbps	FFTAVBOOTH-10f8	Aruba3600-Master	Top > GymTheater	Access Points
2	US209-1812	-88.00	10	-	1	24.93 Kbps	US209-1812	Aruba3600-Master	Top > UpperSchool	Access Points
3	ACL-LSLIB1-10ba	-88.50	1	-	0	4.95 Kbps	ACL-LSLIB1-10ba	Aruba3600-Master	Top > AdminLibrary	Access Points
4	VASC15-14d2	-89.50	15	-	1	1.93 Kbps	VASC15-14d2	Aruba3600-Local	Top > VisualArts	Access Points
5	VASC13-1502	-89.50	2	-	0	2.92 Kbps	VASC13-1502	Aruba3600-Local	Top > VisualArts	Access Points
6	VASC10-1418	-90.00	14	-	0	505 bps	VASC10-1418	Aruba3600-Local	Top > VisualArts	Access Points
7	LS20-0482	-90.00	2	-	1	35.12 Kbps	LS20-0482	Aruba3600-Local	Top > LowerSchool	Access Points
8	US204-15be	-90.00	18	-	1	22.92 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
9	MS202-047e	-90.00	2	-	5	8.17 Kbps	MS202-047e	Aruba3600-Local	Top > MiddleSchool	Access Points
10	US-ADMIN-NEW-COPIER-10a6	-90.00	4	-	2	7.58 Kbps	US-ADMIN-NEW-COPIER-10a6	Aruba3600-Master	Top > UpperSchool	Access Points
11	LSADMIN-13f2	-90.50	16	-	1	43.56 Kbps	LSADMIN-13f2	Aruba3600-Local	Top > LowerSchool	Access Points
12	PAVILION-CSO-143e	-90.50	25	-	1	20.71 Kbps	PAVILION-CSO-143e	Aruba3600-Local	Top > Pavilion	Access Points
13	VASC12-1088	-90.50	4	-	0	461 bps	VASC12-1088	Aruba3600-Local	Top > VisualArts	Access Points
14	US101-144a	-90.50	2	-	1	10.35 Kbps	US101-144a	Aruba3600-Master	Top > UpperSchool	Access Points
15	MS207-0402	-90.50	3	-	0	17.96 Kbps	MS207-0402	Aruba3600-Local	Top > MiddleSchool	Access Points
16	PAVILION-SBAR-3b0a	-91.00	9	-	1	12.16 Kbps	PAVILION-SBAR-3b0a	Aruba3600-Local	Top > Pavilion	Access Points
17	VASCBREAK-1108	-91.00	12	-	1	1.72 Kbps	VASCBREAK-1108	Aruba3600-Local	Top > VisualArts	Access Points
18	ACL-3RD-COPIER-05a6	-91.00	0	-	0	1.56 Kbps	ACL-3RD-COPIER-05a6	Aruba3600-Master	Top > AdminLibrary	Access Points
19	VASC25-1506	-91.00	6	-	1	3.06 Kbps	VASC25-1506	Aruba3600-Local	Top > VisualArts	Access Points
20	ACL-C18-15e0	-91.00	3	-	0	1.50 Kbps	ACL-C18-15e0	Aruba3600-Master	Top > AdminLibrary	Access Points
21	LS-MUSIC-110c	-91.50	12	-	1	10.65 Kbps	LS-MUSIC-110c	Aruba3600-Local	Top > LowerSchool	Access Points
22	MS103-0412	-91.50	2	-	1	4.32 Kbps	MS103-0412	Aruba3600-Local	Top > MiddleSchool	Access Points
23	ACL-IT-0512	-91.50	2	-	3	15.91 Kbps	ACL-IT-0512	Aruba3600-Master	Top > AdminLibrary	Access Points
24	ECC1-13e2	-91.50	4	-	0	21.44 Kbps	ECC1-13e2	Aruba3600-Local	Top > LowerSchool	Access Points
25	BO-AP-13ee	-92.00	5	-	1	62.82 Kbps	BO-AP-13ee	Aruba3600-Master	Top > BO	Access Points

Most MAC/Phy Errors (5 GHz)

Rank	Device	MAC/Phy Errors	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	ACL-C01-15d8	132	7	-92.50	-	17	169.79 Kbps	ACL-C01-15d8	Aruba3600-Master	Top > AdminLibrary	Access Points
2	US208-1a14	89	19	-93.00	-	13	324.50 Kbps	US208-1a14	Aruba3600-Master	Top > UpperSchool	Access Points
3	US110-1810	85	8	-89.00	-	2	363.24 Kbps	US110-1810	Aruba3600-Master	Top > UpperSchool	Access Points
4	US108-1624	73	66	-93.00	-	2	289.86 Kbps	US108-1624	Aruba3600-Master	Top > UpperSchool	Access Points
5	US201-1532	71	9	-90.00	-	2	339.23 Kbps	US201-1532	Aruba3600-Master	Top > UpperSchool	Access Points
6	MS210-0326	68	43	-92.00	-	3	286.08 Kbps	MS210-0326	Aruba3600-Local	Top > MiddleSchool	Access Points
7	ACL-B11-1586	68	6	-92.50	-	3	201.44 Kbps	ACL-B11-1586	Aruba3600-Master	Top > AdminLibrary	Access Points
8	MS103-0412	60	0	-87.50	-	2	222.81 Kbps	MS103-0412	Aruba3600-Local	Top > MiddleSchool	Access Points
9	ACL-IT-0512	60	5	-91.50	-	6	143.53 Kbps	ACL-IT-0512	Aruba3600-Master	Top > AdminLibrary	Access Points
10	MS-LOBBY-044e	57	1	-92.50	-	3	187.84 Kbps	MS-LOBBY-044e	Aruba3600-Local	Top > MiddleSchool	Access Points
11	US209-1812	52	19	-92.00	-	1	179.07 Kbps	US209-1812	Aruba3600-Master	Top > UpperSchool	Access Points
12	MS109-037c	52	22	-92.50	-	4	236.17 Kbps	MS109-037c	Aruba3600-Local	Top > MiddleSchool	Access Points
13	US104-10f2	51	6	-93.00	-	2	169.12 Kbps	US104-10f2	Aruba3600-Master	Top > UpperSchool	Access Points
14	VASC22-14e0	50	14	-92.00	-	4	117.19 Kbps	VASC22-14e0	Aruba3600-Local	Top > VisualArts	Access Points
15	US113-169a	46	12	-92.00	-	1	187.51 Kbps	US113-169a	Aruba3600-Master	Top > UpperSchool	Access Points
16	ACL-A18-13e0	44	3	-92.50	-	3	132.71 Kbps	ACL-A18-13e0	Aruba3600-Master	Top > AdminLibrary	Access Points
17	US214-177c	44	12	-93.00	-	1	191.98 Kbps	US214-177c	Aruba3600-Master	Top > UpperSchool	Access Points
18	US106-0dae	43	110	-91.00	-	1	159.99 Kbps	US106-0dae	Aruba3600-Master	Top > UpperSchool	Access Points
19	ACL-C04-1046	42	6	-92.50	-	1	112.75 Kbps	ACL-C04-1046	Aruba3600-Master	Top > AdminLibrary	Access Points
20	MS202-047e	42	25	-93.00	-	13	75.01 Kbps	MS202-047e	Aruba3600-Local	Top > MiddleSchool	Access Points
21	LS12-03e2	38	0	-93.00	-	9	85.71 Kbps	LS12-03e2	Aruba3600-Local	Top > LowerSchool	Access Points
22	US211-1774	35	199	-89.00	-	1	103.63 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
23	MS208-0686	33	2	-93.00	-	1	173.71 Kbps	MS208-0686	Aruba3600-Local	Top > MiddleSchool	Access Points
24	MS207-0402	33	3	-91.50	-	0	135.43 Kbps	MS207-0402	Aruba3600-Local	Top > MiddleSchool	Access Points
25	LS20-0482	32	0	-90.50	-	5	58.59 Kbps	LS20-0482	Aruba3600-Local	Top > LowerSchool	Access Points

Most MAC/Phy Errors (2.4 GHz)

Rank	Device	MAC/Phy Errors	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	US113-169a	49	4	-93.00	-	2	111.96 Kbps	US113-169a	Aruba3600-Master	Top > UpperSchool	Access Points
2	GYM-WTROOM-1382	40	5	-92.00	-	5	93.56 Kbps	GYM-WTROOM-1382	Aruba3600-Master	Top > GymTheater	Access Points
3	US106-0dae	30	1	-93.00	-	1	134.65 Kbps	US106-0dae	Aruba3600-Master	Top > UpperSchool	Access Points
4	MS102-03d2	26	2	-95.00	-	4	21.52 Kbps	MS102-03d2	Aruba3600-Local	Top > MiddleSchool	Access Points
5	US-ADMIN-OLD-BRKROOM-1124	25	18	-92.50	-	2	39.52 Kbps	US-ADMIN-OLD-BRKROOM-1124	Aruba3600-Master	Top > UpperSchool	Access Points
6	US-ADMIN-NEW-HALLWAY-1428	23	1	-93.50	-	2	26.82 Kbps	US-ADMIN-NEW-HALLWAY-1428	Aruba3600-Master	Top > UpperSchool	Access Points
7	US201-1532	22	11	-93.50	-	2	29.23 Kbps	US201-1532	Aruba3600-Master	Top > UpperSchool	Access Points
8	US211-1774	21	8	-95.50	-	2	38.60 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
9	LS12-03e2	20	7	-94.00	-	4	37.94 Kbps	LS12-03e2	Aruba3600-Local	Top > LowerSchool	Access Points
10	US104-10f2	20	3	-94.50	-	2	32.44 Kbps	US104-10f2	Aruba3600-Master	Top > UpperSchool	Access Points
11	MS212-03c0	19	2	-95.00	-	2	85.32 Kbps	MS212-03c0	Aruba3600-Local	Top > MiddleSchool	Access Points
12	MS-LOBBY-044e	15	5	-93.00	-	2	41.74 Kbps	MS-LOBBY-044e	Aruba3600-Local	Top > MiddleSchool	Access Points
13	LSADMIN-13f2	14	16	-90.50	-	1	43.56 Kbps	LSADMIN-13f2	Aruba3600-Local	Top > LowerSchool	Access Points
14	BO-AP-13ee	13	5	-92.00	-	1	62.82 Kbps	BO-AP-13ee	Aruba3600-Master	Top > BO	Access Points
15	US110-1810	13	2	-95.00	-	1	21.35 Kbps	US110-1810	Aruba3600-Master	Top > UpperSchool	Access Points
16	US204-15be	13	18	-90.00	-	1	22.92 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
17	US214-177c	13	12	-93.50	-	0	23.66 Kbps	US214-177c	Aruba3600-Master	Top > UpperSchool	Access Points
18	LS14-0406	13	4	-93.50	-	1	23.58 Kbps	LS14-0406	Aruba3600-Local	Top > LowerSchool	Access Points
19	LS2-KINDER-144e	13	8	-92.50	-	3	28.92 Kbps	LS2-KINDER-144e	Aruba3600-Local	Top > Kindergarten	Access Points
20	ACL-B11-1586	13	2	-94.50	-	1	28.03 Kbps	ACL-B11-1586	Aruba3600-Master	Top > AdminLibrary	Access Points
21	FFTSTAGE-10a2	13	2	-95.50	-	1	40.63 Kbps	FFTSTAGE-10a2	Aruba3600-Master	Top > GymTheater	Access Points
22	GYM-USCHOIR-8986	12	3	-94.50	-	1	24.23 Kbps	GYM-USCHOIR-8986	Aruba3600-Master	Top > GymTheater	Access Points
23	PAVILION-CSO-143e	11	25	-90.50	-	1	20.71 Kbps	PAVILION-CSO-143e	Aruba3600-Local	Top > Pavilion	Access Points
24	US209-1812	10	10	-88.00	-	1	24.93 Kbps	US209-1812	Aruba3600-Master	Top > UpperSchool	Access Points
25	ACL-C01-15d8	10	5	-92.50	-	1	16.53 Kbps	ACL-C01-15d8	Aruba3600-Master	Top > AdminLibrary	Access Points

Most Channel Changes (5 GHz)

Rank	Device	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	US211-1774	199	-89.00	-	1	103.63 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
2	ACL-B02-1040	172	-93.00	-	1	25.91 Kbps	ACL-B02-1040	Aruba3600-Master	Top > AdminLibrary	Access Points
3	MS205-041c	168	-93.00	-	0	43.86 Kbps	MS205-041c	Aruba3600-Local	Top > MiddleSchool	Access Points
4	ACL-3RD-CONF-040e	139	-92.50	-	0	29.40 Kbps	ACL-3RD-CONF-040e	Aruba3600-Master	Top > AdminLibrary	Access Points
5	VASC10-1418	111	-92.50	-	1	57.22 Kbps	VASC10-1418	Aruba3600-Local	Top > VisualArts	Access Points
6	US106-0dae	110	-91.00	-	1	159.99 Kbps	US106-0dae	Aruba3600-Master	Top > UpperSchool	Access Points
7	ECC1-13e2	99	-93.00	-	1	62.34 Kbps	ECC1-13e2	Aruba3600-Local	Top > LowerSchool	Access Points
8	ACL-3RD-HLWY-04de	77	-92.00	-	0	52.15 Kbps	ACL-3RD-HLWY-04de	Aruba3600-Master	Top > AdminLibrary	Access Points
9	US108-1624	66	-93.00	-	2	289.86 Kbps	US108-1624	Aruba3600-Master	Top > UpperSchool	Access Points
10	US-ADMIN-NEW-COPIER-10a6	58	-93.00	-	1	14.70 Kbps	US-ADMIN-NEW-COPIER-10a6	Aruba3600-Master	Top > UpperSchool	Access Points
11	US206-1540	54	-92.50	-	1	109.03 Kbps	US206-1540	Aruba3600-Master	Top > UpperSchool	Access Points
12	ACL-3RD-COPIER-05a6	53	-92.50	-	0	6.23 Kbps	ACL-3RD-COPIER-05a6	Aruba3600-Master	Top > AdminLibrary	Access Points
13	ACL-LSLIB2-155e	51	-92.00	-	1	4.36 Kbps	ACL-LSLIB2-155e	Aruba3600-Master	Top > AdminLibrary	Access Points
14	MS210-0326	43	-92.00	-	3	286.08 Kbps	MS210-0326	Aruba3600-Local	Top > MiddleSchool	Access Points
15	US204-15be	37	-91.00	-	1	71.12 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
16	ACL-LSLIB1-10ba	32	-93.00	-	0	15.72 Kbps	ACL-LSLIB1-10ba	Aruba3600-Master	Top > AdminLibrary	Access Points
17	LS3-KINDER-14ee	32	-93.00	-	0	533 bps	LS3-KINDER-14ee	Aruba3600-Local	Top > Kindergarten	Access Points
18	MS202-047e	25	-93.00	-	13	75.01 Kbps	MS202-047e	Aruba3600-Local	Top > MiddleSchool	Access Points
19	MS109-037c	22	-92.50	-	4	236.17 Kbps	MS109-037c	Aruba3600-Local	Top > MiddleSchool	Access Points
20	US-ADMIN-NEW-CONF-144c	22	-92.00	-	1	31.35 Kbps	US-ADMIN-NEW-CONF-144c	Aruba3600-Master	Top > UpperSchool	Access Points
21	US209-1812	19	-92.00	-	1	179.07 Kbps	US209-1812	Aruba3600-Master	Top > UpperSchool	Access Points
22	US208-1a14	19	-93.00	-	13	324.50 Kbps	US208-1a14	Aruba3600-Master	Top > UpperSchool	Access Points
23	ACL-HOS-0342	18	-93.00	-	0	6.46 Kbps	ACL-HOS-0342	Aruba3600-Master	Top > AdminLibrary	Access Points
24	ACL-B01-154c	18	-92.00	-	1	68.18 Kbps	ACL-B01-154c	Aruba3600-Master	Top > AdminLibrary	Access Points
25	PAVILION-OUTDOOR-d543	15	-93.00	-	0	2.06 Kbps	PAVILION-OUTDOOR-d543	Aruba3600-Local	Top > Pavilion	Access Points

Most Channel Changes (2.4 GHz)

Rank	Device	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	PAVILION-OUTDOOR-d543	71	-95.50	-	0	3.58 Kbps	PAVILION-OUTDOOR-d543	Aruba3600-Local	Top > Pavilion	Access Points
2	MS109-037c	47	-94.50	-	2	5.58 Kbps	MS109-037c	Aruba3600-Local	Top > MiddleSchool	Access Points
3	MSTL-1094	27	-92.00	-	1	15.20 Kbps	MSTL-1094	Aruba3600-Local	Top > MiddleSchool	Access Points
4	PAVILION-CSO-143e	25	-90.50	-	1	20.71 Kbps	PAVILION-CSO-143e	Aruba3600-Local	Top > Pavilion	Access Points
5	US-ADMIN-OLD-BRKROOM-1124	18	-92.50	-	2	39.52 Kbps	US-ADMIN-OLD-BRKROOM-1124	Aruba3600-Master	Top > UpperSchool	Access Points
6	US204-15be	18	-90.00	-	1	22.92 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
7	LSADMIN-13f2	16	-90.50	-	1	43.56 Kbps	LSADMIN-13f2	Aruba3600-Local	Top > LowerSchool	Access Points
8	MS205-041c	16	-93.50	-	1	6.27 Kbps	MS205-041c	Aruba3600-Local	Top > MiddleSchool	Access Points
9	VASC15-14d2	15	-89.50	-	1	1.93 Kbps	VASC15-14d2	Aruba3600-Local	Top > VisualArts	Access Points
10	LS3-KINDER-14ee	15	-92.50	-	0	1.76 Kbps	LS3-KINDER-14ee	Aruba3600-Local	Top > Kindergarten	Access Points
11	VASC10-1418	14	-90.00	-	0	505 bps	VASC10-1418	Aruba3600-Local	Top > VisualArts	Access Points
12	LS-MUSIC-110c	12	-91.50	-	1	10.65 Kbps	LS-MUSIC-110c	Aruba3600-Local	Top > LowerSchool	Access Points
13	VASCBREAK-1108	12	-91.00	-	1	1.72 Kbps	VASCBREAK-1108	Aruba3600-Local	Top > VisualArts	Access Points
14	US214-177c	12	-93.50	-	0	23.66 Kbps	US214-177c	Aruba3600-Master	Top > UpperSchool	Access Points
15	US201-1532	11	-93.50	-	2	29.23 Kbps	US201-1532	Aruba3600-Master	Top > UpperSchool	Access Points
16	US209-1812	10	-88.00	-	1	24.93 Kbps	US209-1812	Aruba3600-Master	Top > UpperSchool	Access Points
17	PAVILION-SBAR-3b0a	9	-91.00	-	1	12.16 Kbps	PAVILION-SBAR-3b0a	Aruba3600-Local	Top > Pavilion	Access Points
18	LS16-05b2	9	-93.50	-	4	19.88 Kbps	LS16-05b2	Aruba3600-Local	Top > LowerSchool	Access Points
19	VASC14-1514	9	-93.00	-	1	5.44 Kbps	VASC14-1514	Aruba3600-Local	Top > VisualArts	Access Points
20	LS4-KINDER-2-1456	9	-95.00	-	0	55 bps	LS4-KINDER-2-1456	Aruba3600-Local	Top > Kindergarten	Access Points
21	ACL-ADM-RCP-0ba6	9	-93.50	-	0	1.89 Kbps	ACL-ADM-RCP-0ba6	Aruba3600-Master	Top > AdminLibrary	Access Points
22	ACL-3RD-CONF-040e	8	-95.00	-	0	6.34 Kbps	ACL-3RD-CONF-040e	Aruba3600-Master	Top > AdminLibrary	Access Points
23	US211-1774	8	-95.50	-	2	38.60 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
24	LS2-KINDER-144e	8	-92.50	-	3	28.92 Kbps	LS2-KINDER-144e	Aruba3600-Local	Top > Kindergarten	Access Points
25	US206-1540	8	-94.00	-	0	17.71 Kbps	US206-1540	Aruba3600-Master	Top > UpperSchool	Access Points

Most Transmit Power Changes (5 GHz)

Rank	Device	Transmit Power Changes	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	ACL-C18-15e0	1025	6	-92.50	-	1	20.33 Kbps	ACL-C18-15e0	Aruba3600-Master	Top > AdminLibrary	Access Points
2	ACL-C04-1046	929	6	-92.50	-	1	112.75 Kbps	ACL-C04-1046	Aruba3600-Master	Top > AdminLibrary	Access Points
3	ACL-B02-1040	260	172	-93.00	-	1	25.91 Kbps	ACL-B02-1040	Aruba3600-Master	Top > AdminLibrary	Access Points
4	LS3-KINDER-14ee	191	32	-93.00	-	0	533 bps	LS3-KINDER-14ee	Aruba3600-Local	Top > Kindergarten	Access Points
5	ACL-B01-154c	147	18	-92.00	-	1	68.18 Kbps	ACL-B01-154c	Aruba3600-Master	Top > AdminLibrary	Access Points
6	VASC13-1502	141	6	-92.00	-	1	46.82 Kbps	VASC13-1502	Aruba3600-Local	Top > VisualArts	Access Points
7	ACL-IT-0512	123	5	-91.50	-	6	143.53 Kbps	ACL-IT-0512	Aruba3600-Master	Top > AdminLibrary	Access Points
8	ACL-C01-15d8	116	7	-92.50	-	17	169.79 Kbps	ACL-C01-15d8	Aruba3600-Master	Top > AdminLibrary	Access Points
9	MS205-041c	93	168	-93.00	-	0	43.86 Kbps	MS205-041c	Aruba3600-Local	Top > MiddleSchool	Access Points
10	ECC1-13e2	84	99	-93.00	-	1	62.34 Kbps	ECC1-13e2	Aruba3600-Local	Top > LowerSchool	Access Points
11	ACL-3RD-HLWY-04de	82	77	-92.00	-	0	52.15 Kbps	ACL-3RD-HLWY-04de	Aruba3600-Master	Top > AdminLibrary	Access Points
12	VASCBREAK-1108	81	11	-92.00	-	0	15.82 Kbps	VASCBREAK-1108	Aruba3600-Local	Top > VisualArts	Access Points
13	ACL-C19-15b8	78	7	-92.50	-	5	48.86 Kbps	ACL-C19-15b8	Aruba3600-Master	Top > AdminLibrary	Access Points
14	US208-1a14	60	19	-93.00	-	13	324.50 Kbps	US208-1a14	Aruba3600-Master	Top > UpperSchool	Access Points
15	VASC23-14a4	58	1	-91.00	-	3	104.94 Kbps	VASC23-14a4	Aruba3600-Local	Top > VisualArts	Access Points
16	LS2-KINDER-144e	48	2	-92.50	-	0	8.66 Kbps	LS2-KINDER-144e	Aruba3600-Local	Top > Kindergarten	Access Points
17	LS4-KINDER-1-1450	35	6	-92.50	-	1	25.60 Kbps	LS4-KINDER-1-1450	Aruba3600-Local	Top > Kindergarten	Access Points
18	ACL-3RD-COPIER-05a6	35	53	-92.50	-	0	6.23 Kbps	ACL-3RD-COPIER-05a6	Aruba3600-Master	Top > AdminLibrary	Access Points
19	US110-1810	29	8	-89.00	-	2	363.24 Kbps	US110-1810	Aruba3600-Master	Top > UpperSchool	Access Points
20	US211-1774	26	199	-89.00	-	1	103.63 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
21	LSADMIN-13f2	23	11	-90.50	-	1	4.94 Kbps	LSADMIN-13f2	Aruba3600-Local	Top > LowerSchool	Access Points
22	MS210-0326	22	43	-92.00	-	3	286.08 Kbps	MS210-0326	Aruba3600-Local	Top > MiddleSchool	Access Points
23	US-ADMIN-NEW-CONF-144c	21	22	-92.00	-	1	31.35 Kbps	US-ADMIN-NEW-CONF-144c	Aruba3600-Master	Top > UpperSchool	Access Points
24	US-ADMIN-NEW-COPIER-10a6	20	58	-93.00	-	1	14.70 Kbps	US-ADMIN-NEW-COPIER-10a6	Aruba3600-Master	Top > UpperSchool	Access Points
25	ACL-3RD-CONF-040e	19	139	-92.50	-	0	29.40 Kbps	ACL-3RD-CONF-040e	Aruba3600-Master	Top > AdminLibrary	Access Points

Most Transmit Power Changes (2.4 GHz)

Rank	Device	Transmit Power Changes	Channel Changes	Avg Noise (dBm)	Avg Channel Busy (%)	Clients	Usage	Location	Controller	Folder	Group
1	LS4-KINDER-2-1456	827	9	-95.00	-	0	55 bps	LS4-KINDER-2-1456	Aruba3600-Local	Top > Kindergarten	Access Points
2	US108-1624	768	2	-95.50	-	0	6.90 Kbps	US108-1624	Aruba3600-Master	Top > UpperSchool	Access Points
3	US206-1540	768	8	-94.00	-	0	17.71 Kbps	US206-1540	Aruba3600-Master	Top > UpperSchool	Access Points
4	LS3-KINDER-14ee	739	15	-92.50	-	0	1.76 Kbps	LS3-KINDER-14ee	Aruba3600-Local	Top > Kindergarten	Access Points
5	US101-144a	672	2	-90.50	-	1	10.35 Kbps	US101-144a	Aruba3600-Master	Top > UpperSchool	Access Points
6	MS103-0412	632	2	-91.50	-	1	4.32 Kbps	MS103-0412	Aruba3600-Local	Top > MiddleSchool	Access Points
7	ACL-A18-13e0	599	6	-94.00	-	1	7.65 Kbps	ACL-A18-13e0	Aruba3600-Master	Top > AdminLibrary	Access Points
8	US104-10f2	545	3	-94.50	-	2	32.44 Kbps	US104-10f2	Aruba3600-Master	Top > UpperSchool	Access Points
9	US204-15be	527	18	-90.00	-	1	22.92 Kbps	US204-15be	Aruba3600-Master	Top > UpperSchool	Access Points
10	ACL-C04-1046	520	2	-92.00	-	0	10.66 Kbps	ACL-C04-1046	Aruba3600-Master	Top > AdminLibrary	Access Points
11	ACL-C01-15d8	502	5	-92.50	-	1	16.53 Kbps	ACL-C01-15d8	Aruba3600-Master	Top > AdminLibrary	Access Points
12	ACL-B02-1040	479	2	-93.00	-	0	2.44 Kbps	ACL-B02-1040	Aruba3600-Master	Top > AdminLibrary	Access Points
13	US-ADMIN-NEW-COPIER-10a6	466	4	-90.00	-	2	7.58 Kbps	US-ADMIN-NEW-COPIER-10a6	Aruba3600-Master	Top > UpperSchool	Access Points
14	ACL-IT-0512	409	2	-91.50	-	3	15.91 Kbps	ACL-IT-0512	Aruba3600-Master	Top > AdminLibrary	Access Points
15	PAVILION-OUTDOOR-d543	397	71	-95.50	-	0	3.58 Kbps	PAVILION-OUTDOOR-d543	Aruba3600-Local	Top > Pavilion	Access Points
16	US208-1a14	378	1	-94.00	-	1	13.83 Kbps	US208-1a14	Aruba3600-Master	Top > UpperSchool	Access Points
17	US211-1774	359	8	-95.50	-	2	38.60 Kbps	US211-1774	Aruba3600-Master	Top > UpperSchool	Access Points
18	BO-AP-13ee	336	5	-92.00	-	1	62.82 Kbps	BO-AP-13ee	Aruba3600-Master	Top > BO	Access Points
19	VASCBREAK-1108	307	12	-91.00	-	1	1.72 Kbps	VASCBREAK-1108	Aruba3600-Local	Top > VisualArts	Access Points
20	US106-0dae	307	1	-93.00	-	1	134.65 Kbps	US106-0dae	Aruba3600-Master	Top > UpperSchool	Access Points
21	VASC22-14e0	299	1	-93.00	-	1	7.53 Kbps	VASC22-14e0	Aruba3600-Local	Top > VisualArts	Access Points
22	ACL-ADM-RCP-0ba6	297	9	-93.50	-	0	1.89 Kbps	ACL-ADM-RCP-0ba6	Aruba3600-Master	Top > AdminLibrary	Access Points
23	ACL-C18-15e0	284	3	-91.00	-	0	1.50 Kbps	ACL-C18-15e0	Aruba3600-Master	Top > AdminLibrary	Access Points
24	ACL-IT-TEST124AP-295a	276	7	-95.50	-	0	1 bps	-	Aruba3600-Master	Top > AdminLibrary	Access Points
25	ACL-ARTGAL-04d8	269	5	-95.50	-	1	15.25 Kbps	ACL-ARTGAL-04d8	Aruba3600-Master	Top > AdminLibrary	Access Points